

31 CHAMBERS STREET



KAM CONSULTANTS
 35-40 36th Street
 Long Island City
 New York, 11106
 Tel: (718) 729-1997
 Fax: (718) 729-1876

REPORT OF AIR MONITORING (PHASE CONTRAST MICROSCOPY ANALYSIS OF AIR FILTERS)

CLIENT: DCAS

DATE: 09/25/01

PROJECT:

ADDRESS: 31 Chamber Street, Manhattan

7th Floor, 5th Floor, 3rd Floor, Basement

CLIENT SAMPLE ID#	LOCATION	R E S P	W O R K	TIME IN	TIME OUT	FLOW BEF. (lpm)	FLOW AFTER (lpm)	SAMPLE VOLUME (liters)	FIBERS PER FIELD	FIBERS PER CC	REMARKS	LAB ID#
01	7th Floor - Inside Room # 703	1		12:45	14:45	10	10	1200	<0.055	< 0.01	Air Quality (Immed. TAT)	A010926C-01
02	7th Floor - By Elevator Lobby	1		12:48	14:48	10	10	1200	<0.055	< 0.01	Air Quality (Immed. TAT)	A010926C-02
03	7th Floor - Inside Room # 734	1		12:50	14:50	10	10	1200	<0.055	< 0.01	Air Quality (Immed. TAT)	A010926C-03
04	7th Floor - By West Side Staircase	1		12:52	14:52	10	10	1200	<0.055	< 0.01	Air Quality (Immed. TAT)	A010926C-04
05	7th Floor - Inside Room # 715	1		12:56	14:56	10	10	1200	<0.055	< 0.01	Air Quality (Immed. TAT)	A010926C-05
06	5th Floor - East Side By Elevators	1		13:15	15:15	10	10	1200	<0.055	< 0.01	Air Quality (Immed. TAT)	A010926C-06
07	5th Floor - Inside Court Rom # 509	1		13:18	15:18	10	10	1200	<0.055	< 0.01	Air Quality (Immed. TAT)	A010926C-07
08	5th Floor - West Side by Staircase	1		13:22	15:22	10	10	1200	<0.055	< 0.01	Air Quality (Immed. TAT)	A010926C-08
09	5th Floor - Corridor S.W. Corner By Rm. # 505	1		13:26	15:26	10	10	1200	<0.055	< 0.01	Air Quality (Immed. TAT)	A010926C-09
10	5th Floor - Inside Court Rom # 503	1		13:30	15:30	10	10	1200	<0.055	< 0.01	Air Quality (Immed. TAT)	A010926C-10
11	3rd Floor - Inside Room # 301	1		13:40	15:40	10	10	1200	<0.055	< 0.01	Air Quality (Immed. TAT)	A010926C-11
12	3rd Floor - By Elevator Lobby	1		13:42	15:42	10	10	1200	<0.055	< 0.01	Air Quality (Immed. TAT)	A010926C-12
13	3rd Floor - North Corridor	1		13:45	15:45	10	10	1200	0.070	< 0.01	Air Quality (Immed. TAT)	A010926C-13
14	3rd Floor - Inside Room # 305	1		13:48	15:48	10	10	1200	<0.055	< 0.01	Air Quality (Immed. TAT)	A010926C-14
15	3rd Floor - By Staircase	1		13:52	15:52	10	10	1200	<0.055	< 0.01	Air Quality (Immed. TAT)	A010926C-15
16	Basement - East Side Corridor	1		14:12	16:12	10	10	1200	<0.055	< 0.01	Air Quality (Immed. TAT)	A010926C-16
17	Basement - North Side Entrance	1		14:20	16:20	10	10	1200	<0.055	< 0.01	Air Quality (Immed. TAT)	A010926C-17
18	Basement - North Side Corridor	1		14:24	16:24	10	10	1200	<0.055	< 0.01	Air Quality (Immed. TAT)	A010926C-18
19	Basement - West Side Corridor	1		14:26	16:26	10	10	1200	<0.055	< 0.01	Air Quality (Immed. TAT)	A010926C-19
20	Basement - South Side Corridor	1		14:30	16:30	10	10	1200	<0.055	< 0.01	Air Quality (Immed. TAT)	A010926C-20
21	Field Blank								<0.055			A010926C-21
22	Field Blank								<0.055			A010926C-22

TYPE OF RESPIRATORS:

TYPE OF WORK:

1 = HALF FACE, 2 = PAPR, 3 = TYPE C, 4 = OTHER (SPECIFY):

1 = BLDG DECON, 2 = PLASTICIZING, 3 = GROSS REMOVAL, 4 = GLOVEBAG, 5 = CLEANING,

6 = ENCAPSULATION, 7 = BAGOUT, 8 = OTHER (SPECIFY):

SAMPLING TECHNICIAN: M. Tchatchueng

ROTAMETER: KAM- 02

Analyst:

Deepak Bajracharya

DATE RECEIVED: 09/26/01

DATE OF ANALYSIS: 09/26/01

DATE OF REPORT: 09/26/01

Lab Manager:

David Chen

The samples listed above are analyzed by Phase Contrast Microscopy (PCM) as per NIOSH 7400 Method -Issue 3. The detection limit of this method is 7 fibers per square mm per filter area.

KAM CONSULTANTS shall not be liable for information arising from samples that are not in its QA and QC program

The results relate only to the items calibrated or tested. The certificate of report shall not be reproduced without approval of the laboratory.

The report must not be used by the client to claim endorsement by NVLAP or any agency of the U.S. Government

NYS-DOH ELAP # 11273

AHIA # 100269



KAM CONSULTANTS
35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

CHAIN OF CUSTODY FOR ASBESTOS AIR MONITORING

CLIENT: DCAS
PROJECT:

SAMPLING DATE: 09/25/01

ADDRESS: 31 CHAMBER STREET, Manhattan

FIELD DATA									LAB ANALYSIS				
SAMPLE ID#	TYPE	LOCATION	R E S P	W O R K	TIME IN	TIME OUT	FLOW BEF. (ipm)	FLOW AFTER (ipm)	VOLUME (liters)	FIBERS PER FIELD	FIBERS PER CC	LAB ID #	CASSETTE 25MM 37MM
7TH FLOOR													
01	L	Inside Room # 703			12 ⁴⁵	14 ⁴⁵	10	10	1200	3/100	<0.01	1	TEST METHOD: PCM TEM
02	L	BY Elevator Lobby			12 ⁴⁸	14 ⁴⁸	10	10	1200	2/100	<0.01	2	
03	L	Inside Rm # 734			12 ⁵⁰	14 ⁵⁰	10	10	1200	0.5/100	<0.01	3	TURN-AROUND TIME: IMMEDIATE
04	L	BY WEST side STAIR CASE			12 ⁵²	14 ⁵²	10	10	1200	2/100	<0.01	4	12-HOUR
05	L	Inside Rm # 715			12 ⁵⁶	14 ⁵⁶	10	10	1200	1/100	<0.01	5	24-HOUR
5TH FLOOR													
06	L	EAST side BY ELEVATORS			13 ¹⁵	15 ¹⁵	10	10	1200	4/100	<0.01	6	24-HOUR
07	L	Inside Court Rm # 509			13 ¹⁸	15 ¹⁸	10	10	1200	0.5/100	<0.01	7	OTHER:
08	L	WEST side BY STAIR CASE			13 ²²	15 ²²	10	10	1200	1/100	<0.01	8	ANALYST: DB
09	L	CORRIDOR S.W. Corner BY Rm # 505			13 ²⁶	15 ²⁶	10	10	1200	1/100	<0.01	9	DATE OF ANALYSIS: 9-26-01
10	L	Inside Court Rm # 503			13 ³⁰	15 ³⁰	10	10	1200	3/100	<0.01	10	TIME OF ANALYSIS: 5:41
3TH FLOOR													
11	L	Inside Room # 301			13 ⁴⁰	15 ⁴⁰	10	10	1200	5/100	<0.01	11	
12	L	BY Elevator Lobby			13 ⁴²	15 ⁴²	10	10	1200	3/100	<0.01	12	

SAMPLE TYPE:

A=BACKGROUND, B=PREABATEMENT, C=DURING ABATEMENT, D=POST-ABATEMENT
E=OUTSIDE WORK AREA, F=INSIDE WORK AREA, G=MICROTRAP EXHAUST DISCHARGE
H=DECONTAMINATION FACILITY, I=CRITICAL BARRIER, J=OUTSIDE BLDG., K=FIELD BLANK
L= AIR QUALITY, M=COMPLIANCE MONITORING

TYPE OF RESPIRATORS:

1 = HALF FACE, 2 = PAPR, 3 = TYPE C, 4 = OTHER (SPECIFY):

TYPE OF WORK:

1 = BLDG DECON, 2 = PLASTICIZING, 3 = GROSS REMOVAL, 4 = GLOVEBAG, 5 = CLEANING, 6 = ENCAPSULATION, 7 = BAGOUT, 8 = OTHER (SPECIFY):

TECHNICIAN:

MATHIEU T. MILCEK ZIBBY

ROTAMETER: KAM-02

PAGE 1 OF 2

CHAIN OF CUSTODY	RELINGUISHED BY: MATHIEU T.	COMMENTS:	RECEIVED AT LAB BY: n/l
	METHOD OF SHIPMENT: H/D		SAMPLE CONDITION UPON RECEIPT: good
	DATE/TIME:		DATE/TIME: 9/26

RECEIVED
KAM CONSULTANTS
SEP 26 5:41



KAM CONSULTANTS
35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

CHAIN OF CUSTODY FOR ASBESTOS AIR MONITORING

CLIENT: DCAS
PROJECT:

SAMPLING DATE: 09/28/01

ADDRESS: 31-CHAMBER STREET, Manhattan

FIELD DATA									LAB ANALYSIS				
SAMPLE ID#	TYPE	LOCATION	R E S P	W O R K	TIME IN	TIME OUT	FLOW BEF. (lpm)	FLOW AFTER (lpm)	VOLUME (liters)	FIBERS PER FIELD	FIBERS PER CC	LAB ID #	CASSETTE (25MM) 37MM
13	L	3TH FLOOR North Corridor			13:45	15:45	10	10	1200	7/100	<0.01	13	TEST METHOD: (PCM) TEM
14	L	Inside Room #305			13:48	15:48	10	10	1200	4/100	<0.01	14	TURN-AROUND TIME: <u>IMMEDIATE</u> 12-HOUR 24-HOUR 24-HOUR OTHER: 2001 ANALYST: DCS DATE OF ANALYSIS: 9-28-01 TIME OF ANALYSIS: 5:15 PM
15	L	BY STAIR CASE			13:52	15:52	10	10	1200	3/100	<0.01	15	
		BASEMENT					10	10	1200				
16	L	EAST Side Corridor			14:12	16:12	10	10	1200	1/100	<0.01	16	RECEIVED KAM CONSULTANTS
17	L	North Side Entrance			14:20	16:20	10	10	1200	3/100	<0.01	17	
18	L	North Side Corridor			14:24	16:24	10	10	1200	2/100	<0.01	18	
19	L	WEST Side Corridor			14:26	16:26	10	10	1200	3/100	<0.01	19	
20	L	South Side 11			14:30	16:30	10	10	1200	0.5/100	<0.01	20	
21	K	Field Blank								0/100		21	
22	K	11 11								0/100		22	

SAMPLE TYPE:

A=BACKGROUND, B=PREABATEMENT, C=DURING ABATEMENT, D=POST-ABATEMENT
E=OUTSIDE WORK AREA, F=INSIDE WORK AREA, G=MICROTRAP EXHAUST DISCHARGE
H=DECONTAMINATION FACILITY, I=CRITICAL BARRIER, J=OUTSIDE BLDG., K=FIELD BLANK
L= AIR QUALITY, M=COMPLIANCE MONITORING

TYPE OF RESPIRATORS:

1 = HALF FACE, 2 = PAPR, 3 = TYPE C, 4 = OTHER (SPECIFY)

TYPE OF WORK:

1 = BLDG DECON, 2 = PLASTICIZING, 3 = GROSS REMOVAL, 4 = GLOVEBAG, 5 = CLEANING,
6 = ENCAPSULATION, 7 = BAGOUT, 8 = OTHER (SPECIFY):

TECHNICIAN: MATHIEU T ; MICHAEL ZIBBY

ROTAMETER: KAM-02

PAGE 2 OF 2

CHAIN OF CUSTODY	RELINQUISHED BY: M.T METHOD OF SHIPMENT: MD DATE/TIME:	COMMENTS:	RECEIVED AT LAB BY: NLC SAMPLE CONDITION UPON RECEIPT: Good DATE/TIME: 9/28/01
------------------	--	-----------	--