NYC 9/11 Public Portal Document

ATC ASSOCIATES INC.

BATCH NO. 2C110

BULK SAMPLE DATA AND CHAIN OF CUSTODY FORM

PROJECT INFORMATION

1. Client: NYC - BOE	2. Project Nam AHERA REINSPECTION	3. Project # 14584-0865	4. Project Manager: Yiannis Efstathiou
	2a. Project Address: 100 Trinity Place, New York, NY 10006		4a. Investigator: Chacko Mathew

5. Date:	6. Building Name: M833	8. Turnaround Time:	9. Comments (Field):
3/9/02	7. Sampling Areas:	☐ STAT ☐ 24 HRS ☐ 72 HRS ☐ OTHER ☐ 6 HRS ☐ 48 HOURS ☐ NORMAL	Analyzed all them for fiberglass 10. Time in / Time out:

H.A.#	SAMPLE ID NUMBER	MATERIAL DESCRIPTION	LOCATION	FLOOR NUMBER	RESULTS
1	M833-3/9/02-Fiberglass- 01	Settled Dust	1st Flr Lobby by Auditorium Entrance		ND
2	M833-3/9/02-Fiberglass- 02	Settled Dust	Auditorium Floor by Stage		
3	M833-3/9/02-Fiberglass- 03	Settled Dust	3rd Flr hallway by Rm 306		
4	M833-3/9/02-Fiberglass- 04	Settled Dust	5th Floor hallway by 510		
5	M833-3/9/02-Fiberglass- 05	Settled Dust	Inside classroom Floor Rm 606		
6	M833-3/9/02-Fiberglass- 06	Settled Dust	Class room Floor Rm 410		
7	M833-3/9/02-Fiberglass- 07	Settled Dust	7th Floor hallway Floor by elevators		
8	M833-3/9/02-Fiberglass- 08	Settled Dust	Cafeteria Floor by Stairs		
9	M833-3/9/02-Fiberglass- 09	Settled Dust	9th Flr hallway by office 933		
	M833-3/9/02-Fiberglass-	Settled Dust			

CHAIN OF CUSTODY

17. Relinquished By:	18. Date:	19. Time:	20. Received By:	21. Date:	22. Time:	23. Method of Submittal:	
[illegible]	3/9/02		[illegible]	3/9/02	1130h	FIELD	
						WALK IN	
						US MAIL	
						FED-X	
						OTHER	

LAB INFORMATION

24. Name and Signature:	25. Date:	26. Time:	27. Comments (Lab):
24a. Analyzed By: [signature]	3/9/02	[signature]	
24b. Analyzed By:			
24c. QC By:			

Filename: P:\USERS\DATA\WP96\WP\FORMS\NY-13.XLS

Form NY-13

CONFIDENTIAL, CITY_21MC100_003390974

SUBJECT TO PROTECTIVE ORDER NO. 2, SEPT. 2008

NYC-WTC_000178843