



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 1 of 3

TURNAROUND TIME			
☐ 2 hrs	☐ 6 hrs	☐ 48 hrs	☐ Standard
☐ 4 hrs	☐ 24 hrs	☐ 72 hrs	☒ Other <u>15 min</u>

PROJECT INFORMATION 60875

1 Client <u>NYC-BOE</u>		2 Project Name <u>HS of Economics and Finance (M833)</u>		3 Project # <u>14584-065</u>		4 Project Monitor <u>M. BALON</u>		4c Rotameter Number <u>11P-12A</u>	
5 Date <u>02/20/02</u>		6 Abatement Location <u>Entire</u>		7 ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture _____ Lot # _____		8 ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacture <u>nickpore</u> Lot # <u>98 117.617</u>		9 Type a ☐ Background b ☐ Pre-Abate c ☐ Abatement d ☐ Post-Abate e ☐ OSHA f ☐ Environmental g ☒ Ambient h ☐ Other	

DAILY AIR SAMPLE RECORD

0 Sample ID Number	11 Pump Number	12 Sample Location			13 Time (24 hrs clock)			14 Flow Rate (L/min)			15 Total Air Vol (liters)	16 # Fibers/Fields Minus Blank	17 Fiber Conc F/CC
		12a IWA	12b OWA	12c Sample Coordinates	13a Start	13b End	13c Total	14a Start	14b End	14b Avg			
01				Field Blank									
02				Field Blank									
03			V	Outside the building - Roof South east corner	07:36	11:24	228	8.0	8.0	8.0	1824		
04		V		8th floor - Cafeteria North West corner	07:39	11:26	227	8.0	8.0	8.0	1846		
05			V	Staircase B (open staircase) 7th floor landing	07:41	11:27	226	8.0	8.0	8.0	1808		
06		V		1st floor - Auditorium Left side of the stage	07:44	11:30	226	8.0	8.0	8.0	1808		
07		V		1st floor - Lobby Next to Room 102A	07:45	11:32	227	8.0	8.0	8.0	1816		
08			V	Outside the building Adj. to Main Entrance	07:46	11:33	227	8.0	8.0	8.0	1816		

CHAIN OF CUSTODY

18 Relinquished By <u>I. B. Balon</u>	19 Received By <u>Mark Terjesen</u>	20 Date <u>02/28/02</u>	21 Time <u>2:15</u>
II			
III			

26 ATC Project Manager <u>Mark Terjesen</u>	27 Result To <u>Mark Terjesen</u> Beeper/Phone #'s <u>ATC ext 266</u>
--	--

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22 Lab Name <u>ATC-TEM</u>	23 Date <u>3/1/02</u>	24 Time <u>4:10</u>
a Analyzed By <u>RDH</u>		
b QC By		
c Lab Batch # <u>0175</u>		

28 Comments

25 Microscope Make/Serial # ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079
Analysis Methodology PCM - NIOSH 7400A TEM - AHERA

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY-1 (1.01)

SUBJECT TO PROTECTIVE ORDER NO. 2, SEPT. 2008

CONFIDENTIAL

CITY_21MC100_003459497



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

 Page 2 of 3

TURNAROUND TIME			
☐ 2 hrs	☐ 6 hrs	☐ 48 hrs	☐ Standard
☐ 4 hrs	☐ 24 hrs	☐ 72 hrs	☒ Other <u>14 hrs</u>

PROJECT INFORMATION

1 Client <u>NYC-BCE</u>		2 Project Name <u>H.S. of Economics and Finance (M833)</u>		3 Project # <u>14504-865</u>		4 Project Monitor <u>M BALOTA</u>		4c Rotameter Number <u>HP 120</u>	
2a Project Address <u>100 Trinity Pl NY, NY</u>		3a Task # <u>01</u>							
5 Date <u>2/28/02</u>		6 Abatement Location <u>Entire</u>		7 ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture _____ Lot # _____		8 ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacture <u>Mullipore</u> Lot # <u>88-117.617</u>		9 Type a ☐ Background b ☐ Pre-Abate c ☐ Abatement d ☐ Post-Abate e ☐ OSHA f ☐ Environmental g ☒ Ambient h ☐ Other	

DAILY AIR SAMPLE RECORD

10 Sample ID Number	11 Pump Number	12 Sample Location			13 Time (24 hrs clock)			14 Flow Rate (L/min)			15 Total Air Vol (liters)	16 # Fibers/Fields Minus Blank	17 Fiber Conc F/CC
		12a IWA	12b OWA	12c Sample Coordinates	13a Start	13b End	13c Total	14a Start	14b End	14c Avg			
				Field Blank									
				Field Blank									
09			✓	Outside the building - Roof South east corner	11:24	14:12	228	8.0	8.0	8.0	1824		
10			✓	Staircase (open staircase) At the 7th floor landing	11:27	15:14	227	8.0	8.0	8.0	1816		
11		✓		1st floor - Lobby Next to Room # 1024	11:32	15:18	226	8.0	8.0	8.0	1808		
12			✓	Outside the building Adj to Main Entrance	11:35	15:19	226	8.0	8.0	8.0	1808		
13		✓		9th floor corridor Adj to Room # 903	15:24	19:12	226	8.0	8.0	8.0	1824		
14		✓		8th floor - Room # 804 Inside the room	15:28	19:15	224	8.0	8.0	8.0	1816		

CHAIN OF CUSTODY

18 Relinquished By		19 Received By		20 Date	21 Time
I <u>Al. Balota</u>		<u>Mark Terjesen</u>		<u>2/28/02</u>	<u>2:15</u>
II					
III					

26 ATC Project Manager

Mark Terjesen

27 Result To

Mark Terjesen

 Beeper/Phone #'s ATC ext 266

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22 Lab Name <u>ATC-TEM</u>		23 Date	24 Time
a Analyzed By <u>R/R</u>		<u>3/01/02</u>	<u>4:00</u>
b QC By			
c Lab Batch # <u>0375</u>			

28 Comments

25 Microscope Make/Serial #

- ☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology

 PCM - NIOSH 7400A
 TEM - AHERA

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY-1 (1/01)

SUBJECT TO PROTECTIVE ORDER NO. 2, SEPT. 2008

CONFIDENTIAL

CITY_21MC100_003459498



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 3 of 3

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other Rush

PROJECT INFORMATION

Client NYC - BOE		2 Project Name H.S. of Economics and Finance (MBS)		3 Project # 14584-CGS		4 Project Monitor		4c Rotameter Number 14P 125	
		2a Project Address 100 Trinity Pl. NY, NY.		3a Task # 01		4a Air Sampler M BALOTA			
Date 2.28.02	6 Abatement Location Entire		7 ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture _____ Lot # _____		8 ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacture <u>nuclepore</u> Lot # <u>28 117.617</u>		9 Type a ☐ Background b ☐ Pre-Abate c ☐ Abatement d ☐ Post-Abate e ☐ OSHA f ☐ Environmental g ☒ Ambient h ☐ Other		

DAILY AIR SAMPLE RECORD

Sample ID Number	11 Pump Number	12 Sample Location			13 Time (24 hrs clock)			14 Flow Rate (L/min)			15 Total Air Vol (liters)	16 # Fibers/Fields Minus Blank	17 Fiber Conc F/CC
		12a IWA	12b OWA	12c Sample Coordinates	13a Start	13b End	13c Total	14a Start	14b End	14b Avg			
				Field Blank									
				Field Blank									
15		✓		7th floor - corridor By Boy's bathroom	15:30	19:17	227	8.0	8.0	8.0	1816		
16		✓		6th floor - Room # 604 Inside the room	15:34	19:20	226	8.0	8.0	8.0	1808		
17		✓		5th floor - corridor adj. to Room # 504	15:37	19:24	227	8.0	8.0	8.0	1816		
18		✓		4th floor - Room # 406 Inside the room	15:40	19:26	226	8.0	8.0	8.0	1808		
19		✓		3rd floor corridor Between Rm # 305 & 306	15:44	19:30	226	8.0	8.0	8.0	1808		
20				sealed Blank									

CHAIN OF CUSTODY

18 Relinquished By M. Balota	19 Received By Mark Teijesen	20 Date 2/28/02	21 Time 2:45
II			

26 ATC Project Manager Mark Teijesen	27 Result To Mark Teijesen Beeper/Phone #s ATC ext 266
--	--

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22 Lab Name ATC-TEM	23 Date 3/1/02	24 Time 4:00	25 Microscope Make/Serial # ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079
a Analyzed By RRuy			
b QC By			
c Lab Batch # 6.8/5			Analysis Methodology PCM - NIOSH 7400A TEM - AHERA
28 Comments			

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY-1 (1/01)

SUBJECT TO PROTECTIVE ORDER NO. 2, SEPT. 2008

CONFIDENTIAL,

CITY_21MC100_003459499