



AIR MONITORING DATA AND

CHAIN OF CUSTODY FORM

Page 1 of 3

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other Rush

PROJECT INFORMATION

1 Client <u>BCE</u>	2 Project Name <u>H.S. of Economics and Finance</u>	3 Project # <u>14584-865</u>	4 Project Monitor <u>M. BALOTA</u>	4c Rotameter Number <u>HP-126</u>
2a Project Address <u>100 Trinity Pl NY, NY</u>	3a Task #	4a Air Sampler <u>- 11 -</u>		
5 Date <u>02 26 02</u>	6 Abatement Location <u>Entire</u>	7 ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture Lot #	8 ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacture <u>Nuclepore</u> Lot # <u>98.117.615</u>	9 Type a ☐ Background b ☐ Pre-Abate c ☐ Abatement d ☐ Post-Abate e ☐ OSHA f ☐ Environmental g ☒ Ambient h ☐ Other

DAILY AIR SAMPLE RECORD

10 Sample ID Number	11 Pump Number	12 Sample Location			13 Time (24 hrs clock)			14 Flow Rate (L/min)			15 Total Air Vol (liters)	16 # Fibers/Fields Minus Blank	17 Fiber Conc F/CC
		12a IWA	12b OWA	12c Sample Coordinates	13a Start	13b End	13c Total	14a Start	14b End	14b Avg			
01				Field Blank open 30 sec.									
02				Field Blank open 30 sec									
				Main Roof									
03			✓	South east corner	15.51	19.14	203	9.0	9.0	9.0	1827		
04		✓		9th floor corridor									
				Adj. to Room # 905	15.54	19.16	202	9.0	9.0	9.0	1848		
05		✓		8th floor - Cafeteria									
				North West corner	15.56	19.17	201	9.0	9.0	9.0	1809		
06		✓		8th floor Room # 801									
				Inside the room	15.58	19.18	200	9.0	9.0	9.0	1800		
07			✓	Staircase B (open staircase)									
				At 7th fl Landing	16.02	19.24	202	9.0	9.0	9.0	1818		
08		✓		7th floor corridor									
				Next to Room # 703	16.04	19.25	201	9.0	9.0	9.0	1809		

CHAIN OF CUSTODY

18 Relinquished By <u>I Al Balota</u>	19 Received By <u>W. Hoyle</u>	20 Date <u>02/26/02</u>	21 Time
II			
III			
26 ATC Project Manager <u>Mark Teijesen</u>	27 Result To <u>Mark Teijesen</u> Beeper/Phone #'s <u>ATC ext 266</u>		

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22 Lab Name <u>Y-100</u>	23 Date <u>9/27/02</u>	24 Time <u>10:00</u>	25 Microscope Make/Serial # ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079
a Analyzed By <u>100</u>	b QC By		Analysis Methodology PCM - NIOSH 7400A <u>TEM - AFERA</u>
c Lab Batch # <u>6844</u>			
28 Comments			

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY 1 (1/01)

SUBJECT TO PROTECTIVE ORDER NO. 2, SEPT. 2008

CONFIDENTIAL,

CITY_21MC100_003459509



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 2 of 3

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other Push

PROJECT INFORMATION

1 Client <u>NYC - BOE</u>		2 Project Name <u>H.S. of Economics and Finance</u>		3 Project # <u>14524-865</u>		4 Project Monitor <u>M. BALOTA</u>	
		2a Project Address <u>100 Trinity Pl. NY, NY</u>		3a Task # <u>01</u>		4c Rotameter Number <u>HP-128</u>	
5 Date <u>09.26.08</u>		6 Abatement Location <u>Entire</u>		7 ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture _____ Lot # _____		8 ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacture <u>Nuckopore</u> Lot # <u>20.117.617</u>	
				9 Type a ☐ Background b ☐ Pre-Abate		c ☐ Abatement d ☐ Post-Abate e ☐ OSHA f ☐ Environmental g ☒ Ambient h ☐ Other	

DAILY AIR SAMPLE RECORD

10 Sample ID Number	11 Pump Number	12 Sample Location			13 Time (24 hrs clock)			14 Flow Rate (L/min)			15 Total Air Vol (liters)	16 # Fibers/Fields Minus Blank	17 Fiber Conc F/CC
		12a IWA	12b OWA	12c Sample Coordinates	13a Start	13b End	13c Total	14a Start	14b End	14b Avg			
				Field Blank									
				Field Blank									
09		✓		6th floor - Room # 604 Inside the room	16.06	19.26	200	9.0	9.0	9.0	1800		
10		✓		5th floor corridor Adj. to Room # 503	16.07	19.27	200	9.0	9.0	9.0	1800		
11		✓		4th floor - Room # 404 Inside the room	16.09	19.33	204	9.0	9.0	9.0	1836		
12		✓		3rd floor corridor Next to Room # 306	16.10	19.34	204	9.0	9.0	9.0	1836		
13		✓		1st floor - Auditorium Left side of the stage	16.14	19.36	202	9.0	9.0	9.0	1818		
14		✓		1st floor - Lobby Next to Room # 102	16.15	19.38	203	9.0	9.0	9.0	1827		

CHAIN OF CUSTODY

18 Relinquished By		19 Received By		20 Date	21 Time
I <u>M. Balota</u>		<u>R. Kope</u>		<u>09/26/08</u>	<u>12:10</u>
II _____		_____		_____	_____
III _____		_____		_____	_____
26 ATC Project Manager <u>Mark Tejesen</u>		27 Result To <u>Mark Tejesen</u> Beeper/Phone #'s <u>ATC ext 266</u>			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22 Lab Name <u>F&E</u>		23 Date	24 Time
a Analyzed By <u>CEC</u>		<u>09/26/08</u>	
b QC By			
c Lab Batch # <u>1844</u>			
28 Comments			
25 Microscope Make/Serial # ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079			
Analysis Methodology PCM - NIOSH 7400A <u>TEM - AHERA</u>			

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY-1 (1/01)

SUBJECT TO PROTECTIVE ORDER NO. 2, SEPT. 2008

CONFIDENTIAL,

CITY_21MC100_003459510



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 3 of 3

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other Run it

PROJECT INFORMATION

Client <u>NYC - BVE</u>		2 Project Name <u>H.S. of Economics and Finances</u>		3 Project # <u>14584-865</u>		4 Project Monitor <u>M. BALOTA</u>		4c Rotameter Number <u>HP 12B</u>	
Date <u>12/26/02</u>		2a Project Address <u>100 Trinity Pl. NY, NY</u>		3a Task # <u>01</u>		4a Air Sampler <u>M. BALOTA</u>			
6 Abatement Location <u>Entire</u>		7 ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture _____ Lot # _____		8 ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacture <u>Ruckpaw</u> Lot # <u>22.112.615</u>		9 Type a ☐ Background d ☐ Post-Abate b ☐ Pre-Abate e ☐ OSHA		f ☐ Environmental g ☒ Ambient h ☐ Other	

DAILY AIR SAMPLE RECORD

Sample ID Number	Pump Number	12 Sample Location		12c Sample Coordinates	13 Time (24 hrs clock)			14 Flow Rate (L/min)			15 Total Air Vol (liters)	16 # Fibers/Fields Minus Blank	17 Fiber Conc F/CC
		12a IWA	12b OWA		13a Start	13b End	13c Total	14a Start	14b End	14b Avg			
				Field Blank									
				Field Blank									
15			V	Ground floor - Right side of Main Entrance	16.16	19.39	203	9.0	9.0	9.0	1884		
16				Sealed Blank									

CHAIN OF CUSTODY

8 Relinquished By <u>M. Balota</u>	19 Received By <u>R. Kozak</u>	20 Date <u>12/10/02</u>	21 Time <u>02:00</u>
I			
II			
6 ATC Project Manager <u>Mark Tejesen</u>		27 Result To <u>Mark Tejesen</u> Beeper/Phone #'s <u>AIC ext 266</u>	

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22 Lab Name <u>ATC</u>	23 Date <u>12/10/02</u>	24 Time <u>10:00</u>	25 Microscope Make/Serial # ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079
a Analyzed By <u>10/19</u>			
b QC By			
c Lab Batch # <u>6154</u>			Analysis Methodology PCM - NIOSH 7400A <u>TEM - AHERA</u>
28 Comments			

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY-1 (1/01)

SUBJECT TO PROTECTIVE ORDER NO. 2, SEPT. 2008

CONFIDENTIAL,

CITY_21MC100_003459511