ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE: 06-03-02

CLIENT: NYC BOE

PROJECT ADDRESS: M833/100 Trinity Place
New York, NY 10006

PROJECT NO: 41617-0563

SAMPLED BY: C. Mathew

SAMPLE DATE: 06-01-02
DATE RECEIVED: 06-01-02
DATE ANALYZED: 06-01-02

SAMPLE MEDIA: Dust Wipe Sample
ANALYSIS REQUIRED: Method EPA 3050/7420

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu g/ft^2$)	DETECTION LIMIT ($\mu g/ft^2$)
01	9837	10th Floor & South Side Window Sill	<2.3	2.3
02	9837	9th Floor Hallway by Elevator Floor	<9.0	9.0
03	9837	Cafeteria by Entrance Floor	<9.0	9.0
04	9837	Seventh Floor Hallway by Bridge Floor	<9.0	9.0
05	9837	6th Floor Classroom 606 Floor	<9.0	9.0
06	9837	5th Floor Hallway by Rm 506 Floor	<9.0	9.0
07	9837	4th Floor Classroom 408 Floor	<9.0	9.0
08	9837	3rd Floor Hallway by Rm 309 Floor	<9.0	9.0
09	9837	Main Entrance Lobby by Rm Floor	<9.0	9.0
10	9837	Auditorium by Stage Floor	<9.0	9.0
11	9837	Blank	<9.0 µg	9.0 µg

CONFIDENTIAL, CITY_21MC100_003463407

SUBJECT TO PROTECTIVE ORDER NO. 2, SEPT. 2008

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

NOTE 1:
THE REPORTING LIMIT (RL) IS 18.0 µg
NOTE 2:
HUD Guidelines for final clearance dust wipe samples: Floor 40 µg/ft², Window sills 250 µg/ft², Window wells 400 µg/ft², Exterior surfaces 800 µg/ft².
NOTE 3:
Blank units are in µg

CERTIFICATION AND SIGNATURES

ANALYSIS PERFORMED BY: _____

REPORT PREPARED BY: _____

ATC certifies that this report is an accurate and authentic report of results obtained from the laboratory analysis.

QUALITY ASSURANCE COORDINATOR: _____

LABORATORY DIRECTOR: _____

ATC is accredited by the New York State Department of Health Environmental Laboratory Approval Program (ELAP) and by the American Industrial Hygiene Association (AIHA) to perform analysis of lead in paint, dust wipes, air and soil samples. (ELAP #10879), (AIHA #100229).