

ATC ASSOCIATES, INC.

Page 1 of TIME 10:23

INDOOR AIR QUALITY FIELD REPORT

LOCATION 90 Trinity PlDATE 3-7-02PROJECT NO. 19125-0290

Location	Occup.	Temperature (°F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	Respirable Particulates (µg/m³)	TVOCs (ppm)
Main Entry E.H.		55.6	21.4	576	4	93	0.0
E.H. Main Entry South		56.4	23.3	491	4	103	0.0
E.H. Main Entry North		59.4	24.6	517	4	76	0.0
14th fl. Hallway	0	68.6	28.4	568	2	23	0.0
Kitchen	1	72.4	33.5	617	2	25	0.0
Cafeteria	31	68.3	28.5	582	2	21	0.0
Staircase A 14th fl.	4	68.4	28.9	726	2	21	0.0
13th fl. Hallway	1	69.2	27.9	556	2	24	0.0
R. 1305 Libr.	9	69.6	27.3	491	2	31	0.0
Staircase A 12th fl.	9	69.7	28.9	905	2	34	0.0
Guideline levels ASHRAE/AIHA/EPA		68-75°F/winter 73-79°F/summer	30-60%	Outdoor level + 700 ppm	9 ppm	65 µg/m³ 24-hour average	1 ppm

Comments: _____

The assessed location(s) () Does () Does not meet established indoor air quality guidelines.

Signature: W. BleedinebDate: 3-7-02

SUBJECT TO PROTECTIVE ORDER NO. 2, SEPT. 2008

CONFIDENTIAL,

CITY_21MC100_003463572

ATC ASSOCIATES, INC.

Page 2 of TIME 10:48

INDOOR AIR QUALITY FIELD REPORT

LOCATION 90 Trinity Pl DATE 3-7-02 PROJECT NO. 19125-0290

Location	Occup.	Temperature (°F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	Respirable Particulates(µg/m ³)	TVOCs (ppm)
10th fl. Hallway	2	69.8	30.3	923	2	23	0.0
R. 1203	2	70.1	29.3	734	2	11	0.0
R. 1205	2	70.2	29.4	648	2	34	0.0
R. 1209	4	70.9	29.3	779	2	23	0.0
R. 1215	15	71.1	28.8	726	2	22	0.0
Staircase B 12th fl.	0	70.5	28.7	766	2	24	0.0
11th floor Hallway	0	69.8	29.1	820	2	22	0.0
R. 1115	8	70.5	29.4	917	2	22	0.0
R. 1109	29	70.7	29.5	914	2	25	0.0
R. 1105	13	70.4	27.8	654	2	25	0.0
Guideline levels ASHRAE/AHIA/EPA		68-75°F/winter 73-79°F/summer	30-60%	Outdoor level + 700 ppm	9 ppm	65 µg/m ³ 24-hour average	1 ppm

Comments: _____

The assessed location(s) () Does () Does not meet established indoor air quality guidelines.

Signature: M. Meier Date: 3-7-02

SUBJECT TO PROTECTIVE ORDER NO. 2, SEPT. 2008

CONFIDENTIAL,

CITY_21MC100_003463573

ATC ASSOCIATES, INC.

Page 3 of TIME 11:07

INDOOR AIR QUALITY FIELD REPORT

LOCATION 90 Trinity PlDATE 3-7-02PROJECT NO. 19125-0290

Location	Occup.	Temperature (°F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	Respirable Particulates (µg/m³)	TVOCs (ppm)
Staircase A 10th fl.	1	70.0	27.8	692	2	22	0.0
10th fl. Hallway	0	69.7	27.8	673	2	23	0.0
R. 1006	31	70.3	28.9	795	2	35	0.0
R. 1009	28	70.6	29.9	1023	2	28	0.0
Staircase B 9th fl.	0	70.3	27.9	669	2	24	0.0
9th fl. Hallway	0	69.4	27.3	579	2	21	0.0
R. 905	0	69.0	27.7	596	2	22	0.0
R. 909	0	69.8	27.4	587	2	22	0.0
R. 906	3	69.3	26.7	534	2	26	0.0
R. 905	31	70.0	29.9	966	2	23	0.0
Guideline levels ASHRAE/AIHA/EPA		68-75°F/winter 73-79°F/summer	30-60%	Outdoor level + 700 ppm	9 ppm	65 µg/m³ 24-hour average	1 ppm

Comments: _____

The assessed location(s) () Does () Does not meet established indoor air quality guidelines.

Signature: M. Medeiros Date: 3-7-02

SUBJECT TO PROTECTIVE ORDER NO. 2, SEPT. 2008

CONFIDENTIAL,

CITY_21MC100_003463574

ATC ASSOCIATES, INC.

Page 4 of TIME 11:38

INDOOR AIR QUALITY FIELD REPORT

LOCATION 90 Trinity PlDATE 3-7-02PROJECT NO. 19125-0290

Location	Occup.	Temperature (°F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	Respirable Particulates (µg/m ³)	TVOCs (ppm)
Staircase A 8th fl.	0	70.0	27.7	665	2	21	0.0
8th fl. hallway	0	69.9	27.6	649	2	24	0.0
R. 809	23	70.4	28.6	860	2	23	0.0
R. 815	7	70.7	28.1	709	2	25	0.0
Staircase B 7th fl.	0	70.8	27.9	662	2	33	0.0
7th fl. hallway	12	69.7	27.2	610	2	24	0.0
R. 715	2	70.5	27.0	571	2	22	0.0
R. 713	0	71.1	26.9	554	2	23	0.0
R. 711	0	71.0	26.6	509	2	25	0.0
R. 705	2	70.8	27.2	686	2	20	0.0
Guideline levels ASHRAE/AIHA/EPA		68-75°F/winter 73-79°F/summer	30-60%	Outdoor level + 700 ppm	9 ppm	65 µg/m ³ 24-hour average	1 ppm

Comments: _____

The assessed location(s) () Does () Does not meet established indoor air quality guidelines.

Signature: M. Medineh Date: 3-7-02

SUBJECT TO PROTECTIVE ORDER NO. 2, SEPT. 2008

CONFIDENTIAL,

CITY_21MC100_003463575

ATC ASSOCIATES, INC.

Page 5 of TIME 11:57

INDOOR AIR QUALITY FIELD REPORT

LOCATION 90 Trinity PLDATE 3-7-02PROJECT NO. 19125-0290

Location	Occup.	Temperature (°F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	Respirable Particulates (µg/m ³)	TVOCs (ppm)
R-702	1	70.2	26.8	566	2	25	0.0
Staircase A 6th fl.	0	70.5	27.3	668	2	28	0.0
6th fl. Hallway	19	70.3	28.4	768	2	24	0.0
R-603	1	70.7	27.7	695	2	24	0.0
R-602	3	70.8	28.1	726	2	32	0.0
R-604	1	70.8	27.4	680	2	36	0.0
R-611	1	70.8	27.9	684	2	21	0.0
Staircase A 5th fl.	2	71.0	29.2	891	2	25	0.0
5th fl. Hallway	0	70.5	28.9	613	2	39	0.0
R-503	25	70.3	27.5	613	2	40	0.0
Guideline levels ASHRAE/AIHA/EPA		68-75°F/winter 73-79°F/summer	30-60%	Outdoor level + 700 ppm	9 ppm	65 µg/m ³ 24-hour average	1 ppm

Comments: _____

The assessed location(s) () Does () Does not meet established indoor air quality guidelines.

Signature: W. Weelink Date: 3-7-02

SUBJECT TO PROTECTIVE ORDER NO. 2, SEPT. 2008

CONFIDENTIAL,

CITY_21MC100_003463576

ATC ASSOCIATES, INC.

Page 6 of TIME 12:10

INDOOR AIR QUALITY FIELD REPORT

LOCATION 90 Trinity PlDATE 3-7-02PROJECT NO. 19125-0290

Location	Occup.	Temperature (°F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	Respirable Particulates (µg/m³)	TVOCs (ppm)
R. 508	0	70.3	27.2	541	2	40	0.0
R. 515	15	71.0	28.9	697	2	34	0.0
Staircase # 4th fl.	0	70.8	28.5	694	2	29	0.0
4th fl. Hallway	0	69.8	27.4	558	2	34	0.0
R. 415	9	70.1	26.6	551	2	33	0.0
R. 404	9	70.3	27.0	589	2	36	0.0
R. 403	2	70.2	26.8	529	2	37	0.0
Staircase # 3rd fl.	0	70.0	26.7	594	2	35	0.0
3rd fl. Hallway	0	70.2	28.4	675	2	31	0.0
R. 305	37	71.6	31.0	1082	2	44	0.0
Guideline levels ASHRAE/AIHA/EPA		68-75°F/winter 73-79°F/summer	30-60%	Outdoor level + 700 ppm	9 ppm	65 µg/m³ 24-hour average	1 ppm

Comments: _____

The assessed location(s) () Does () Does not meet established indoor air quality guidelines.

Signature: M. UedineDate: 3-7-02

SUBJECT TO PROTECTIVE ORDER NO. 2, SEPT. 2008

CONFIDENTIAL,

CITY_21MC100_003463577

ATC ASSOCIATES, INC.

Page 7 of TIME 12:37

INDOOR AIR QUALITY FIELD REPORT

LOCATION 90 Trinity PlDATE 3-7-02PROJECT NO. 19125-0290

Location	Occup.	Temperature (°F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	Respirable Particulates(µg/m ³)	TVOCs (ppm)
R. 309	24	72.2	30.4	753	2	29	0.0
R. 315	1	71.7	27.4	565	2	29	0.0
2nd fl. Hallway	0	70.4	28.1	621	2	24	0.0
R. 206 Lecture Room	0	71.1	27.4	730	2	36	0.0
18th Hallway	0	74.3	31.3	674	2	40	0.0
Gym	0	75.8	29.9	716	2	40	0.0
1st fl. Main Lobby	5	69.5	26.1	507	2	33	0.0
Ext. Main Entr.		64.7	25.8	423	3	78	0.0
Ext. Main Entr. North		64.5	25.4	411	3	64	0.0
Ext. Main Entr. South		63.8	25.2	401	3	73	0.0
Guideline levels ASHRAE/AHIA/EPA		68 -75°F/winter 73 -79°F/summer	30-60%	Outdoor level + 700 ppm	9 ppm	65 µg/m ³ 24-hour average	1 ppm

Comments: _____

The assessed location(s) () Does () Does not meet established indoor air quality guidelines.

Signature: W. WeidnerDate: 3-7-02

SUBJECT TO PROTECTIVE ORDER NO. 2, SEPT. 2008

CONFIDENTIAL,

CITY_21MC100_003463578

ATC ASSOCIATES, INC.

Page 8 of TIME 14:01

INDOOR AIR QUALITY FIELD REPORT

LOCATION 90 Trinity PlDATE 3-7-02PROJECT NO. 19125-0290

Location	Occup.	Temperature (°F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	Respirable Particulates (µg/m³)	TVOCs (ppm)
Ext. Main Entr.		58.4	24.3	621	4	117	0.0
Ext. Main Entr. Souther		58.9	25.6	634	4	123	0.0
Ext. Main Entr. North		60.0	26.4	643	3	68	0.0
14th Fl. Hallway		67.8	23.2	721	2	25	0.0
Kitchen		73.4	34.5	686	2	20	0.0
Cafeteria		68.5	29.4	811	2	21	0.0
Staircase A 14th Fl.		68.9	29.7	724	2	16	0.0
13th Fl. Hallway		71.3	28.6	556	2	21	0.0
Library		71.4	27.1	911	2	24	0.0
Staircase A 12th Fl.		70.3	29.1	613	2	18	0.0
Guideline levels ASHRAE/AIHA/EPA		68 -75°F/winter 73 -79°F/summer	30-60%	Outdoor level + 700 ppm	9 ppm	65 µg/m³ 24-hour average	1 ppm

Comments: _____

The assessed location(s) ☐ Does ☐ Does not meet established indoor air quality guidelines.Signature: W. Alledine Date: 3-7-02

SUBJECT TO PROTECTIVE ORDER NO. 2, SEPT. 2008

CONFIDENTIAL,

CITY_21MC100_003463579

ATC ASSOCIATES, INC.

Page 9 of 9

TIME 14:23

INDOOR AIR QUALITY FIELD REPORT

LOCATION 90 Trinity PLDATE 3-7-02PROJECT NO. 19125-0290

Location	Occup.	Temperature (°F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	Respirable Particulates (µg/m³)	TVOCs (ppm)
10th Fl. Hallway	0	71.3	29.3	927	2	21	0.0
R. 1203	0	72.4	30.1	811	2	14	0.0
R. 1205	0	71.8	29.5	846	2	30	0.0
R. 1209	0	71.1	29.5	784	2	20	0.0
R. 1215	7	72.3	29.9	731	2	20	0.0
Staircase B 12th Fl.	0	70.4	31.4	694	2	22	0.0
11th Fl. Hallway	0	70.9	30.8	903	2	11	0.0
R. 1115	0	70.9	29.7	987	2	19	0.0
R. 1109	0	70.0	28.3	846	2	16	0.0
R. 1105	0	73.0	34.1	599	2	25	0.0
Guideline levels ASHRAE/AIHA/EPA		68-75°F/winter 73-79°F/summer	30-60%	Outdoor level + 700 ppm	9 ppm	65 µg/m³ 24-hour average	1 ppm

Comments: _____

The assessed location(s) () Does () Does not meet established indoor air quality guidelines.

Signature: Al. UedinehDate: 3-7-02

SUBJECT TO PROTECTIVE ORDER NO. 2, SEPT. 2008

CONFIDENTIAL,

CITY_21MC100_003463580

ATC ASSOCIATES, INC.

Page 10 of TIME 14:49

INDOOR AIR QUALITY FIELD REPORT

LOCATION 90 Trinity PlDATE 3-7-02PROJECT NO. 19125-0290

Location	Occup.	Temperature (°F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	Respirable Particulates (µg/m³)	TVOCs (ppm)
Staircase # 10th fl.	0.0	74.1	28.6	721	2	20	0.0
10th fl. Hallway	0	71.8	28.3	717	2	19	0.0
R. 1006	4	72.3	29.5	834	2	18	0.0
R. 1009	7	72.1	26.7	987	2	14	0.0
Staircase B 9th fl.	0	69.4	25.8	720	2	23	0.0
9th fl. Hallway	0	71.5	27.5	676	2	28	0.0
R. 915	0	70.8	26.8	688	2	17	0.0
R. 909	0	73.4	26.7	617	2	19	0.0
R. 906	0	71.2	27.6	620	2	21	0.0
R. 905	0	73.0	31.1	911	2	23	0.0
Guideline levels ASHRAE/AIHA/EPA		68-75°F/winter 73-79°F/summer	30-60%	Outdoor level + 700 ppm	9 ppm	65 µg/m³ 24-hour average	1 ppm

Comments: _____

The assessed location(s) () Does () Does not meet established indoor air quality guidelines.

Signature: W. Uedineh Date: 3-7-02

SUBJECT TO PROTECTIVE ORDER NO. 2, SEPT. 2008

CONFIDENTIAL,

CITY_21MC100_003463581

ATC ASSOCIATES, INC.

Page 10 of 10TIME 15:17

INDOOR AIR QUALITY FIELD REPORT

LOCATION 90 Trinity PlDATE 3-7-02PROJECT NO. 19125-0290

Location	Occup.	Temperature (°F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	Respirable Particulates($\mu\text{g}/\text{m}^3$)	TVOCs (ppm)
Staircase A 8th fl.	0	73.1	26.7	629	2	19	0.0
8th fl. Hallway	0	72.4	26.9	827	2	14	0.0
R. 809	1	73.6	29.3	921	2	18	0.0
R. 815	0	73.6	27.4	820	2	22	0.0
Staircase B 7th fl.	0	72.9	28.7	729	2	35	0.0
7th fl. Hallway	0	71.8	29.3	721	2	19	0.0
R. 715	0	72.1	27.6	884	2	30	0.0
R. 713	0	73.7	27.9	728	2	32	0.0
R. 711	0	72.9	25.4	825	2	27	0.0
R. 705	0	71.4	26.3	829	2	29	0.0
Guideline levels ASHRAE/AHIA/EPA		68-75°F/winter 73-79°F/summer	30-60%	Outdoor level + 700 ppm	9 ppm	65 $\mu\text{g}/\text{m}^3$ 24-hour average	1 ppm

Comments: _____

The assessed location(s) ☐ Does ☐ Does not meet established indoor air quality guidelines.Signature: Mr. NeedlesDate: 3-7-02

SUBJECT TO PROTECTIVE ORDER NO. 2, SEPT. 2008

CONFIDENTIAL,

CITY_21MC100_003463582

ATC ASSOCIATES, INC.

Page 2 of TIME 15:40

INDOOR AIR QUALITY FIELD REPORT

LOCATION 90 Trinity Pl DATE 3-7-02 PROJECT NO. 19125-0290

Location	Occup.	Temperature (°F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	Respirable Particulates(µg/m ³)	TVOCs (ppm)
R. 702	0	72.4	25.7	624	2	26	0.0
Staircase # 6th fl.	3	72.9	26.3	676	2	20	0.0
R. 603	6	73.1	28.1	812	2	14	0.0
R. 602	0	71.4	27.4	727	2	18	0.0
R. 604	0	72.8	27.9	843	2	24	0.0
R. 611	11	70.8	27.4	728	2	20	0.0
Staircase A 5th fl.	0	71.4	28.9	695	2	26	0.0
5th fl. Hallway	0	72.0	28.2	911	2	31	0.0
6th fl. Hallway	0	71.9	29.9	786	2	20	0.0
R. 503	0	70.8	27.8	692	2	24	0.0
Guideline levels ASHRAE/AIHA/EPA		68-75°F/winter 73-79°F/summer	30-60%	Outdoor level + 700 ppm	9 ppm	65 µg/m ³ 24-hour average	1 ppm

Comments: _____

The assessed location(s) () Does () Does not meet established indoor air quality guidelines.

Signature: Al. Mednick Date: 3-7-02

SUBJECT TO PROTECTIVE ORDER NO. 2, SEPT. 2008

CONFIDENTIAL,

CITY_21MC100_003463583

ATC ASSOCIATES, INC.

Page 13 of TIME 15:59

INDOOR AIR QUALITY FIELD REPORT

LOCATION 90 Trinity PlDATE 3-7-02PROJECT NO. 19125-0290

Location	Occup.	Temperature (°F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	Respirable Particulates (µg/m³)	TVOCs (ppm)
R. 506	0	71.6	26.2	621	2	26	0.0
R. 515	3	72.4	27.4	718	2	31	0.0
Staircase B 4th fl.	0	71.7	27.2	737	2	25	0.0
4th fl. Hallway	0	70.4	26.9	642	2	27	0.0
R. 415	0	72.8	25.8	622	2	30	0.0
R. 404	0	71.9	26.4	710	2	25	0.0
R. 403	0	71.1	25.4	643	2	20	0.0
Staircase A 3rd fl.	0	72.3	25.3	674	2	24	0.0
3rd fl. Hallway	0	71.8	27.1	622	2	23	0.0
R. 305	0	73.8	29.8	986	2	30	0.0
Guideline levels ASHRAE/AHIA/EPA		68 -75°F/winter 73 -79°F/summer	30-60%	Outdoor level + 700 ppm	9 ppm	65 µg/m³ 24-hour average	1 ppm

Comments: _____

The assessed location(s) ☐ Does ☐ Does not meet established indoor air quality guidelines.

Signature: _____

Date: _____

SUBJECT TO PROTECTIVE ORDER NO. 2, SEPT. 2008

CONFIDENTIAL,

CITY_21MC100_003463584

ATC ASSOCIATES, INC.
INDOOR AIR QUALITY FIELD REPORT

Page 14 of TIME 18:23LOCATION 90 Trinity PlDATE 3-7-02PROJECT NO. 19125-0290

Location	Occup.	Temperature (°F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	Respirable Particulates (µg/m³)	TVOCs (ppm)
R. 309	3	73.8	29.5	826	2	26	0.0
R. 315	6	72.6	28.1	658	2	29	0.0
2nd. Fl. Hallway	4	71.9	27.7	708	2	23	0.0
R. 206	0	72.3	26.8	818	2	31	0.0
88m Hallway	0	76.4	30.1	696	2	40	0.0
Gym	0	77.2	28.5	710	2	40	0.0
1st. Fl. Main lobby	0	68.7	25.8	684	2	32	0.0
Ext. Main Entry	0	61.7	25.3	504	4	96	0.0
Ext. Main Entry North	0	59.4	24.9	496	4	108	0.0
Ext. Main Entry South	0	60.8	25.6	499	3	111	0.0
Guideline levels ASHRAE/AIHA/EPA		68-75°F/winter 73-79°F/summer	30-60%	Outdoor level + 700 ppm	9 ppm	65 µg/m³ 24-hour average	1 ppm

Comments: _____

The assessed location(s) ☐ Does ☐ Does not meet established indoor air quality guidelines.

Signature: _____ Date: _____

SUBJECT TO PROTECTIVE ORDER NO. 2, SEPT. 2008

CONFIDENTIAL,

CITY_21MC100_003463585