ATC ASSOCIATES INC

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 1 of 1

TURNAROUND TIME

[ ] 2 hrs [ ] 6 hrs [ ] 48 hrs [ ] Standard
[ ] 4 hrs [ ] 24 hrs [ ] 72 hrs [ ] Other

8965 9/12 3152-3163

PROJECT INFORMATION

1. Client: DEP
2. Project Name: DEP clean up
2a. Project Address: 125 Cedar St NY
3. Project #: 15-22306-0002
3a. Task #: 00002
4. Project Monitor:
4a. Air Sampler: E. Lemanovich
4c. Rotameter Number: SD-006
5. Date: 9.27.2
6. Abatement Location: Around building
7. [ ] PCM (0.8 micron MCE) Cassette Filter Manufacture Lot #
8. [✓] TEM (0.45 micron MCE) Cassette Filter Manufacture MMI Lot # 916
9. Type: a. [ ] Background b. [ ] Pre-Abate c. [ ] Abatement d. [ ] Post Abate e. [ ] OSHA f. [ ] Environmental g. [ ] Ambient h. [✓] Other Cleaning

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock) 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.) 14a. Start	14b. End	14b. Avg	15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
01				Field Blank									
02, 03				Field Blank									
04			✓	In front of building	06:30	14:00	450	4	4	4	1800		
05			✓	— " —	06:31	14:01	450	4	4	4	1800		
06			✓	In back of building	06:40	14:10	450	4	4	4	1800		
07			✓	— " —	06:41	14:11	450	4	4	4	1800		
08			✓	— " —	06:42	14:12	450	4	4	4	1800		
09			✓	— " —	06:43	14:13	450	4	4	4	1800		
10			✓	— " —	06:44	14:14	450	4	4	4	1800		
11			✓	Hallway Clean room of decon	06:50	14:20	450	4	4	4	1800		
12			✓	2nd floor — " —	06:54	14:24	450	4	4	4	1800		

CHAIN OF CUSTODY

18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I E Lemanovich		9.27.2	
II	TG	9/27/02	16:00
III			

26. ATC Project Manager: B. Sabbemi

27. Result To: B. Sabbemi
Beeper/Phone #'s

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: TEC	23. Date:	24. Time:
a. Analyzed By: [signature]	9/28	11:20
b. QC By:		
c. Lab Batch #:		

28. Comments:

25. Microscope Make/Serial #:
[ ] Nikon Labophot 238913
[ ] Nikon Labophot 238917
[ ] Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

WHITE - File YELLOW - Client Report PINK - Lab GOLDENROD - Field

NY 1 (3/01)

CITY_21MC100_009369169