



AIR MONITORING DATA AND

CHAIN OF CUSTODY FORM

Page 1 of 1

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☒ 24 hrs ☐ 72 hrs ☐ Other _____

PROJECT INFORMATION

1. Client DEP		2. Project Name DEP Clean up		3. Project # 15-12306-0002		4. Project Monitor: E. Lemnovich		4c. Radiometer Monitor: HP 22	
5. Date: 10.16.02		6. Abatement Location: Shaft of elevator		7. ☒ PCM (0.5 micron MCE) Cassette/Titer Manufacturer Lot # 91344102		8. ☐ TEM (0.45 micron MCE) Cassette/Titer Manufacturer Lot #		9. Type: a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☐ Ambient h. ☒ Monitor Clean-up	
2a. Project Address 125 Cedar St NY		3a. Task # 00002		4a. Air Sampler E. Lemnovich					

DAILY AIR SAMPLE RECORD

[illegible]

CHAIN OF CUSTODY

18. Relinquished By:	19. Received By:	20. Date:	21. Time:
E. Lemarovich	<i>[Signature]</i>	10.16.02	21.40
IT			
UUT			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: <u>ASC</u>	23. Date: <u>10/16/02</u>	24. Time: <u>2:25 PM</u>	25. Microscope Make/Serial # <u>Nikon Labophot 239079</u>
a. Analyzed by: <u>W. Hooper</u>			☐ Nikon Labophot 239013
b. QC By:			☐ Nikon Labophot 238917
c. Lab Batch #: <u>101632</u>			☐ Nikon Labophot 239079

26. ATC Project Manager: B. Sallemi	27. Result To: <u>B. Sallemi</u> Description # 's _____
--	--

28. Comments

Analysis Methodology
J PCM - NIOSH 7400A
TEAM - AHEPA

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field -

NY-1 (109)

10/18/2002 15:53 FAX 212 353 8306

ATC

003

CITY_21MC100_009369427

NYC-WTC_000181824