

Asbestos Inspection Report

Premise No. 130 Liberty Street					Inspection Date: 10/30/08	
Floor Various	Zip 10006	Borough 1	Block 54	Lot 1	Squad # 1	Badge # AO61
Inspector H. Guirguis		Building Type A		Basis of Inspection TRU0086MN08		Photos Taken NO
Contractor's Name LVI Environmental				Sample Number -----		
Address City				Sample Number -----		
State Zip Phone				Sample Number -----		
Laboratory Name TRC Environmental Corp				Owner's Name The Lower Manhattan Development Corp.		
Address 1430 Broadway		City New York		Address One Liberty Plaza		City New York
State NY	Zip 10018	Phone		State NY	Zip 10006	Phone (212) 962-2300
Contact Person Arnel Javal, Sr. Proj. Mgr./TRC Environmental				Time of Inspection from: 08:00am – 09:30am		
<p>On arrival I met Nugent Gerald, supervisor for LVI Environmental, at the LVI field office. He informed me that a total of 1 Handler Supervisor and 7 Asbestos Handlers were in the north vestibule of the 16th floor today for the first shift.</p> <p>The daily work schedule informed me of the following:</p> <ol style="list-style-type: none"> 1. 11th floor: 32 men- scraping area 11-13 box debris. 2. 8th floor: 34 men- demo, boxing debris, putting platform across shafts 3. 7th floors: 4 men- demo, boxing debris 4. 6th floors: 30 men- demo, boxing debris 4. Various floors : 12 men loading out boxes to ATC trailer <p>I used the north hoist to 15th floor and stair A from the 15th floor to proceed to the north vestibule on the 16th floor.</p> <p>No log book was observed on the floor, the supervisor informed me that all the workers signed on 7th floor and then moved to the 16th floor.</p> <p>I donned personal protection and accessed the work areas</p> <p>The workers were found in the process of preparing the work area, bringing the equipment in (4 HEPA vacuums, 1 jackhammer, concrete saw, crow bars, and metal cutting tools), setting up the scaffolds and fine spraying amended water in the work area. Inspection was done on the Micro trap Machines and on all the work area</p> <p>I exited the work area after decontaminating myself.</p>						
NOV #	Infraction	Infraction	Infraction	Infraction	Infraction	
NOV #	Infraction	Infraction	Infraction	Infraction	Result Code 2	
NOV #	Infraction	Infraction	Infraction	Infraction	Supervisor's Initial <i>ref</i>	

Borough 1=Manhattan 2=Bronx 3=Brooklyn 4=Queens 5=Richmond
 Building Type A ≥6 stories B <6 stories C single family D school E hospital F public owned
 Result Code 1 = Violation Issued 2=No Violation Issued 3=No access 4=Project not started (no NOV)
 5=Public Owned Property