Asbestos Inspection Report

Premise No. 130 Liberty Street					Inspection Date: 10/28/08	
Floor Various	Zip 10006	Borough 1	Block 54	Lot 1	Squad # 1	Badge # AO61

Inspector H. Guirguis	Building Type A	Basis of Inspection TRU0086MN08	Photos Taken NO

Contractor's Name LVI Environmental	Sample Number ----------
Address City	Sample Number ----------
State Zip Phone	Sample Number ----------
Laboratory Name TRC Environmental Corp	Owner's Name The Lower Manhattan Development Corp.
Address City 1430 Broadway New York	Address City One Liberty Plaza New York
State Zip Phone NY 10018	State Zip Phone NY 10006 (212) 962-2300
Contact Person Arnel Javal, Sr. Proj. Mgr./TRC Environmental	Time of Inspection from: 08:00am – 09:00am

On arrival I met Nugent Gerald, Supervisor for LVI Environmental at the LVI field office, who informed me that a total of 1 Handler Supervisor and 30 Asbestos Handlers were in the 6th floor today for the first shift.
The daily work schedule informed me of the following:
1. **11th floor**: 32 men- scraping area 11-13, box debris.
2. **8th floor**: 34 men- demo, boxing debris, putting platform across shafts
3. **7th floors**: 8 men- demo, boxing debris
4. **6th floors**: 30 men- demo, boxing debris
4. **Various floors** : 12 men loading out boxes to ATC trailer

After signing the log book donned personal protection and accessed the work areas.

1. 6th floor: workers were found in the process of Demo, boxing debris; there was still a lot of wet debris on the floor, demolition was not completed, workers were cutting metals using power tools, HEPA vacuum attached with the power tools, fine spraying amended water in the work area, preparing Gaylord boxes, Inspection was done on the Micro trap Machines and the Micro trap tents and on all the work area
   I used the stairs to go to the 7th floor
2. 7th, 9th and 10th floor: There were no activity or personnel observed on the floor
   Gaylord boxes and numerous poly wrapped beams were on the floor ready to be taken out
3. 8th floor: workers were found in the process of demo, boxing debris, putting platform across shafts, fine spraying amended water on the Gaylord boxes, poly wrapped beams and the work area, preparing Gaylord boxes and poly wrapped beams,
   Inspection was done on the Micro trap Machines and the Micro trap tents. 20 Micro trap Machines were powered on and 5 were on stand by,
   Gaylord boxes and numerous poly wrapped beams were on the floor ready to be taken out
4. 11th floor: workers were found in the process of cleaning the floor, the beams and wet wiping the walls, HEPA vacuuming the floor, preparing Gaylord boxes
   Inspection was done on the Micro trap Machines and the Micro trap tents. 20 Micro trap Machines were powered on and 5 were on stand by,
   I used the stairs to get to the 6th floor.

I exited the work area after decontaminating and signing the log book.

NOV #	Infraction	Infraction	Infraction	Infraction
NOV #	Infraction	Infraction	Infraction	Result Code 2
NOV #	Infraction	Infraction	Infraction	Supervisor's Initial MJ

Borough 1=Manhattan 2=Bronx 3=Brooklyn 4=Queens 5=Richmond
Building Type A ≥6 stories B <6 stories C single family D school E hospital F public owned
Result Code 1 = Violation Issued 2=No Violation Issued 3=No access 4=Project not started (no NOV)
5=Public Owned Property