

Asbestos Inspection Report

Premise No. 130 Liberty Street					Inspection Date: 10/27/08	
Floor Various	Zip 10006	Borough 1	Block 54	Lot 1	Squad # 1	Badge # AO61
Inspector H. Guirguis		Building Type A		Basis of Inspection TRU0086MN08		Photos Taken Yes
Contractor's Name LVI Environmental				Sample Number -----		
Address City				Sample Number -----		
State Zip Phone				Sample Number -----		
Laboratory Name TRC Environmental Corp				Owner's Name The Lower Manhattan Development Corp.		
Address 1430 Broadway		City New York		Address One Liberty Plaza		City New York
State NY	Zip 10018	Phone		State NY	Zip 10006	Phone (212) 962-2300
Contact Person Arnel Javal, Sr. Proj. Mgr./TRC Environmental				Time of Inspection from: 08:00am – 09:30am		
On arrival I met Nugent Gerald, Supervisor for LVI Environmental at the LVI field office, who informed me that on 15th and 14th floor a total of 1 Handler Supervisor and 4 Asbestos Handlers were in the south compromise bay on each floor today for the first shift. The daily work schedule informed me of the following: 1. 11th floor: 32 men- scraping area 11-13, box debris. 2. 8th floor: 34 men- demo, boxing debris, putting platform across shafts 3. 7th floors: 8 men- demo, boxing debris 4. 6th floors: 30 men- demo, boxing debris 4. Various floors: 12 men loading out boxes to ATC trailer After signing the log book donned personal protection I entered the work area. 1. 14th floor: workers were found in the process of HEPA vacuuming the floor after removing the walker duct, boxing debris, fine spraying amended water was being performed on the work area Demo, boxing debris Inspection was done on the Micro trap Machines. I exited the work area after decontaminating myself and signing the log book. I used the stairs to go to the 15th floor After signing the log book donned personal protection I entered the work area. 1. 15th floor: workers were found in the process of jack hammering the floor, and using crow bars to remove walker ducts, cutting the metal ducts into smaller pieces before rapping, , HEPA vacuum attached with the power tools boxing debris, fine spraying amended water was being performed on the work area. I exited the work area after decontaminating myself and signing the log book.						
NOV #	Infraction	Infraction	Infraction	Infraction	Infraction	
NOV #	Infraction	Infraction	Infraction	Infraction	Result Code 2	
NOV #	Infraction	Infraction	Infraction	Infraction	Supervisor's Initial <i>nyf</i>	

Borough 1=Manhattan 2=Bronx 3=Brooklyn 4=Queens 5=Richmond
 Building Type A ≥6 stories B <6 stories C single family D school E hospital F public owned
 Result Code 1 = Violation Issued 2=No Violation Issued 3=No access 4=Project not started (no NOV)
 5=Public Owned Property