

Asbestos Inspection Report

Premise No. 130 Liberty Street					Inspection Date: 07/28/08	
Floor Various	Zip 10006	Borough 1	Block 54	Lot 1	Squad # 1	Badge # AO61
Inspector H. Guirguis		Building Type A		Basis of Inspection TRU0086MN08		Photos Taken Yes
Contractor's Name LVI Environmental				Sample Number _____		
Address City				Sample Number _____		
State Zip Phone				Sample Number _____		
Laboratory Name TRC Environmental Corp				Owner's Name The Lower Manhattan Development Corp.		
Address City 1430 Broadway New York				Address City One Liberty Plaza New York		
State Zip Phone NY 10018				State Zip Phone NY 10006 (212) 962-2300		
Contact Person Arnel Javal, Sr. Proj. Mgr./TRC Environmental				Time of Inspection from: 9:20 am – 10:00 am		
<p>On arrival I met Victor, a Project Monitor of TRC Environmental, at the TRC field office who informed me that a total of 1 Supervisor and 24 Asbestos Handlers were on the 14th floor for the first shift.</p> <p>The daily work schedule informed me of the following:</p> <ol style="list-style-type: none"> 1. 16th, 17th floors: 30 men fine cleaning floors 2. 14th & 15th floors: 24 men scraping, boxing debris 3. 13th & 12th floors: 16 men demo, boxing debris 4. 8th & 7th floor: 6 men setting up Micro traps 5. 6 men - various floors loading out boxes to ATC trailer <p>I went to the decontamination enclosure system on the 14th floor where I met Rocco, the Handler supervisor. After signing the log book I donned personal protection and accessed the work areas.</p> <ol style="list-style-type: none"> 1. The workers were found in the process of scraping and boxing debris 2. Only 22 workers were in the work area and 1 worker in the decontamination enclosure system 3. The workers were found in the process of Scraping and wrapping debris <ul style="list-style-type: none"> 8 workers on scaffolds, cleaning ceilings and beams 8 workers removing debris from ground 3 workers fine spraying amended water in the work area 3 workers preparing Gaylord boxes 18 Gaylord boxes on the floor ready to be taken out 4. Inspection was done on the Micro trap Machines and the Micro trap tents. 20 Micro trap Machines were powered on and 5 were on stand by 5. The Negative Pressure was 0.069 <p>I exited the work area after decontaminating myself and signing the log book.</p>						
NOV #	Infraction	Infraction	Infraction	Infraction		
NOV #	Infraction	Infraction	Infraction	Result Code 2		
NOV #	Infraction	Infraction	Infraction	Supervisor's Initial <i>rmj</i> 7/28/08		

Borough 1=Manhattan 2=Bronx 3=Brooklyn 4=Queens 5=Richmond
Building Type A ≥6 stories B <6 stories C single family D school E hospital F public owned
Result Code 1 = Violation Issued 2=No Violation Issued 3=No access 4=Project not started (no NOV)
5=Public Owned Property