

Asbestos Inspection Report

Premise No. 130 Liberty Street					Inspection Date: 07/22/08	
Floor Various	Zip 10006	Borough 1	Block 54	Lot 1	Squad # 1	Badge # AO61
Inspector H. Guirguis		Building Type A		Basis of Inspection TRU0086MN06		Photos Taken Yes
Contractor's Name LVI Environmental				Sample Number -----		
Address City				Sample Number -----		
State Zip Phone				Sample Number -----		
Laboratory Name TRC Environmental Corp				Owner's Name The Lower Manhattan Development Corp.		
Address City 1430 Broadway New York				Address City One Liberty Plaza New York		
State Zip Phone NY 10018				State Zip Phone NY 10006 (212) 962-2300		
Contact Person Arnel Javal, Sr. Proj. Mgr./TRC Environmental				Time of Inspection from: 6:00 pm – 7:00 pm		
<p>On arrival, I met Victor, a Project Monitor for TRC Environmental at TRC field office, who informed me that a total of 1 Handler Supervisor and 18 Asbestos Handlers were on the 15th floor today for the Second shift. The daily work schedule informed me of the following:</p> <ol style="list-style-type: none"> 1. 16th, 17th floors: 20 men (each) Setting up for cleaning floor. 2. 14th & 15th floors: 18 men (each) Demo, Wrapping debris & Boxing 3. 13th & 12th floors: 12men Setting up floors 4. 12 men - Various floors Loading out boxes to ATC trailer <p>I went to the decontamination enclosure system on the 15th floor and after signing the log book, donned personal protection and accessed the work areas.</p> <ol style="list-style-type: none"> 1. The workers were found in the process of wrapping debris <ul style="list-style-type: none"> 9 workers cleaning scaffolds parts preparing it to be ready to taken out 4 workers removing debris from ground 2 workers fine spraying amended water in the work area 2 workers preparing Gaylord boxes 1 worker in the decontamination enclosure system 15 Gaylord boxes and numerous poly wrapped beams piled on the floor ready to be taken out 2. Inspection was done on the Micro trap Machines and the Micro trap tents and on all the work area. 3. I observed part of the plastic missing around the 15A exit, the supervisor was advised and he covered the area with plastic and tape. 4. The Negative Pressure was 0.055 <p>I exited the work area after decontaminating myself and signing the log book.</p>						
NOV #	Infraction	Infraction	Infraction	Infraction		
NOV #	Infraction	Infraction	Infraction	Infraction	Result Code 2	
NOV #	Infraction	Infraction	Infraction	Infraction	Supervisor's Initial <i>my</i> <i>7/22/08</i>	

Borough 1=Manhattan 2=Bronx 3=Brooklyn 4=Queens 5=Richmond
 Building Type A ≥6 stories B <6 stories C single family D school E hospital F public owned
 Result Code 1 = Violation Issued 2=No Violation Issued 3=No access 4=Project not started (no NOV)
 5=Public Owned Property