

Asbestos Inspection Report

Premise No. 130 Liberty Street					Inspection Date: 07/15/08	
Floor Various	Zip 10006	Borough 1	Block 54	Lot 1	Squad # 1	Badge # AO61
Inspector H. Guirguis		Building Type A		Basis of Inspection TRU0238MN06		Photos Taken Yes
Contractor's Name LVI Environmental				Sample Number -----		
Address City				Sample Number -----		
State Zip Phone				Sample Number -----		
Laboratory Name TRC Environmental Corp				Owner's Name The Lower Manhattan Development Corp.		
Address City 1430 Broadway New York				Address City One Liberty Plaza New York		
State Zip Phone NY 10018				State Zip Phone NY 10006 (212) 962-2300		
Contact Person Arnel Javal, Sr. Proj. Mgr./TRC Environmental				Time of Inspection from: 8:25 am – 09:00 am		
<p>On arrival, I met Arnel Javal, The Senior Project Manager of TRC Environmental at TRC field office, who informed me that a total of 1 Handler Supervisor and 24 Asbestos Handlers were on the 14th floor today for the first shift. The daily work schedule informed me of the following:</p> <ol style="list-style-type: none"> 1. 16th, 17th floors: Setting up for cleaning floor. 2. 14th & 15th floors: Demo, Wrapping debris 3. 13th & 12th floors: Setting up floors 4. 10th floor: Setting up Micro trap tents, Wrapping cable 5. 20th floor: Poly over Stairwell B 6. Various floors Loading out boxes to ATC trailer <p>I went to the decontamination enclosure system on the 14th floor, after signing the log book donned personal protection and accessed the work areas.</p> <ol style="list-style-type: none"> 1. The workers were found in the process of wrapping debris; there was still a lot of wet debris on the floor 2. Demolition was completed in all areas 3. Inspection was done on the Micro trap Machines and the Micro trap tents and on all the work area. 4. The Negative Pressure was 0.043 <p>I exited the work area after decontaminating myself and signing the log book.</p>						
NOV #	Infraction	Infraction	Infraction	Infraction		
NOV #	Infraction	Infraction	Infraction	Result Code 2		
NOV #	Infraction	Infraction	Infraction	Supervisor's Initial <i>RM</i> 7/108		

Borough 1=Manhattan 2=Bronx 3=Brooklyn 4=Queens 5=Richmond
 Building Type A ≥6 stories B <6 stories C single family D school E hospital F public owned
 Result Code 1 = Violation Issued 2=No Violation Issued 3=No access 4=Project not started (no NOV)
 5=Public Owned Property