

DEP

**CITY OF NEW YORK
DEPARTMENT OF ENVIRONMENTAL PROTECTION
BUREAU OF ENVIRONMENTAL COMPLIANCE**

ELAP #11045
Commissioner Emily Lloyd

**DETA ASBESTOS LABORATORY
96-05 HORACE HARDING EXPRESSWAY
CORONA, NEW YORK 11368
(718) 595-6309 FAX # (718) 595-6307**

TEST METHODS: 1. Friable Material EPA 600/M4/82/020

2. Non Friable Material Item No. 198.6 (NOB by PLM)

Incident #:	1715280	Date Collected:	08/26/07
Inspector :	R. RAMMOHAN	Received:	08/26/07
Premise :	130 LIBERTY STREET	Analyzed:	08/27/07
Boro :	Manhattan		
Analyst :	G. FRUCHTMAN		

Client #:

DEP Sample #: 70826/A078007

Laboratory #: 70826/144

Location Sampled: 14 FL "A" STAIR

Color: BEIGE


Homogenous: Yes

Asbestos Present: No

Results (%)

Cellulose	20
Vermiculite	10
Matrix	70

Comments:

Reviewed by: 
Laboratory Director

Polarized Light Microscopy is not consistently reliable in detecting asbestos in flooring and similar non-friable organically bound materials. Quantitative transmission electron microscopy is the only method that can be used to determine if this material can be considered or treated as non-asbestos containing.

This report may not be reproduced except with the written approval of this laboratory. The test report relates only to the item(s) listed and does not represent a product endorsement by ELAP or any U.S. Government Agency.