

Asbestos Inspection Report

Premise No. 130 Liberty Street					Inspection Date: 06/11/09	
Floor Various	Zip 10006	Borough 1	Block 54	Lot 1	Squad # 1	Badge # A062
Inspector M.Gagnidze		Building Type F		Basis of Inspection TRU2068MN08		Photos Taken yes
Contractor's Name LVI Environmental				Sample Number -----		
Address 462 Getty Avenue		City Clifton		Sample Number -----		
State NJ	Zip 07011	Phone 973-772-3660		Sample Number -----		
Third Party Air Monitor TRC Environmental Corp				Owner's Name The Lower Manhattan Development Corp.		
Address 1340 Broadway		City New York		Address One Liberty Plaza		City New York
State NY	Zip 10018	Phone 212-221-7822		State NY	Zip 10006	Phone (212) 962-2300
Contact Person Arnel Javal, Sr. Proj. Mgr/TRC Environmental				Time of Inspection from: 6:30 pm to 7:25 pm		
<p>I arrived at the premise at 6:30 pm. LVI schedule informed that activities include: clear floor, scrape fireproofing, demo, load out on 1st floor.</p> <p>I proceeded to the decon, signed the log book, don the appropriate level of personal protective equipment to enter the regulated area on 1st floor.</p> <p>Three workers were present for the decon maintenance, cleaning shower chamber and organizing the clean room.</p> <p>Negative air pressure on the floor was -0.042.</p> <p>1st Floor – 50 Asbestos Handlers were inside the work area, scraping fireproofing at the west side extended area and the north/west side of the area #5; cutting metal panels using power tools with HEPA vacuum attached; workers on scissor lift were cutting air duct, spraying with amended water. On mezzanine and at the west side of the vestibule workers on scissor lift were cutting metal fixtures from the columns and beams.</p> <p>Others were picking up debris, placing into the boxes using metal shovels, spraying the area with amended water, cleaning the floor from debris, preparing and loading out boxes through the waste decon. 30 Gaylord boxes were on the floor ready for load out. 40 micro trap machines were on and 5 on stand by. Inspection was done on micro trap tents.</p> <p>After following the decontamination procedure I exited the work area.</p> <p>Inspection was done on ATC trailer.</p>						
NOV #	Infraction	Infraction	Infraction	Infraction	Infraction	
NOV #	Infraction	Infraction	Infraction	Infraction	Result Code 2	
NOV #	Infraction	Infraction	Infraction	Infraction	Supervisor's Initial <i>MS</i>	

Borough 1=Manhattan 2=Bronx 3=Brooklyn 4=Queens 5=Richmond
 Building Type A ≥6 stories B <6 stories C single family D school E hospital F public owned
 Result Code 1 = Violation Issued 2=No Violation Issued 3=No access 4=Project not started (no NOV)
 5=Public Owned Property