

Asbestos Inspection Report

Premise No. 130 Liberty Street					Inspection Date: 05/11/09	
Floor 1 st Fl	Zip 10006	Borough 1	Block 54	Lot 1	Squad # 1	Badge # A062
Inspector M. Gagnidze		Building Type F		Basis of Inspection TRU2068MN08		Photos Taken yes
Contractor's Name LVI Environmental Services Inc.				Sample Number _____		
Address 462 Gerry Ave				City Clifton		
State NJ				Zip 07011		
Phone (973) 772-3660				Sample Number _____		
Third Party Air Monitor TRC Environmental Corp				Owner's Name The Lower Manhattan Development Corp.		
Address 1340 Broadway				City New York		
State NY				Zip 10018		
Phone (212) 221-7822				State NY		
Zip 10006				Phone (212) 962-2300		
Contact Person Arnel Javal, Sr. Proj. Mgr/TRC Environmental				Time of Inspection from: 10:20 pm to 11:10 pm		
<p>I entered the premise at 10:20 pm. LVI schedule informed that activities include: Clear floor, demo & wrap metal, load out on 1st floor.</p> <p>I proceeded to the decon, signed the log book, don the appropriate level of personal protective equipment to enter the regulated area on 1st floor. Two workers were present for the decon maintenance organizing the clean room. Negative air pressure was -0.027.</p> <p>1st Floor – 30 workers were present inside the work area. A large amount of debris – cut conduits and beams mixed with metal fixtures - exists on the floor. Asbestos Handlers were cutting metal ducts into the pieces at the various locations, using equipment with HEPA vacuum attached.</p> <p>Two workers at the north/west side hallway were harnessed in scissor lift; one worker was cutting air duct and another Handler spraying amended water around the area.</p> <p>Workers at the south side area were wrapping beams with poly. Others were replacing filters of micro trap machines, preparing, wrapping and loading out sealed and sprayed boxes through the north side waste decon. 30 Gaylord boxes were ready for load out. 35 micro trap machines were powered on and 5 on stand by. Inspection was done on micro trap tents.</p> <p>After following the decontamination procedure I signed the log book and left the decon.</p> <p>Inspection was done on ATC trailer.</p>						
NOV #	Infraction	Infraction	Infraction	Infraction	Infraction	
NOV #	Infraction	Infraction	Infraction	Infraction	Result Code 2	
NOV #	Infraction	Infraction	Infraction	Infraction	Supervisor's Initial	<i>ryf</i>

Borough 1=Manhattan 2=Bronx 3=Brooklyn 4=Queens 5=Richmond
 Building Type A ≥6 stories B <6 stories C single family D school E hospital F public owned
 Result Code 1 = Violation Issued 2=No Violation Issued 3=No access 4=Project not started (no NOV)
 5=Public Owned Property