

Asbestos Inspection Report

Premise No. 130 Liberty Street					Inspection Date: 03/18/09	
Floor Various	Zip 10006	Borough 1	Block 54	Lot 1	Squad # 1	Badge # AO61
Inspector H. Guirguis		Building Type A		Basis of Inspection TRU2068MN08		Photos Taken Yes
Contractor's Name LVI Environmental				Sample Number _____		
Address City				Sample Number _____		
State Zip Phone				Sample Number _____		
Laboratory Name TRC Environmental Corp				Owner's Name The Lower Manhattan Development Corp.		
Address City 1430 Broadway New York				Address City One Liberty Plaza New York		
State Zip Phone NY 10018				State Zip Phone NY 10006 (212) 962-2300		
Contact Person Arnel Javal, Sr. Proj. Mgr./TRC Environmental				Time of Inspection from: 08:00am – 10:00am		
<p>On arrival I met Nugent Gerald, Supervisor for LVI Environmental at the LVI field office, who informed me that a total of 1 Handler Supervisor and 15 Asbestos Handlers were in the 11th floor today.</p> <p>The daily work schedule informed me of the following.</p> <ol style="list-style-type: none"> 1. 11th floor: 15 men- each- Exterior façade removal 2. 12th & 11th floor: 12 men- Eagle-installing decks for façade work 3. 3rd floor: 50 men-scrape fireproofing clear off floor 4. 2nd floor: 58 men-clear off floor, scrape fireproofing 5. 1st floor: 76men-clear floor, cut ducts, demo walls, ceilings, etc. 6. Various floors : 14 men loading out boxes to ATC trailer <p>I used the north hoist to the 11th floor.</p> <ol style="list-style-type: none"> 1. 11th floor: A handler supervisor and 15 workers were found in the process of Removing Aluminum column covers and fascia with non-friable ACM caulking material and glass from the east side south end area, Poly wrapped the aluminum pieces, boxing debris, fine spraying amended water on the Gaylord boxes and the work area, Inspection was done on the work area. I used the stair A to the 10th floor and inspection was done to the decon Area. 						
NOV #	Infraction	Infraction	Infraction	Infraction	Infraction	
NOV #	Infraction	Infraction	Infraction	Infraction	Result Code 2	
NOV #	Infraction	Infraction	Infraction	Infraction	Supervisor's Initial	

Borough 1=Manhattan 2=Bronx 3=Brooklyn 4=Queens 5=Richmond
 Building Type A ≥6 stories B <6 stories C single family D school E hospital F public owned
 Result Code 1 = Violation Issued 2=No Violation Issued 3=No access 4=Project not started (no NOV)
 5=Public Owned Property