

Asbestos Inspection Report

Premise No. 130 Liberty Street					Inspection Date: 04/27/09	
Floor Various	Zip 10006	Borough 1	Block 54	Lot 1	Squad # 1	Badge # A062
Inspector M.Gagnidze		Building Type F		Basis of Inspection TRU2068MN08		Photos Taken yes
Contractor's Name LVI Environmental				Sample Number _____		
Address _____ City _____				Sample Number _____		
State _____ Zip _____ Phone _____				Sample Number _____		
Laboratory Name TRC Environmental Corp				Owner's Name The Lower Manhattan Development Corp.		
Address _____ City _____ 1340 Broadway New York				Address _____ City _____ One Liberty Plaza New York		
State _____ Zip _____ Phone _____ NY 10018				State _____ Zip _____ Phone _____ NY 10006 (212) 962-2300		
Contact Person Arnel Javal, Sr. Proj. Mgr/TRC Environmental				Time of Inspection from: 8:50 am to 9:45 am		
<p>I entered the premise at 8:50 am. LVI schedule informed that activities include: Clear floor, cut ducts, demo walls, ceilings on 1st floor.</p> <p>I proceeded to the decon, signed the log book, don the appropriate level of personal protective equipment to enter the regulated area on 1st floor. Two workers were present for the decon maintenance, cleaning shower chambers and organizing the clean room. Negative air pressure was -0.025.</p> <p>1st Floor – 75 workers were present inside the work area.</p> <p>Workers on mezzanine of the north/east side work area were demolishing the drop Ceilings and spraying with amended water. Workers harnessed in scissor lifts were demolishing the brick wall. Two workers on the north side of the work area were cutting and removing air duct, using power tool with HEPA vacuum attached.</p> <p>On mezzanines at the various locations workers were demolishing the brick wall and spraying with amended water, breaking down hard drop ceiling, placing debris into the boxes.</p> <p>Other workers were: cutting metal into small pieces at the various locations using power tools with HEPA vacuum attached, placing into the boxes and spraying; wrapping beams with poly, loading out sealed and sprayed boxes through the north side waste decon.</p> <p>40 Gaylord boxes were ready for load out. 35 micro trap machines were powered on and 5 on stand by. Inspection was done on micro trap tents.</p> <p>After following the decontamination procedure I signed the log book and left the decon. Inspection was done on ATC trailer.</p>						
NOV #	Infraction	Infraction	Infraction	Infraction	Infraction	
NOV #	Infraction	Infraction	Infraction	Infraction	Result Code 2	
NOV #	Infraction	Infraction	Infraction	Infraction	Supervisor's Initial <i>nyf</i>	

Borough 1=Manhattan 2=Bronx 3=Brooklyn 4=Queens 5=Richmond
 Building Type A ≥6 stories B <6 stories C single family D school E hospital F public owned
 Result Code 1 = Violation Issued 2=No Violation Issued 3=No access 4=Project not started (no NOV)
 5=Public Owned Property