

Asbestos Inspection Report

Premise No. 130 Liberty Street					Inspection Date: 03/30/09	
Floor Various	Zip 10006	Borough 1	Block 54	Lot 1	Squad # 1	Badge # A062
Inspector M.Gagnidze		Building Type F		Basis of Inspection TRU2068MN08		Photos Taken yes
Contractor's Name LVI Environmental				Sample Number -----		
Address City				Sample Number -----		
State Zip Phone				Sample Number -----		
Laboratory Name TRC Environmental Corp				Owner's Name The Lower Manhattan Development Corp.		
Address 1340 Broadway City New York				Address One Liberty Plaza City New York		
State Zip Phone NY 10018				State Zip Phone NY 10006 (212) 962-2300		
Contact Person Arnel Javal, Sr. Proj. Mgr/TRC Environmental				Time of Inspection from: 10:30 pm to 11:25 pm		

I entered the premise at 10:30 pm. LVI schedule informed that activities include: demo walls, ceilings, ducts on 1st floor.

I proceeded to the decon, signed the log book, don the appropriate level of personal protective equipment to enter the regulated area on 1st floor. Four workers were present for the decon maintenance, cleaning shower chambers and organizing the clean room. Negative air pressure was -0.038.

1st Floor – 75 workers were observed inside the work area, working on mezzanines at the various locations: clearing off the floor from debris, spraying with amended water, placing debris into the boxes; cutting and removing hard drop ceiling; cutting conduit; HEPA vacuum has been attached during cutting.

Workers at three locations harnessed in scissor lifts were breaking down the hard drop ceiling, cutting metal fixtures, spraying with amended water.
Four workers were plasticizing frames around the machines inside of mechanical room.

Other workers were: cutting metal into small pieces at the various locations, placing into the boxes and spraying; wrapping beams with poly, loading out sealed and sprayed boxes through the north side waste decon.
A large amount of debris and poly wrapped beams still exists on the floor.

40 Gaylord boxes were to be taken out. 35 micro trap machines were powered on and 5 on stand by. Inspection was done on micro trap tents.

After following the decontamination procedure I signed the log book and left the decon.

Inspection was done on ATC trailer.

NOV #	Infraction	Infraction	Infraction	Infraction
NOV #	Infraction	Infraction	Infraction	Result Code 2
NOV #	Infraction	Infraction	Infraction	Supervisor's Initial <i>ryk</i>

Borough 1=Manhattan 2=Bronx 3=Brooklyn 4=Queens 5=Richmond
 Building Type A ≥6 stories B <6 stories C single family D school E hospital F public owned
 Result Code 1 = Violation Issued 2=No Violation Issued 3=No access 4=Project not started (no NOV)
 5=Public Owned Property