

Asbestos Inspection Report

Premises: 130 Liberty Street					Inspection Date: 02/12/09	
Floor Various	Zip 10006	Borough 1	Block 54	Lot 1	Squad # 1	Badge # A011
Inspector N. Patel		Building Type A		Basis of Inspection TRU2068MN08		Photos Taken No
Contractor's Name LVI Environmental				Sample Number -----		
Address 462 Getty Avenue				City Clifton		
State NJ				Zip 07011		
Phone (973) 772-3660				Sample Number -----		
Laboratory Name TRC Environmental corp.				Owner's Name The Lower Manhattan Development Corp.		
Address 1430 Broadway				City New York		
State NY				Zip 10018		
Phone (212) 962-2300				Sample Number -----		
Contact Person Arnel Javal, Sr. Proj. Mgr. / TRC Environmental				Time of Inspection from: 1:20 pm – 2:20 pm (1 st , 2 nd , 3 rd & 4 th floor)		
<p>I arrived at 8:00 am at 130 Liberty Street for 5th floor visual inspection. Because of high wind, DOB canceled working above 75' height.</p> <p>On the 1st floor, I enters from the remote decontamination system, suits up, dons respirator, enters to the containment and met Mr. Jorge Sandoval, foreman. There were 20 people working on the floor. They were demolishing partition walls, spraying amended water on the debris, boxing debris, preparing Gaylord boxes, replacing Air filters, cutting metals into pieces with HEPA vacuum attached to the power tool and in the decontamination system. Seven (7) Gaylord boxes piled on the floor ready to be load out. Negative Air pressure was -0.030. I found no water to clean rubber shoes near stair B. I told foreman to put that and he did it. I used stair B to go to 2nd floor.</p> <p>On the 2nd floor, I met Mr. Jose Jimenez, supervisor. There were 32 people working on the floor. They were erecting platform in the east side, demolishing ducts and walls, spraying amended water on the debris, boxing debris, preparing Gaylord boxes and cutting metals into pieces with HEPA vacuum attached to the power tool. Six (6) Gaylord boxes and number of poly wrapped beams were on the floor ready to be load out. I used stair B to go to 3rd floor.</p> <p>On the 3rd floor, I met Mr. Geraldo, supervisor. There were 27 people working on the floor. They were demolishing partition walls and cutting ducts with HEPA vacuum attached to the power tool, Eagle putting platform across shaft area, preparing Gaylord boxes, spraying amended water on the debris and boxing it and cutting metals into pieces with HEPA vacuum attached. Seventeen (17) Gaylord boxes and numerous poly wrapped beams piled on the floor ready to be load out. I used stair B to go to 4th floor.</p> <p>On the 4th floor, Nobody was working on the floor. An inspection was done on the micro trap machines and micro trap tents – Air pumps were on. Five (5) Gaylord boxes were on the floor ready to be load out. I used stair B to back to 1st floor remote decontamination area, decontaminated myself, signed the log book and exited out. My observation was discussed with LVI and ATC personal.</p>						
NOV#						RESULT 2
NOV#						
NOV#						SUPERVISOR

Borough 1=Manhattan 2=Bronx 3=Brooklyn 4=Queens 5=Richmond
 Building Type A ≥6 stories B <6 stories C single family D school E hospital F public owned
 Result: Code 1 = Violation Issued 2=No Violation Issued 3=No access 4=Project not started (no NOV) 5=Public Owned Property