



THE CITY OF NEW YORK DEPARTMENT OF ENVIRONMENTAL PROTECTION
JOEL A. MIELE, SR., P.E. Commissioner

ROBERT C. AVALTRONI
Deputy Commissioner

PHONE (718) 595-4418
FAX (718) 595-4422

ASBESTOS ANALYTICAL REPORT

ASBESTOS CONTROL PROGRAM LABORATORY
96-05 HORACE HARDING EXPRESSWAY
CORONA, NEW YORK 11368
(718) 595-6309 FAX# (718) 595-6307

Bureau of
Air, Noise, & Hazardous
Materials

ELAP # 11045

TEST METHODS: 1) 40 CFR Part 763, Subpart F, App. A
2) Polarized Light Microscopy plus Stratified Point-Counting Method
3) EPA/600/R-93/116

Incident #: SVC#185065
Inspector : R. RAMMOHAN
Premise : 80 MAIDEN LANE
Boro : Manhattan
Analyst : L. WYATT

Date Collected: 07/10/00
Received: 07/10/00
Analyzed: 07/10/00

Client #:

DEP Sample #:	00710/A078007	00710/A078008	00710/A078009
Laboratory #:	00710/464	00710/465	00710/466
Location Sampled:	BSMT STORAGE RM	BSMT STORAGE RM	BSMT STORAGE RM
Color:	WHITE	WHITE	WHITE
Homogenous:	Yes	Yes	Yes
Asbestos Present:	Yes	Yes	Yes

Results (%)

Chrysotile	22	Chrysotile	18	Chrysotile	22
Matrix	78	Matrix	82	Matrix	78

Comments:

Reviewed by:

[Signature]
Laboratory Director

This test report may not be reproduced except with the written approval of this laboratory. The test report relates only to the item(s) listed and does not represent a product endorsement by NVLAP or any other U.S. Government agency.

59-17 Junction Boulevard, 11th Floor, Corona, New York 11368-5107



CITY_DEP_WORBY_CANNATA_SUBP_000131468