

CITY OF NEW YORK
DEPARTMENT OF ENVIRONMENTAL PROTECTION
ASBESTOS CONTROL PROGRAM
59-17 JUNCTION BOULEVARD
CORONA, NY 11368

CHRISTOPHER WARD, P.E.
COMMISSIONER

ASBESTOS CONTROL PROGRAM
BULK ANALYSIS CHAIN OF CUSTODY

Incident No.: 873950

Date Sampled: 7/20/04

Premise: 90 West Street

Time: 2:30 am/pm

Boro: MANHATTAN

Inspector: R. RAMMOHAN
Print

Admoley
Sign

TURNAROUND TIME: 24HRS [] 48HRS [] 1 WK [] 2 WKS [] 4 WKS []

SAMPLE NUMBER	DESCRIPTION	LOCATION SAMPLED	LAB ID
1. 40720/A078001	Cementitious	23 rd North	
2. 40720/A078002	Cementitious	23 rd North	
3. 40720/A078003	Mixed dirt	Roof N.E	
4. 40720/A078004	Fibrous Spray on	West MCH. space below roof	
5. 40720/A078005	Cementitious	21 st North	
6. 40720/A078006	Cementitious	21 st	
7. 40720/A078007	Mixed dirt	21 st South Ledge	
8. 40720/A078008	Roofing	21 st North Ledge	
9. 40720/A078009	Cementitious	17 th North	
10. 40720/A078010	Fibrous Insulation	20 th N.E. St	
11. 40720/A078011	Cementitious	17 th North East.	

ANALYSES REQUESTED: Asbestos FLM [☒]

Asbestos TEM []

DATE	TIME	ACCEPTED BY	COMMENTS
		PRINT	
		SIGN	
		P	
		S	
		P	
		S	
		P	
		S	