



ambient group inc.

Indoor environmental quality surveys
Water treatment consulting
Asbestos & lead field services
Regulatory compliance programs
Air, water & soil analytical laboratories

NATIONAL HEADQUARTERS

55 WEST 39TH STREET
12TH FLOOR
NEW YORK, NEW YORK 10018
TEL: (212) 944-4615
FAX: (212) 944-4618
WEB: WWW.AMBIENTGROUP.COM

December 19, 2001

Mr. Mike Martin
Jack Resnick & Sons
75 Park Place
New York, New York 10022

RECEIVED

DEC 20 2001

JACK RESNICK & SONS

**Re: 75 Park Place – 8th Floor
Ambient Project # 211658**

Dear Mr. Martin:

In accordance with our Clearance Air and Surface Monitoring and Analysis, the 8th floor at 75 Park Place has been tested and completed. Ambient Group, Inc. collected the following: (1) air samples analyzed by transmission electron microscopy (TEM) on December 10, 2001; (2) surface metals samples on December 10, 2001; and (3) airborne metal samples on December 11, 2001.

Results of all clearance air and surface monitoring samples indicated levels below applicable OSHA PELs and regulated guidelines or other criteria. Based on the above analytical results, the subject area is cleared for re-occupancy.

Should you have any questions regarding this information, please feel free to call me.

Sincerely,
Signed for Ambient Group, Inc. by:


John Leitner,
Vice President

Cc: Ed Hartz
LappYen

GLEN COVE, NY
516 609-0009

MIAMI, FL
305 860-0101

CHICAGO, IL
312 527-5526

CORONA, CA
909 272-4730

CITY_21MC100_002777820