



KAM CONSULTANTS
 35-40 36th Street
 Long Island City
 New York, 11106
 Tel: (718) 729-1997
 Fax: (718) 729-1876

BULK SAMPLE ANALYSIS REPORT

CLIENT: NYC-DCAS

BUILDING ADDRESS: 1 Centre Street, Manhattan, NY

PROJECT#:

Client Sample ID# :	1	2	3	4	5
Lab Sample ID# :	010920A-1243	010920A-1244	010920A-1245	010920A-1246	010920A-1247
Sample Location:	DIC Office 20th Floor South	Room # 2002 20th Floor	Room # 2015 South East 20th Floor	Men's Bathroom 20th Floor	Conference Room 20th Floor Room B
Homogeneity:	Window Yes	Yes	Yes	Yes	Yes
Sample Description:	A/C Vent Wipe	A/C Vent Wipe	A/C Vent Wipe	Window Sill Wipe	Desk Wipe
Color:	Blk	Blk	Blk	Blk	Blk
Texture:	Mixed	Mixed	Mixed	Mixed	Mixed
Sample Treatment:	None	None	None	None	None
Asbestos Present: (Type & Percent)	ND	ND	ND	ND	ND
Total Percent Asbestos:	0%	0%	0%	0%	0%
Other Fibr. Mat. (Type & Percent):	3%CELL <1%FBGL	3%SYNTH	2%SYNTH <1%FBGL	1%CELL <1%FBGL	4%CELL 5%SYNTH
Non Fibr. Mat. (Percent):	96%	97%	97%	98%	91%
Date Received:	9/20/01				
Date of Analysis:	9/20/01				
Date of Report:	9/20/01				

Analyst:

Roody Louis

Lab Manager:

David Chen

- * Analysis of samples is performed by Polarized Light Microscopy (PLM) - Point Counting Method (EPA 600/M4-82-020)
- * Analytical equipments: Stereobinocular microscope (MEIJI EMT-Serial # 25930), Polarized Light Microscope (MEIJI ML-POL-Serial # 88034)
- * PLM is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials. Quantitative transmission electron microscopy is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos-containing
- * Samples will be stored for ninety (90) days and then returned to the client upon request
- * The results relate only to the items calibrated or tested.
- * The certificate of report shall not be reproduced without the written approval of the laboratory.
- * The report must not be used by the client to claim endorsement by NVLAP or any agency of the US Government.

NYS-DOH ELAP # 11273

NIST-NVLAP # 102047

AIHA #: 100269



KAM CONSULTANTS
 35-40 36th Street
 Long Island City
 New York, 11106
 Tel: (718) 729-1997
 Fax: (718) 729-1876

BULK SAMPLE ANALYSIS REPORT

CLIENT: NYC-DCAS

BUILDING ADDRESS: 1 Centre Street, Manhattan, NY

PROJECT#:

Client Sample ID# :	6	7	8	9	10
Lab Sample ID# :	010920A-1248	010920A-1249	010920A-1250	010920A-1251	010920A-1252
Sample Location:	Mechanical Dust Vent By Room B 20th Floor	Room 2052 20th Floor A/C Vent	Room #2057 20th Floor North A/C Vent	Room # 2057 20th Floor North	Field Blank Window
Homogeneity:	Yes	Yes	Yes	Yes	Yes
Sample Description:	Mech. Duct Vent Wipe	A/C Vent Wipe	A/C Vent Wipe	Desk Wipe	Wipe
Color:	Blk	Blk	Blk	Blk	Blk
Texture:	Mixed	Mixed	Mixed	Mixed	Mixed
Sample Treatment:	None	None	None	None	None
Asbestos Present: (Type & Percent)	ND	ND	ND	ND	ND
Total Percent Asbestos:	0%	0%	0%	0%	0%
Other Fibr. Mat. (Type & Percent):	3%SYNTH	8%SYNTH	3%SYNTH 5%CELL	5%CELL 5%SYNTH	0%
Non Fibr. Mat. (Percent):	97%	92%	92%	90%	100%
Date Received:	9/20/01				
Date of Analysis:	9/20/01				
Date of Report:	9/20/01				

Analyst:

R. Louis
 Roddy Louis

Lab Manager:

David Chen
 David Chen

- * Analysis of samples is performed by Polarized Light Microscopy (PLM) - Point Counting Method (EPA 600/M4-82-020)
- * Analytical equipments: Stereobinocular microscope (MEIJI EMT-Serial # 25930), Polarized Light Microscope (MEIJI ML-POL-Serial # 88034)
- * PLM is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials. Quantitative transmission electron microscopy is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos-containing
- * Samples will be stored for ninety (90) days and then returned to the client upon request
- * The results relate only to the items calibrated or tested.
- * The certificate of report shall not be reproduced without the written approval of the laboratory.
- * The report must not be used by the client to claim endorsement by NVLAP or any agency of the US Government.

NYS-DOH ELAP # 11273

NIST-NVLAP # 102047

AIHA #: 100269



KAM CONSULTANTS
 35-40 36th Street
 Long Island City
 New York, 11106
 Tel: (718) 729-1997
 Fax: (718) 729-1876

BULK SAMPLE ANALYSIS REPORT

CLIENT: NYC-DCAS

BUILDING ADDRESS: 1 Centre Street, Manhattan, New York

PROJECT#:

Client Sample ID# :	1	2	3	4	5
Lab Sample ID# :	010929A-7	010929A-8	010929A-9	010929A-10	010929A-11
Sample Location:	Room 2517 25th Floor West	Room 2517 25th Floor West	Room 2517 25th Floor West	Room 2517 25th Floor West	28th Floor South
Homogeneity:	Yes	Yes	Yes	Yes	Yes
Sample Description:	Window Sill Wipe	Furniture Wipe	Window A/C Wipe	Furniture Wipe	Window Sill Wipe
Color:	Blk	Blk	Blk	Blk	Blk
Texture:	Mixed	Mixed	Mixed	Mixed	Mixed
Sample Treatment:	None	None	None	None	None
Asbestos Present: (Type & Percent)	ND	ND	ND	ND	ND
Total Percent Asbestos:	0%	0%	0%	0%	0%
Other Fibr. Mat. (Type & Percent):	15%SYNTH	8%SYNTH	20%SYNTH 2%CELL	5%SYNTH 3%CELL	10%SYNTH
Non Fibr. Mat. (Percent):	85%	92%	78%	92%	90%
Date Received:	9/29/01				
Date of Analysis:	10/1/01				
Date of Report:	10/1/01				

Analyst:

Roody Louis

Lab Manager:

David Chen

- * Analysis of samples is performed by Polarized Light Microscopy (PLM) - Point Counting Method (EPA 600/M4-82-020)
- * Analytical equipments: Stereobinocular microscope (MEIJI EMT-Serial # 25930), Polarized Light Microscope (MEIJI ML-POL-Serial # 88034)
- * PLM is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials. Quantitative transmission electron microscopy is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos-containing
- * Samples will be stored for ninety (90) days and then returned to the client upon request
- * The results relate only to the items calibrated or tested.
- * The certificate of report shall not be reproduced without the written approval of the laboratory.
- * The report must not be used by the client to claim endorsement by NVLAP or any agency of the US Government.

NYS-DOH ELAP # 11273

NIST-NVLAP # 102047

AIHA #: 100269



KAM CONSULTANTS
 35-40 36th Street
 Long Island City
 New York, 11106
 Tel: (718) 729-1997
 Fax: (718) 729-1876

BULK SAMPLE ANALYSIS REPORT

CLIENT: NYC-DCAS

BUILDING ADDRESS: 1 Centre Street, Manhattan, New York

PROJECT#:

Client Sample ID# :	6	7	8	9	10
Lab Sample ID# :	010929A-12	010929A-13	010929A-14	010929A-15	010929A-16
Sample Location:	28th Floor South	28th Floor South	28th Floor West	28th Floor West	28th Floor West
Homogeneity:	Yes	Yes	Yes	Yes	Yes
Sample Description:	Window Sill Wipe	Furniture Wipe	Window Sill Wipe	Window Sill Wipe	Furniture Wipe
Color:	Blk	Blk	Blk	Blk	Blk
Texture:	Mixed	Mixed	Mixed	Mixed	Mixed
Sample Treatment:	None	None	None	None	None
Asbestos Present: (Type & Percent)	ND	ND	ND	ND	ND
Total Percent Asbestos:	0%	0%	0%	0%	0%
Other Fibr. Mat. (Type & Percent):	15%SYNTH 5%CELL	5%SYNTH <1%FBGL	15%SYNTH 2%CELL <1%FBGL	10%SYNTH	8%SYNTH 1%CELL <1%FBGL
Non Fibr. Mat. (Percent):	80%	94%	82%	90%	90%
Date Received:	9/29/01				
Date of Analysis:	10/1/01				
Date of Report:	10/1/01				

Analyst:

Roody Louis
 Roody Louis

Lab Manager:

David Chen
 David Chen

- * Analysis of samples is performed by Polarized Light Microscopy (PLM) - Point Counting Method (EPA 600/M4-82-020)
- * Analytical equipments: Stereobinocular microscope (MEIJI EMT-Serial # 25930), Polarized Light Microscope (MEIJI ML-POL-Serial # 88034)
- * PLM is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials. Quantitative transmission electron microscopy is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos-containing
- * Samples will be stored for ninety (90) days and then returned to the client upon request
- * The results relate only to the items calibrated or tested.
- * The certificate of report shall not be reproduced without the written approval of the laboratory.
- * The report must not be used by the client to claim endorsement by NVLAP or any agency of the US Government.

NYS-DOH ELAP # 11273

NIST-NVLAP # 102047

AIHA #: 100269



KAM CONSULTANTS
 35-40 36th Street
 Long Island City
 New York, 11106
 Tel: (718) 729-1997
 Fax: (718) 729-1876

BULK SAMPLE ANALYSIS REPORT

CLIENT: NYC-DCAS

BUILDING ADDRESS: 1 Centre Street, Manhattan, New York

PROJECT#:

Client Sample ID# : 11	12	13	14	15
Lab Sample ID# : 010929A-17	010929A-18	010929A-19	010929A-20	010929A-21
Sample Location: 28th Floor North	28th Floor North	28th Floor North	29th Floor South	29th Floor South
Homogeneity: Yes	Yes	Yes	Yes	Yes
Sample Description: Window Sill Wipe	Window Sill Wipe	Furniture Wipe	Window Sill Wipe	Window Sill Wipe
Color: Blk	Blk	Blk	Blk	Blk
Texture: Mixed	Mixed	Mixed	Mixed	Mixed
Sample Treatment: None	None	None	None	None
Asbestos Present: (Type & Percent) ND	ND	ND	ND	ND
Total Percent Asbestos: 0%	0%	0%	0%	0%
Other Fibr. Mat. (Type & Percent): 10%SYNTH 1%CELL	5%SYNTH	10%SYNTH 2%CELL 1%FBGL	10%SYNTH 8%CELL	7%SYNTH
Non Fibr. Mat. (Percent): <1%FBGL 88%	95%	87%	82%	93%
Date Received: 9/29/01				
Date of Analysis: 10/1/01				
Date of Report: 10/1/01				

Analyst:

Roody Louis

Lab Manager:

David Chen

- * Analysis of samples is performed by Polarized Light Microscopy (PLM) - Point Counting Method (EPA 600/M4-82-020)
- * Analytical equipments: Stereobinocular microscope (MEIJI EMT-Serial # 25930), Polarized Light Microscope (MEIJI ML-POL-Serial # 88034)
- * PLM is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials. Quantitative transmission electron microscopy is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos-containing
- * Samples will be stored for ninety (90) days and then returned to the client upon request
- * The results relate only to the items calibrated or tested.
- * The certificate of report shall not be reproduced without the written approval of the laboratory.
- * The report must not be used by the client to claim endorsement by NVLAP or any agency of the US Government.

NYS-DOH ELAP # 11273

NIST-NVLAP # 102047

AIHA #: 100269



KAM CONSULTANTS
35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

BULK SAMPLE ANALYSIS REPORT

CLIENT: NYC-DCAS

BUILDING ADDRESS: 1 Centre Street, Manhattan, New York

PROJECT#:

Client Sample ID# : 16	17	18	19	20
Lab Sample ID# : 010929A-22	010929A-23	010929A-24	010929A-25	010929A-26
Sample Location: 29th Floor South	29th Floor West	29th Floor West	29th Floor West	29th Floor North
Homogeneity: Yes	Yes	Yes	Yes	Yes
Sample Description: Furniture Wipe	Window Sill Wipe	Window Sill Wipe	Furniture Wipe	Window Sill Wipe
Color: Blk	Blk	Blk	Blk	Blk
Texture: Mixed	Mixed	Mixed	Mixed	Mixed
Sample Treatment: None	None	None	None	None
Asbestos Present: (Type & Percent) ND	ND	ND	ND	ND
Total Percent Asbestos: 0%	0%	0%	0%	0%
Other Fibr. Mat. (Type & Percent): 10%SYNTH 1%CELL	5%CELL	5%CELL <1%SYNTH	15%SYNTH 5%CELL	10%SYNTH
Non Fibr. Mat. (Percent): 89%	95%	94%	80%	90%
Date Received: 9/29/01				
Date of Analysis: 10/1/01				
Date of Report: 10/1/01				

Analyst:

Roody Louis

Lab Manager:

David Chen

- * Analysis of samples is performed by Polarized Light Microscopy (PLM) - Point Counting Method (EPA 600/M4-82-020)
- * Analytical equipments: Stereobinocular microscope (MEIJI EMT-Serial # 25930), Polarized Light Microscope (MEIJI ML-POL-Serial # 88034)
- * PLM is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials. Quantitative transmission electron microscopy is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos-containing
- * Samples will be stored for ninety (90) days and then returned to the client upon request
- * The results relate only to the items calibrated or tested.
- * The certificate of report shall not be reproduced without the written approval of the laboratory.
- * The report must not be used by the client to claim endorsement by NVLAP or any agency of the US Government.

NYS-DOH ELAP # 11273

NIST-NVLAP # 102047

AIHA #: 100269



KAM CONSULTANTS
 35-40 36th Street
 Long Island City
 New York, 11106
 Tel: (718) 729-1997
 Fax: (718) 729-1876

BULK SAMPLE ANALYSIS REPORT

CLIENT: NYC-DCAS

BUILDING ADDRESS: 1 Centre Street, Manhattan, New York

PROJECT#:

Client Sample ID# :	21	22
Lab Sample ID# :	010929A-27	010929A-28
Sample Location:	29th Floor North	29th Floor North

Homogeneity:	Yes	Yes
Sample Description:	Window Sill Wipe	Furniture Wipe

Color:	Blk	Blk
Texture:	Non Fibrous	Non Fibrous
Sample Treatment:	None	None

Asbestos Present: (Type & Percent)	ND	ND
---------------------------------------	----	----

Total Percent Asbestos:	0%	0%
------------------------------------	-----------	-----------

Other Fibr. Mat. (Type & Percent):	0%	0%
---------------------------------------	----	----

Non Fibr. Mat. (Percent):	100%	100%
------------------------------	------	------

Date Received: 9/29/01

Date of Analysis: 10/1/01

Date of Report: 10/1/01

Analyst:

Roody Louis

Lab Manager:

David Chen

- * Analysis of samples is performed by Polarized Light Microscopy (PLM) - Point Counting Method (EPA 600/M4-82-020)
- * Analytical equipments: Stereobinocular microscope (MEIJI EMT-Serial # 25930), Polarized Light Microscope (MEIJI ML-POL-Serial # 88034)
- * PLM is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials. Quantitative transmission electron microscopy is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos-containing
- * Samples will be stored for ninety (90) days and then returned to the client upon request
- * The results relate only to the items calibrated or tested.
- * The certificate of report shall not be reproduced without the written approval of the laboratory.
- * The report must not be used by the client to claim endorsement by NVLAP or any agency of the US Government.

NYS-DOH ELAP # 11273

NIST-NVLAP # 102047

AIHA #: 100269