



KAM CONSULTANTS
 35-40 36th Street
 Long Island City
 New York, 11106
 Tel: (718) 729-1997
 Fax: (718) 729-1876

BULK SAMPLE ANALYSIS REPORT

CLIENT: NYC-DCAS

BUILDING ADDRESS: OFFICE BLDG.- 2 Lafayette, Manhattan, NY

PROJECT#:

Client Sample ID# :	1	2	3	4	5
Lab Sample ID# :	010917A-808	010917A-809	010917A-810	010917A-811	010917A-812
Sample Location:	5th Floor Stair "Y"	5th Floor Stair "W"	5th Floor Lobby By Elevators	12th Floor Elevators Lobby	12th Floor Stair "Y"
Homogeneity:	Yes	Yes	Yes	Yes	Yes
Sample Description:	Floor Wipe	Floor Wipe	Floor Wipe	Floor Wipe	Floor Wipe
Color:	Blk	Blk	Blk	Blk	Blk
Texture:	Mixed	Mixed	Mixed	Mixed	Mixed
Sample Treatment:	None	None	None	None	None
Asbestos Present: (Type & Percent)	ND	ND	ND	ND	ND
Total Percent Asbestos:	0%	0%	0%	0%	0%
Other Fibr. Mat. (Type & Percent):	10%CELL	5%CELL	10%CELL 5%SYNTH	15%CELL	10%CELL
Non Fibr. Mat. (Percent):	90%	95%	85%	85%	90%
Date Received:	9/17/01				
Date of Analysis:	9/17/01				
Date of Report:	9/17/01				

Analyst:

George Kouvaras

Lab Manager:

David Chen

- * Analysis of samples is performed by Polarized Light Microscopy (PLM) - Point Counting Method (EPA 600/M4-82-020)
- * Analytical equipments: Stereobinocular microscope (MEIJI EMT-Serial # 25930). Polarized Light Microscope (MEIJI ML-POL-Serial # 88034)
- * PLM is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials. Quantitative transmission electron microscopy is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos-containing
- * Samples will be stored for ninety (90) days and then returned to the client upon request
- * The results relate only to the items calibrated or tested.
- * The certificate of report shall not be reproduced without the written approval of the laboratory.
- * The report must not be used by the client to claim endorsement by NVLAP or any agency of the US Government.

NYS-DOH ELAP # 11273

NIST-NVLAP # 102047

AIHA #: 100269



KAM CONSULTANTS
 35-40 36th Street
 Long Island City
 New York, 11106
 Tel: (718) 729-1997
 Fax: (718) 729-1876

BULK SAMPLE ANALYSIS REPORT

CLIENT: NYC-DCAS

BUILDING ADDRESS: OFFICE BLDG.- 2 Lafayette, Manhattan, NY

PROJECT#:

Client Sample ID# :	6	7	8	9	10
Lab Sample ID# :	010917A-813	010917A-814	010917A-815	010917A-816	010917A-817
Sample Location:	12th Floor Stair "W"	9th Floor Elevator Lobby	7th Floor Lobby By Elevator	7th Floor Stairway "Y"	7th Floor Stairs "W"
Homogeneity:	Yes	Yes	Yes	Yes	Yes
Sample Description:	Floor Wipe	Floor Wipe	Floor Wipe	Floor Wipe	Floor Wipe
Color:	Blk	Blk	Blk	Blk	Blk
Texture:	Mixed	Mixed	Mixed	Mixed	Mixed
Sample Treatment:	None	None	None	None	None
Asbestos Present: (Type & Percent)	ND	ND	ND	ND	ND
Total Percent Asbestos:	0%	0%	0%	0%	0%
Other Fibr. Mat. (Type & Percent):	5%CELL	5%CELL 5%SYNTH	5%CELL	5%CELL	8%CELL 5%SYNTH
Non Fibr. Mat. (Percent):	95%	90%	95%	95%	87%
Date Received:	9/17/01				
Date of Analysis:	9/17/01				
Date of Report:	9/17/01				

Analyst:

George Kouvaras

Lab Manager:

David Chen

- * Analysis of samples is performed by Polarized Light Microscopy (PLM) - Point Counting Method (EPA 600/M4-82-020)
- * Analytical equipments: Stereobinocular microscope (MEIJI EMT-Serial # 25930), Polarized Light Microscope (MEIJI ML-POL-Serial # 88034)
- * PLM is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials. Quantitative transmission electron microscopy is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos-containing
- * Samples will be stored for ninety (90) days and then returned to the client upon request
- * The results relate only to the items calibrated or tested.
- * The certificate of report shall not be reproduced without the written approval of the laboratory.
- * The report must not be used by the client to claim endorsement by NVLAP or any agency of the US Government.

NYS-DOH ELAP # 11273

NIST-NVLAP # 102047

AIHA #: 100269



KAM CONSULTANTS
 35-40 36th Street
 Long Island City
 New York, 11106
 Tel: (718) 729-1997
 Fax: (718) 729-1876

BULK SAMPLE ANALYSIS REPORT

CLIENT: NYC-DCAS

BUILDING ADDRESS: OFFICE BLDG.- 2 Lafayette, Manhattan, NY

PROJECT#:

Client Sample ID# :	11	12	13
Lab Sample ID# :	010917A-818	010917A-819	010917A-820
Sample Location:	3rd Floor Elevator Lobby	Ground Floor By Elevator #5	Ground Floor Stair "Y"
Homogeneity:	Yes	Yes	Yes
Sample Description:	Floor Wipe	Foot Step Wipe	Floor Wipe
Color:	Blk	Blk	Blk
Texture:	Mixed	Mixed	Mixed
Sample Treatment:	None	None	None
Asbestos Present: (Type & Percent)	ND	ND	ND
Total Percent Asbestos:	0%	0%	0%
Other Fibr. Mat. (Type & Percent):	10%CELL	10%CELL 5%SYNTH	10%CELL 5%SYNTH
Non Fibr. Mat. (Percent):	90%	85%	85%
Date Received:	9/17/01		
Date of Analysis:	9/17/01		
Date of Report:	9/17/01		

Analyst:

George Kouvaras

Lab Manager:

David Chen

- * Analysis of samples is performed by Polarized Light Microscopy (PLM) - Point Counting Method (EPA 600/M4-82-020)
- * Analytical equipments: Stereobinocular microscope (MEIJI EMT-Serial # 25930), Polarized Light Microscope (MEIJI ML-POL-Serial # 88034)
- * PLM is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials. Quantitative transmission electron microscopy is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos-containing
- * Samples will be stored for ninety (90) days and then returned to the client upon request
- * The results relate only to the items calibrated or tested.
- * The certificate of report shall not be reproduced without the written approval of the laboratory.
- * The report must not be used by the client to claim endorsement by NVLAP or any agency of the US Government.

NYS-DOH ELAP # 11273

NIST-NVLAP # 102047

AIHA #: 100269