



KAM CONSULTANTS
35-40 38th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

ASBESTOS

CHAIN OF CUSTODY FOR ~~LEAD~~ IN DUST (WIPE SAMPLING)

Client: **DCAS**
Project #: **OFFICE** LI #: **2 LAFAYETTE ST, MI-THRU, NY** Order #:
Building Address:
Date and Time of Collection: **09-16-01 Sun**
Samples Collected by: **26. BOWALL**
Method of Shipment:
Occupant's Name:
Contractor's Name:
Abatement Status:

Occupant's Address:
Contractor's Address:

PAGE 1/1

010917A

Sample #	Location	Surface Type	Area (LxW)	Laboratory Results (Lg Pb/Pb ²)	Remarks
1	5TH FLR STAIR Y	FLOOR			
2	5TH FLR STAIR W	W -			
3	5TH FLR LOBBY BY ELEVATORS	W -			
4	12TH FLR ELEVATORS LOBBY	W -			
5	12TH FLR STAIR Y	W -			
6	12TH FLR STAIR W	W -			
7	9TH FLR ELEVATOR LOBBY	W -			
8	7TH FLR LOBBY BY ELEVATOR	W -			
9	7TH FLR STAIRWAY Y	W -			
10	7TH FLR STAIRS W	W -			
11	3RD FLR ELEVATOR LOBBY	W -			
12	GROUND FLOOR BY ELEVATOR # 5	FOOT STEP			
13	GROUND FLOOR STAIR Y	FLOOR			

RECEIVED
KAM CONSULTANTS
2001 SEP 17 AM 12:22

Delivered by:
Date and Time Received:
Turnaround Time:

Received by:
Method of Analysis: EPA / SW 846 - 3050a.

CITY_21MC100_006262420