NYC 9/11 Public Portal Document

003

KAM CONSULTANTS
35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

REPORT OF AIR MONITORING

(PHASE CONTRAST MICROSCOPY ANALYSIS OF AIR FILTERS)

CLIENT: DCAS
PROJECT:

DATE: 09/18/01
ADDRESS: 60 Centre Street, Manhattan, NY

CLIENT SAMPLE ID#	LOCATION	RESP	WORK	TIME IN	TIME OUT	FLOW BEF. (lpm)	FLOW AFTER (lpm)	SAMPLE VOLUME (liters)	FIBERS PER FIELD	FIBERS PER CC	REMARKS	LAB ID#
01	IWA - Conference Room 7th Floor			19:00	20:00	15	15	900	<0.055	< 0.01	Air Quality (Immed. TAT)	A010919A-01
02	IWA Room 700 7th Floor			19:01	20:01	15	15	900	<0.055	< 0.01	Air Quality (Immed. TAT)	A010919A-02
03	IWA - Lobby South 7th Floor			19:02	20:02	15	15	900	<0.055	< 0.01	Air Quality (Immed. TAT)	A010919A-03
04	IWA - Room 685 6th Floor			19:09	20:09	15	15	900	0.070	< 0.01	Air Quality (Immed. TAT)	A010919A-04
05	IWA - Room 652			19:11	20:11	15	15	900	<0.055	< 0.01	Air Quality (Immed. TAT)	A010919A-05
06	IWA - Room 641			19:13	20:13	15	15	900	0.060	< 0.01	Air Quality (Immed. TAT)	A010919A-06
07	IWA Room 629			19:15	20:15	15	15	900	<0.055	< 0.01	Air Quality (Immed. TAT)	A010919A-07
08	IWA - Reception Area 6th Floor			19:18	20:18	15	15	900	<0.055	< 0.01	Air Quality (Immed. TAT)	A010919A-08
09	IWA - Library 500			20:25	21:25	15	15	900	<0.055	< 0.01	Air Quality (Immed. TAT)	A010919A-09
10	IWA - 561 Room			20:27	21:27	15	15	900	<0.055	< 0.01	Air Quality (Immed. TAT)	A010919A-10
11	IWA - 543 Room			20:29	21:29	15	15	900	<0.055	< 0.01	Air Quality (Immed. TAT)	A010919A-11
12	IWA - Room 532			20:31	21:31	15	15	900	<0.055	< 0.01	Air Quality (Immed. TAT)	A010919A-12
13	IWA - Room 514			20:33	21:33	15	15	900	0.060	< 0.01	Air Quality (Immed. TAT)	A010919A-13
14	IWA - Jury Room 452			20:39	21:39	15	15	900	<0.055	< 0.01	Air Quality (Immed. TAT)	A010919A-14
15	IWA - Room 412			20:45	21:45	15	15	900	<0.055	< 0.01	Air Quality (Immed. TAT)	A010919A-15
16	IWA Room 422			20:47	21:47	15	15	900	<0.055	< 0.01	Air Quality (Immed. TAT)	A010919A-16
17	IWA - Hall by Elevators 4th Floor			20:49	21:49	15	15	900	<0.055	< 0.01	Air Quality (Immed. TAT)	A010919A-17
18	IWA - Room 438			20:51	21:51	15	15	900	0.080	< 0.01	Air Quality (Immed. TAT)	A010919A-18
19	IWA - Room 300 Corridor			21:32	22:32	15	15	900	<0.055	< 0.01	Air Quality (Immed. TAT)	A010919A-19
20	IWA - Hallway by Elevators 3rd Floor			21:35	22:35	15	15	900	<0.055	< 0.01	Air Quality (Immed. TAT)	A010919A-20
21	IWA - Room 315			21:37	22:37	15	15	900	<0.055	< 0.01	Air Quality (Immed. TAT)	A010919A-21
22	IWA - Room 325			21:40	22:40	15	15	900	<0.055	< 0.01	Air Quality (Immed. TAT)	A010919A-22
23	IWA - Corridor 341-345			21:42	22:42	15	15	900	<0.055	< 0.01	Air Quality (Immed. TAT)	A010919A-23

TYPE OF RESPIRATORS: 1 = HALF FACE, 2 = PAPR, 3 = TYPE C, 4 = OTHER (SPECIFY)
TYPE OF WORK: 1= BLDG DECON, 2 = PLASTICIZING, 3 = GROSS REMOVAL, 4 = GLOVEBAG, 5 = CLEANING, 6 = ENCAPSULATION, 7 = BAGOUT, 8 = OTHER (SPECIFY)

SAMPLING TECHNICIAN Z.B Nowak / P Sroka
ROTAMETER: KAM- 04

DATE RECEIVED 09/19/01
DATE OF ANALYSIS: 09/19/01
DATE OF REPORT 09/19/01

Analyst: Deepak Bajracharya

Lab Manager: David Chen

The samples listed above are analyzed by Phase Contrast Microscopy (PCM) as per NIOSH 7400 Method - Issue 3. The detection limit of this method is 7 fibers per square mm per filter area.
KAM CONSULTANTS shall not be liable for information arising from samples that are not in its QA and QC program.
The results relate only to the items calibrated or tested. The certificate of report shall not be reproduced without approval of the laboratory.
The report must not be used by the client to claim endorsement by NVLAP or any agency of the U.S. Government.

NYS-DOH ELAP # 11273 *AIHA # 100269*

KAM CONSULTANTS FAX 7187291576 09/20/2001 10:56

CITY_21MC100_006263404

NYC-WTC_000182342