NYC 9/11 Public Portal Document

KAM CONSULTANTS
35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

CHAIN OF CUSTODY FOR ASBESTOS AIR MONITORING

CLIENT: NYC-DDC
PROJECT: Stuyvesant H.S.

SAMPLING DATE: 10/14/01
ADDRESS: 345 Chambers St., NY, NY 10282

RECEIVED
KAM CONSULTANTS
2001 OCT 15 AM 8:51

T011015D

FIELD DATA							LAB ANALYSIS			
SAMPLE #	LOCATION	TIME IN	TIME OUT	FLOW BEF (lpm)	FLOW AFTER (lpm)	VOLUME (litres)	STRUCTURES DETECTED 0.5-5.0 (μ)	STRUCTURES DETECTED >5.0 (μ)	Structure Density (struc/mm²)	Structure Concentration (s/ru/cc)
1	OUTSIDE NORTH ENTRANCE OF SCHOOL - EAST SIDE	00.00	7.52	3	3	1416	0	0	<16.67	<0.0045
2	↓ - WEST SIDE	00.01	7.54	3	3	1416	0	0	<16.67	<0.0045

TECHNICIAN: A. MARTIROSSIAN
ROTAMETER: KAM101

CHAIN OF CUSTODY	PLEASE, ANALYSE ASAP AND FAX RESULTS DDC HAZMAT (718) 391-1499 DDC OPERATIONS (212) 941-5356 KAM ADAMS (609) 584-1134	RECEIVED AT LAB BY: SAMPLE CONDITION UPON RECEIPT: Good DATE/TIME: 10-15-01

ANALYST Alex Barsegyants DATE RECEVED 10/15 DATE OF ANALYSIS 10/15

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) EPA 40 CFR Part 763 (AHERA)
Sample Volume may be below recommended limit of the method.
FAX RSULTS TO (212) 941-5356

PAGE 01/01
KAM CONSULTANTS 7187293774
10/15/2001 11:22
CITY_21MC100_006413605

NYC-WTC_000182371

PAGE 01/01

KAM CONSULTANTS
35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

CHAIN OF CUSTODY FOR ASBESTOS AIR MONITORING

CLIENT: NYC-DDC
PROJECT: Stuyvesant H.S.

SAMPLING DATE: 10-15-01
ADDRESS: 345 Chambers St. NY, NY 10282

RECEIVED KAM CONSULTANTS 2001 OCT 15 PM 5:42

T011015M

FIELD DATA							LAB ANALYSIS			
SAMPLE #	LOCATION	TIME IN	TIME OUT	FLOW BEF (lpm)	FLOW AFTER (lpm)	VOLUME (liters)	STRUCTURES 0.5-5.0 (μ)	DETECTED >5.0 (μ)	Structure Density (struc/mm²)	Structure Concentration (struc/cc)
	PIER-25									
1	North entrance of school-East	7:58	16:05	3	3	1461	0	0	<16.67	<0.0044
2	- " - West	8:01	16:09	3	3	1464	↓	↓	<16.67	<0.0044

TECHNICIAN:

ROTAMETER KAM101

CHAIN OF CUSTODY	Please analyze ASAP and FAX results; DDC Hazmat (718) 391-1199; DDC Operations (212) 941-5356; DDC BCA ADAMS (609)-524-1134	RECEIVED AT LAB BY: AB SAMPLE CONDITION UPON RECEIPT: DATE/TIME:

ANALYST A Clark B Bak DATE RECEVED 10-15-01 DATE OF ANALYSIS 10-15-01

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) EPA 40 CFR Part 763 (AHERA)
Sample Volume may be below recommended limit of the method
FAX RSULTS TO (212) 941-5356

KAM CONSULTANTS 7187293774 10/15/2001 18:54

CITY_21MC100_00641360

NYC 9/11 Public Portal Document

KAM CONSULTANTS
35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

CHAIN OF CUSTODY FOR ASBESTOS AIR MONITORING

CLIENT: NYC-DDC
PROJECT: Stuyvesant H.S.

SAMPLING DATE: 10-15-01
ADDRESS: 345 Chambers St., NY,NY 10282

T0110167

FIELD DATA							LAB ANALYSIS			
SAMPLE #	LOCATION	TIME IN	TIME OUT	FLOW BEF (lpm)	FLOW AFTER (lpm)	VOLUME (liters)	STRUCTURES DETECTED 0.5-5.0 (μ)	STRUCTURES DETECTED >5.0 (μ)	Structure Density (struc/mm²)	Structure Concentration (struc/cc)
	PIER-25									
1	North Entrance of school-East	16:07	2000	3	3	1419	0	0	<16.67	<0.0045
2	[illegible]	16:11	2401	3	3	1410	0	0	<16.67	<0.0045

TECHNICIAN: DIMITRIOS M SALIS
ROTAMETER KAM101

CHAIN OF CUSTODY	[illegible]	RECEIVED AT LAB BY: [signature] SAMPLE CONDITION UPON RECEIPT: DATE/TIME: 10/16/01

ANALYST [signature]
DATE RECEVED 10/16/01
DATE OF ANALYSIS 10/16/01

RECEIVED
OCT 16 AM 9:55
KAM CONSULTANTS

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) EPA 40 CFR Part 763 (AHERA)
Sample Volume may be below recommended limit of the method
FAX RSULTS TO (212) 941-5356

KAM CONSULTANTS 10/16/2001 08:15 FAX 7187291876
CITY_21MC100_006413607

NYC-WTC_000182373