NYC 9/11 Public Portal Document

ATC ASSOCIATES INC.

BATCH NO. 19513

BULK SAMPLE DATA AND CHAIN OF CUSTODY FORM

PROJECT INFORMATION

1. Client: NYC - BOE	2. Project Name:	3. Project # 19125-0246	4. Project Manager: ANDREAS ANDREOU
	2a. Project Address: 345 Chambers street, New York, NY 10007		4a. Investigator: A. Andreou / Y. Efstathiou

5. Date:	6. Building Name:	8. Turnaround Time:	9. Comments (Field):
9/21/2001	New Stuyvesant HS (M477)	☐ STAT ☐ 24 HRS ☐ 72 HRS ☒ OTHER	ANALYZED ALL SAMPLES
	7. Sampling Areas: 9, 10 & 11 FLOORS	☐ 6 HRS ☐ 48 HOURS ☐ NORMAL RUSH	10. Time in / Time out:

I.D. #	SAMPLE NUMBER	MATERIAL DESCRIPTION	LOCATION	FLOOR No.	DAMAGE Y/N	EXPOSURE & ACCESS	RESULTS
1	M477-9/21-01	DUST SAMPLES	FROM THE FLOOR OF ROOM # C1150	11th		H M L	NONE DETECTED
1	-02	DUST SAMPLES	FROM LOUVERS OF RM # C1150	↓		H M L	↓
1	-03	DUST SAMPLES	FROM THE FLOOR BY THE ENTRANCE TO THE SE SIDE ROOF			H M L	
1	-04	DUST SAMPLES	BY LOUERS ON SE SIDE, FROM PUMP EQUIPMENT			H M L	
1	-05	DUST SAMPLES	FROM INSIDE HVAC UNIT #1,			H M L	CHRYSOTILE ASBESTOS DETECTED
1	-06	DUST SAMPLES	FROM THE FLOOR INSIDE HVAC UNIT #2			H M L	CHRYSOTILE ASBESTOS DETECTED
1	-07	DUST SAMPLES	FROM THE FLOOR BY THE ENTRANCE TO THE SW SIDE ROOF	↓		H M L	NONE DETECTED
2	-08	DUST SAMPLES	FROM TEACHERS DESK IN ROOM #1039	10th		H M L	↓
2	-09	DUST SAMPLES	ROOM #1039 FROM WINDOW WELL OF SE WINDOW	↓		H M L	
2	-10	DUST SAMPLES	ROOM #1030/BOY'S TOILET - FROM THE FLOOR			H M L	↓

CHAIN OF CUSTODY

17. Relinquished By:	18. Date:	19. Time:	20. Received By:	21. Date:	22. Time:
Andreou	9/21/01		MHowd-ATC	9/21/01	7:30PM

23. Method of Submittal	
FIELD	
WALK IN	
US MAIL	
FED-X	
OTHER	

LAB INFORMATION

24. Name and Signature:	25. Date:	26. Time:
24a. Analyzed By: E. A. Cinotti	9/21/01	PM
24b. Analyzed By:		
24c. QC By:		

27. Comments (Lab): 40

Filename: P:\USERS\DATA\WP96\WP\FORMS\NY-13.XLS

Form NY-13

NYC-WTC_000182525

NYC 9/11 Public Portal Document

ATC ASSOCIATES INC.

BATCH NO. 19513

BULK SAMPLE DATA AND CHAIN OF CUSTODY FORM

PROJECT INFORMATION

1. Client: NYC - BOE	2. Project Name:	3. Project # 19125-0246	4. Project Manager: ANDREAS ANDREOU
	2a. Project Address: 345 Chambers street, New York, NY 10007		4a. Investigator: A. Andreou / Y. Efstathiou

5. Date:	6. Building Name:	8. Turnaround Time:	9. Comments (Field):
9/21/2001	New Stuyvesant HS (M477)	☐ STAT ☐ 24 HRS ☐ 72 HRS ☒ OTHER	ANALYZED ALL SAMPLES
	7. Sampling Areas: 9, 10 & 11 Floors	☐ 6 HRS ☐ 48 HOURS ☐ NORMAL RUSH	10. Time in / Time out:

I.D. #	SAMPLE NUMBER	MATERIAL DESCRIPTION	LOCATION	FLOOR No.	DAMAGE Y/N	EXPOSURE & ACCESS	RESULTS
2	M477-9/21-11	DUST SAMPLES	Room #1033 FROM A STUDENT'S DESK	10th		H M L	NONE DETECTED
	-12	DUST SAMPLES	Room #1033, FROM WINDOW SASH SE SIDE			H M L	
	-13	DUST SAMPLES	Room #1024, FROM THE FLOOR			H M L	
	-14	DUST SAMPLES	Room #1024, FROM THE NW WINDOW WELL			H M L	
	-15	DUST SAMPLES	Room #1025, FROM SE CORNER RADIATOR			H M L	
	-16	DUST SAMPLES	Room #1010, FROM THE TOP SHELVE OF THE SINK			H M L	
	-17	DUST SAMPLES	COMPUTER Rm #1009 FROM THE FLOOR BY THE SE CORNER			H M L	
	-18	DUST SAMPLES	COMPUTER Rm #1009 FROM WINDOW WELL SOUTH SIDE			H M L	
	-19	DUST SAMPLES	FROM THE FLOOR BY THE ELEVATOR LOBBY			H M L	
	-20	DUST SAMPLES	Room #1007, FROM THE TEACHER'S DESK			H M L	

CHAIN OF CUSTODY

17. Relinquished By:	18. Date:	19. Time:	20. Received By:	21. Date:	22. Time:
A. Andreou	9/21		M Loud ATC	9/21/01	4:30PM

23. Method of Submittal:	
FIELD	
WALK IN	
US MAIL	
FED-X	
OTHER	

LAB INFORMATION

24. Name and Signature:	25. Date:	26. Time:
24a. Analyzed By: E. H. Chan 10120S	9/21/01	24
24b. Analyzed By:		
24c. QC By		

27. Comments (Lab):

Filename: P:\USERS\DATA\WP96\WP\FORMS\NY-15.XLS

Form NY-15

NYC-WTC_000182526

NYC 9/11 Public Portal Document

ATC ASSOCIATES INC.

BATCH NO. 19513

BULK SAMPLE DATA AND CHAIN OF CUSTODY FORM

PROJECT INFORMATION

1. Client: NYC - BOE	2. Project Name:	3. Project # 19125-0246	4. Project Manager: ANDREAS ANDREOU
	2a. Project Address: 345 Chambers street, New York, NY 10007		4a. Investigator: A. Andreou / Y. Efstathiou

5. Date:	6. Building Name:	8. Turnaround Time:	9. Comments (Field):
9/21/2001	New Stuyvesant HS (M477)	☐ STAT ☐ 24 HRS ☐ 72 HRS ☒ OTHER	ANALYZED ALL SAMPLES
	7. Sampling Areas: 9, 10 & 11 Floors	☐ 6 HRS ☒ 48 HOURS ☐ NORMAL RUSH	10. Time in / Time out:

I.D. #	SAMPLE NUMBER	MATERIAL DESCRIPTION	LOCATION FROM	Floor No.	DAMAGE Y/N	EXPOSURE & ACCESS	RESULTS
2	M477-9/21-21	DUST SAMPLES	Room #1006 "NORTH SIDE MIDDLE WINDOW WELL	10th		H M L	NONE DETECTED
	-22	DUST SAMPLES	Room #1006, FROM A STUDENT'S DESK			H M L	
	-23	DUST SAMPLES	Room #1001, FROM A TABLE BY SOUTH SIDE			H M L	
	-24	DUST SAMPLES	Room #1001, FROM SW SIDE WINDOW WELL			H M L	
3	-25	DUST SAMPLES	Room #902, FROM A TABLE CLOSE TO THE WINDOWS.	9th		H M L	
	-26	DUST SAMPLES	Room #903, FROM THE WELL OF THE 2nd WINDOW FROM SE	SIDE		H M L	
	-27	DUST SAMPLES	Room #903, FROM A LAB DESK			H M L	
	-28	DUST SAMPLES	Room #907, FROM THE RADIATOR			H M L	
	-29	DUST SAMPLES	IN THE HALLWAY BY THE ELEVATOR LOBBY			H M L	
	-30	DUST SAMPLES	ROOM #911, FROM WINDOW WELL OF S-E SIDE WINDOW			H M L	

CHAIN OF CUSTODY

17. Relinquished By:	18. Date:	19. Time:	20. Received By:	21. Date:	22. Time:
Andreou	9/21		Mlouka	9/21/01	7:30PM

23. Method of Submittal:	
FIELD	
WALK IN	
US MAIL	
FED-X	
OTHER	

LAB INFORMATION

24. Name and Signature:	25. Date:	26. Time:
24a. Analyzed By: E. A. Constantinou	9/22/01	am
24b. Analyzed By:		
24c. QC By:		

27. Comments (Lab):

Filename: P:\USERS\DATA\WP96\WP\FORMS\NY-13.XLS

Form NY-13

CITY_21MC100_003099160

NYC-WTC_000182527

NYC 9/11 Public Portal Document

ATC ASSOCIATES INC.

BATCH NO. 19513

BULK SAMPLE DATA AND CHAIN OF CUSTODY FORM

PROJECT INFORMATION

1. Client: NYC - BOE	2. Project Name:	3. Project # 19125-0246	4. Project Manager: ANDREAS ANDREOU
	2a. Project Address: 345 Chambers street. New York. NY 10007		4a. Investigator: A. Andreou / Y. Efstathiou

5. Date:	6. Building Name:	8. Turnaround Time:	9. Comments (Field):
9/21/2001	New Stuyvesant HS (M477)	☐ STAT ☐ 24 HRS ☐ 72 HRS ☒ OTHER	ANALYZED ALL SAMPLES
	7. Sampling Areas: 9, 10 & 11 Floors	☐ 6 HRS ☒ 48 HOURS ☐ NORMAL RUSH	10. Time in / Time out:

I.D. #	SAMPLE NUMBER	MATERIAL DESCRIPTION	LOCATION	FLOOR No.	DAMAGE Y/N	EXPOSURE & ACCESS	RESULTS
3	M477-9/21-31	DUST SAMPLES	ROOM #911, FROM WINDOW SILL OF SW WINDOW	9th		H M L	NONE DETECTED
	-32	DUST SAMPLES	FROM WINDOW SILL OF A WINDOW IN THE HALLWAY BY WEST STAIRS			H M L	"
	-33	DUST SAMPLES	ROOM #925, FROM A LAB DESK			H M L	CHRYSOTILE ASBESTOS DETECTED
	-34	DUST SAMPLES	ROOM #926, FROM A WINDOW SILL			H M L	NONE DETECTED
	-35	DUST SAMPLES	ROOM #931, FROM THE SE WINDOW WELL			H M L	
	-36	DUST SAMPLES	ROOM #931, FROM THE FLOOR MIDDLE OF THE ROOM			H M L	
	-37	DUST SAMPLES	ROOM #935, FROM A RADIATOR MIDDLE OF SOUTH SIDE			H M L	
	-38	DUST SAMPLES	ROOM #940, FROM A DESK @ NW CORNER			H M L	
	-39	DUST SAMPLES	ROOM #939, FROM THE FLOOR, MIDDLE OF SOUTH SIDE			H M L	
	-40	DUST SAMPLES	ROOM #939, FROM WELL OF A WINDOW @ THE MIDDLE OF SOUTH SIDE			H M L	

CHAIN OF CUSTODY

17. Relinquished By:	18. Date:	19. Time:	20. Received By:	21. Date:	22. Time:
[redacted]	9/21		MLowe	9/21/01	4:30PM

23. Method of Submittal	
FIELD	
WALK IN	
US MAIL	
FED-X	
OTHER	

LAB INFORMATION

24. Name and Signature:	25. Date:	26. Time:
24a. Analyzed By E. [illegible]	9/21/01	PM
24b. Analyzed By:		
24c. QC By:		

27. Comments (Lab):

Filename: P:\USERS\DATA\WP96\WP\FORMS\NY-13.XLS

Form NY-13

CITY_21MC100_003099161

NYC-WTC_000182528