

SciLab Job#: 202013269

Client Name: Environmental Health Investigations, Inc.

**Table I**  
**Summary of Bulk Asbestos Analysis Results**  
 0224-0572; Bovis Lend; 75 Park Place, 6th - 9th Floors, New York, NY

| SciLab Sample # | Client Sample# Location                                                             | HG Area | Sample Weight (gram) | Heat Sensitive Organic % | Acid Soluble Inorganic % | Insoluble Non-Asbestos Inorganic % | Asbestos by PLM/DS | Asbestos by TEM |
|-----------------|-------------------------------------------------------------------------------------|---------|----------------------|--------------------------|--------------------------|------------------------------------|--------------------|-----------------|
| 01              | 75P-012602-44<br>At Southwest Corner Inside Univent Heaters @ 9th Floor             |         | ---                  | ---                      | ---                      | ---                                | NVA                | NA              |
| 02              | 75P-012602-45<br>At Northwest Corner Inside Univent Heater @ 9th Floor              |         | ---                  | ---                      | ---                      | ---                                | NVA                | NA              |
| 03              | 75P-012602-46<br>By Southeast Corner At Carpet Floor (By Broken Window) @ 9th Floor |         | ---                  | ---                      | ---                      | ---                                | NVA                | NA              |
| 04              | 75P-012602-47<br>By Center Of 9th Floor On Carpet                                   |         | ---                  | ---                      | ---                      | ---                                | NVA                | NA              |
| 05              | 75P-012602-48<br>At Desks By Southeast Corner @ 9th Floor                           |         | ---                  | ---                      | ---                      | ---                                | NVA                | NA              |
| 06              | 75P-012602-49<br>At Desks By Northeast Corner @ 9th Floor                           |         | ---                  | ---                      | ---                      | ---                                | NVA                | NA              |
| 07              | 75P-012602-50<br>Beneath Floor Panel By East Side @ 9th Floor                       |         | ---                  | ---                      | ---                      | ---                                | NVA                | NA              |
| 08              | 75P-012602-51<br>Beneath Floor Panel By West Side @ 9th Floor                       |         | ---                  | ---                      | ---                      | ---                                | NVA                | NA              |

Analyzed by: Bella Chernis Bella Chernis; Date Analyzed: 1/27/02

\*NAD/NSD = no asbestos detected; NA = not analyzed; NA/PS = not analyzed / positive stop; PLM Bulk Asbestos Analysis by EPA 600/M4-82-020 per 40 CFR 763 (NVLAP Lab #200546-0) and ELAP PLM Analysis Protocol 198.1 for New York samples (NYSDOH ELAP Lab # 11480); ELAP TEM Analysis Protocol 198.4 for negative NY NOB samples. Note: PLM is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials. TEM is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos-containing in New York State (also see EPA Advisory for floor tile, FR 59, 146, 38970, 8/1/94). National Institute of Standards and Technology Accreditation requirements mandate that this report must not be reproduced except in full without the approval of the laboratory. This PLM report relates ONLY to the items tested.  
 ABIA# 102843; VT Cert# AL016055 NVA-No Visible Asbestos

Reviewed By: \_\_\_\_\_

CITY\_21MC100\_009028357