NYC 9/11 Public Portal Document

USEPA Region 2
Air Sampling Work Sheet

Tetra Tech Project, Rockaway, NJ
EPA Contract No. G1058240305701

Site: WTC NYC (WTC)
WA #:
Tetra Tech Contact:
WAM Neil Norrell/Chris Jimenez
Phone:
Phone: 212-608-7097

Sample #	07421	07422	07423	07424	NA
Location	Washing Tent	Austin Tobin Plaza	North Tower	South Tower	
Pump/Sampler #					
Media	Tedlar Bag	Tedlar Bag	Tedlar Bag	Tedlar Bag	
Analysis / Method	VOCs	VOCs	VOCs	VOCs	
Time/Date (Start)	10:25/0 02/02/02	11:05/0 02/02/02	10:56/0 02/02/02	11:11/0 02/02/02	
Time/Date (Stop)	10:26/1 02/02/02	11:06/1 02/02/02	10:57/1 02/02/02	11:12/1 02/02/02	
Total Time (Minutes)	1 (min)	1 (min)	1 (min)	1 (min)	
Pump Fault	N	N	N	N	
Flow rate/min (Start)	1.0 Liters	1.0 Liters	1.0 Liters	1.0 Liters	
Flow rate/min (Stop)	1.0 Liters	1.0 Liters	1.0 Liters	1.0 Liters	
Flow rate/min (Avg)	1.0 Liters	1.0 Liters	1.0 Liters	1.0 Liters	
Volume	1.00 Liters	1.00 Liters	1.00 Liters	1.00 Liters	

Comments:
07421:
07422: Center of debris pit, ground level
07423: SE corner of North Tower, ground level
07424: Approx. center of tower, ground level

NYC-WTC_000186673