NYC 9/11 Public Portal Document

228 East 45th Street
New York, NY 10017
(212) 922-0077
Fax (212) 922-0630

8091

P.O. _____

WARREN & PANZER ENGINEERS, P.C.

AIR MONITORING LOG SHEET/CHAIN-OF-CUSTODY FORM

CLIENT: DEP
PROJECT: 23 Trinity Pl / 47 Broadway
LOCATION: Roof

W&P FILE #: 1079.01.02
TURN AROUND: 24 hrs
TECHNICIAN: FAINSTEIN

Analysis Method: PCM - 7400
(circle one) TEM - AHERA
TEM - EPA LEVEL II

SAMPLE NUMBER	SAMPLE DESCRIPTION/LOCATION	SAMPLE TYPE	PUMP #	FLOWRATE START	FLOWRATE STOP	TIME ON	TIME OFF	TOTAL TIME	VOLUME (liters)	CONCENTR. (fib./cc.)
025	IWA Inside roof	3		3.5	3.5	8-55	15-35	400	1400	
026	" " "	3		"	"	8-56	15-36	"	"	
027	OWA Inside Lecay (Bl.Tw)	3		"	"	8-58	15-38	"	"	
028	" Door access to the roof	3		"	"	9-00	15-40	"	"	
029	" Staircase	3		"	"	9-02	15-42	"	"	
030		1								
031	Blanks	1								
032		1								

SAMPLED BY: Lev Fainstein DATE: 6/13/02
SIGNATURE:
RELEASED BY: Lev Fainstein DATE: 6/13/02
SIGNATURE:
RECEIVED BY: FTC DATE: 6/13
SIGNATURE: 1500

SAMPLE TYPE CODES	
1 - Blank	5 - Final Clearance (inside)
2 - Pre-Abatement	6 - Final Clearance (outside)
3 - During Abatement	7 - Personal
4 - During Glove Bag Removal	8 - Background

SEE REVERSE SIDE FOR ANALYSIS INFORMATION

CITY_21MC100_002942126

NYC-WTC_000186757