

DEPARTMENT OF ENVIRONMENTAL PROTECTION
BUREAU OF AIR, NOISE & HAZARDOUS MATERIALS
ASBESTOS/LEAD CONTROL PROGRAM
59-17 JUNCTION BOULEVARD
CORONA, NY 11368

JOEL A. MIELE, SR., P.E.
COMMISSIONER

ASBESTOS CONTROL PROGRAM
BULK ANALYSIS CHAIN OF CUSTODY

Incident No.: _____ Date Sampled: 2/23/02
Premise: 175 Broadway Time: 1130 am/pm
Boro: MAN.
Inspector: Luisa M. Reyna Luisa M. Reyna
Print Sign

TURNAROUND TIME: 24HRS [X] 48HRS [] 1 WK [] 2 WKS [] 4 WKS []

SAMPLE NUMBER	DESCRIPTION	LOCATION SAMPLED	LAB ID
1. 20223/A055028	Fibrous debris	North parapet wall roof	
2. 20223/A055029	Fibrous debris	South parapet wall roof	
3. 20223/A055030	Fibrous debris	North parapet wall roof	
4. 20223/A055031	Fibrous debris	South side floor on roof	
5. 20223/A055032	Fibrous debris	North west parapet wall roof	
6. 20223/A055033	Fibrous debris	North west parapet wall roof	
7. 20223/A055034	Fibrous debris	N.W. parapet wall roof	
8. 20223/A055035	Fibrous debris	N.W. parapet wall roof	
9. 20223/A055036	Fibrous debris	Metal stairs west side roof	
10.			

ANALYSES REQUESTED: Asbestos PLM [] Asbestos TEM [] Lead []

DATE	TIME	ACCEPTED BY	COMMENTS
2/23/02	3:55 P	PRINT Greg Fought	SAFE Cust 91 BEC Lab
		SIGN [Signature]	
		P	
		S	
		P	
		S	
		P	
		S	
		P	
		S	

DEP ACP REV 9/96