

**DEPARTMENT OF ENVIRONMENTAL PROTECTION
BUREAU OF ENVIRONMENTAL COMPLIANCE
ASBESTOS AND LEAD CONTROL PROGRAM
59-17 JUNCTION BOULEVARD
CORONA, NY 11368
JOEL A. MIELE, SR., P.E.
COMMISSIONER**

DUPLICATE

**BULK
ANALYSIS CHAIN OF CUSTODY**

Incident No.: _____

Date Sampled: 2/23/02

Premise: 92 CHAMBER STREET

Boro: MANHATTAN

Time: 10:30 (am)pm

Inspector: R. RAMMOHAN
Print

RMohay
Signature

Turnaround Time : Immediate ☒ 24 Hours ☐ 48 Hours ☐ 1 Week ☐

SAMPLE NUMBER	DESCRIPTION	LOCATION SAMPLED	LAB ID
1. 20223/A078001	Fibrous & Dirt	Roof, Mid section	102 (CH 1.3
2. 20223/A078002	Fibrous & Dirt	Roof Mid Section	103 (CH 1.2
3. 20223/A078003	Fibrous & Dirt	Roof Mid Section	104
4. 20223/A078004	Dirt	Roof Mid section	105
5. 20223/A078005	Fibrous	Roof Mid section	106
6. 20223/A078006	Fibrous	Roof Mid section	107
7. 20223/A078007	Fibrous	Roof South west wall	108
8. 20223/A078008	Fibrous	Roof South west corner	109
9. 20223/A078009	Fibrous	Roof Behind bulk head.	110
10.			

ANALYSIS REQUESTED: Asbestos PLM ☒

Asbestos TEM ☐

Lead ☐

Date	Time	Accepted By	Comments
1. 2/23/02	10:00 am	Print Greg Fruchtmann	Safe Cust at BEC Lab
		Sign <u>[Signature]</u>	
2.	am pm	Print	
		Sign	
3.	am pm	Print	
		Sign	
4.	am pm	Print	
		Sign	
5.	am pm	Print	
		Sign	

DEP ACLP REV 5/00

CITY_21MC100_002942479