NYC 9/11 Public Portal Document

228 East 45th Street
New York, NY 10017
(212) 922-0077
Fax (212) 922-0630

# WARREN & PANZER ENGINEERS, P. C.

## AIR MONITORING LOG SHEET/CHAIN-OF-CUSTODY FORM

PAGE ____ OF ____

24 hr+/a  12 hr+/a  6 hr+/a  3 hr+/a  Immediate +/a

P.O. ____

CLIENT: NYC DEP
PROJECT: 102 CHURCH ST.
LOCATION: 20th Fl. ROOF

W&P FILE #: 1079.01.02
LABORATORY:
ANALYSIS METHOD: PCM (circle one) 7400 | TEM AHERA | TEM EPA LEVEL II

CONTACT: Mike McLaw

TECHNICIAN: ELKIN CANO

| SAMPLE NUMBER | SAMPLE DESCRIPTION/LOCATION | SAMPLE TYPE | PUMP # | FLOWRATE START | FLOWRATE STOP | TIME ON | TIME OFF | TOTAL TIME | VOLUME (liters) | CONCENTR. (fib./cc.) |
|---|---|---|---|---|---|---|---|---|---|---|
| 1027001 | ON ROOF WEST SIDE | 3 | | 5 | | 08:04 | 14:14 | 370 | 1850 | |
| 1027002 | ON ROOF WEST SIDE | 3 | | 5 | | 08:05 | 14:15 | 370 | 1850 | |
| 1027003 | ON ROOF WEST BY WINDOW | 3 | | 5 | | 08:06 | 14:16 | 370 | 1850 | |
| 1027004 | ON ROOF WEST BY WINDOW | 3 | | 5 | | 08:07 | 14:17 | 370 | 1850 | |
| 1027005 | ON ROOF WEST BY WINDOW | 3 | | 5 | | 08:08 | 12:18 | 250 | 1250 | |
| 1027006 | FIELD BLANK | 1 | | | | | | | | |
| 1027007 | FIELD BLANK | 1 | | | | | | | | |
| 1027008 | FIELD BLANK | 1 | | | | | | | | |
| 1027009 | INSIDE FLOOR MAN BY ENTR. TO ROOF | 3 | | 10 | | 12:20 | 14:20 | 120 | 1200 | |

COMMENTS: TO2-10-175

SAMPLE BY: ELKIN CANO  DATE: 10/27/02
SIGNATURE:
RELEASED BY:  DATE: 10/27/02
SIGNATURE:
RECEIVED BY: A. CATIGA  DATE: 10/28/02
SIGNATURE:

| SAMPLE TYPE CODES | |
|---|---|
| 1 - Blank | 5 - Final Clearance (inside) |
| 2 - Pre-Abatement | 6 - Final Clearance (outside) |
| 3 - During Abatement | 7 - Personal |
| 4 - During Glove Bag Removal | 8 - Background |

SEE REVERSE SIDE FOR ANALYSIS INFORMATION

0007/013
10/29/2002 14:38 FAX
CITY_DEP_WORBY_CANNATA_SUBP_000005107
NYC-WTC_000186775