

DEPARTMENT OF ENVIRONMENTAL PROTECTION
 BUREAU OF ENVIRONMENTAL COMPLIANCE
 ASBESTOS AND LEAD CONTROL PROGRAM
 59-17 JUNCTION BOULEVARD
 CORONA, NY 11368
 JOEL A. MIELE, SR., P.E.
 COMMISSIONER

BULK
 ANALYSIS CHAIN OF CUSTODY

Incident No.:

Date Sampled: 2-23-02

Premise: 165 CHURCH ST.

Boro: MANHATTAN

Time: 3:00 am

Inspector: D. SHAH

Signature: D. Shah

Print

Signature

Turnaround Time : Immediate | ☒ 24 Hours | | 48 Hours | | 1 Week | |

SAMPLE NUMBER	DESCRIPTION	LOCATION SAMPLED	LAB ID
1. 20223/A060012	Fibrous & Dust	Roof Mid Section	
2. 20223/A060013	" "	Roof Mid Section	
3. 20223/A060014	" "	Roof N. W. corner	
4. 20223/A060015	" "	Roof W. Section	
5. 20223/A060016	" "	Roof S. E. corner	
6. 20223/A060017	" "	Roof S. W. corner	
7. 20223/A060018	" "	Roof N. E. corner	
8. 20223/A060019	" "	Roof Mid Section	
9. 20223/A060020	" "	Roof stair side	
10.			

ANALYSIS REQUESTED: Asbestos PLM | | Asbestos TEM | | Lead | |

Date	Time	Accepted By	Comments
1.	am pm	Print	
		Sign	
2.	am pm	Print	
		Sign	
3.	am pm	Print	
		Sign	
4.	am pm	Print	
		Sign	
5.	am pm	Print	
		Sign	

DEP ACLP REV 5/00

ENTERED