

228 East 45th Street
New York, NY 10017
(212) 922-0777
Fax (212) 922-0630

WARREN & PANZER ENGINEERS, P. C.

PAGE 1 of 1

AIR MONITORING LOG SHEET/CHAIN-OF-CUSTODY FORM

24 hr+/a 12 hr+/a 6 hr+/a 3 hr+/a Immediate +/a

P.O. _____

CLIENT: NYC-DEP
PROJECT: Roof Cleanup
LOCATION: 10 Cordland

W&P FILE #: 10790102
LABORATORY: ATE
ANALYSIS METHOD: PCM TEM TEM
circle one 7400 AHERA EPA LEVEL II
TECHNICIAN: N. Wells

CONTACT: Mike Nolan
LLW#: _____
SCA JOB#: _____

SAMPLE NUMBER	SAMPLE DESCRIPTION/LOCATION	SAMPLE TYPE	PUMP #	FLOWRATE START	FLOWRATE STOP	TIME ON	TIME OFF	TOTAL TIME	VOLUME (liters)	CONCENTR. (lb./cc.)
001A	1st landing on stairs	3		7	7	07:30	11:30	240	1680	
002A	Entrance to roof top of stairs	3		7	7	07:31	11:21	240	1680	m
003A	Center area of roof 1.W.A.	3		7	7	07:32	11:32	240	1680	
004A	Right side of roof adj. to deck	3		7	7	07:34	11:34	240	1680	
005A	Left side of roof 1.W.A.	3		7	7	07:35	11:35	240	1680	
006	Field Blank									
007	Field Blank									
008	Sealed Blank									

COMMENTS:

SAMPLE BY: <u>[Signature]</u>	DATE: <u>7/9</u>
SIGNATURE: <u>N. Wells</u>	
RELEASED BY: _____	DATE: _____
SIGNATURE: _____	
RECEIVED BY: <u>MAC</u>	DATE: <u>7/9</u>
SIGNATURE: <u>[Signature]</u>	16:20

SAMPLE TYPE CODES	
1 - Blank	5 - Final Clearance (Inside)
2 - Pre-Abatement	6 - Final Clearance (outside)
3 - During Abatement	7 - Personal
4 - During Glove Bag Removal	8 - Background

SEE REVERSE SIDE FOR ANALYSIS INFORMATION

CITY_21MC100_002942955