

228 East 45th Street
New York, NY 10017
(212) 922-0077
Fax (212) 922-0630

WARREN & PANZER ENGINEERS, P. C. AIR MONITORING LOG SHEET/CHAIN-OF-CUSTODY FORM

PAGE 1 OF 1

P.O. _____

CLIENT: D.E.P.
PROJECT: DEP Sampling; Roof Cleaning
LOCATION: 24 John St. NY, NY.
on Roof.

W&P FILE #: 1079.01.02
LABORATORY: Warren and Panzer
ANALYSIS METHOD: PCM TEM TEM
circle one 7400 AHERA EPA LEVEL II
TECHNICIAN: Yury Bedin.

CONTACT: Mr. M. Nalan.

SAMPLE NUMBER	SAMPLE DESCRIPTION/LOCATION	SAMPLE TYPE	PUMP #	FLOWRATE START STOP	TIME ON OFF	TOTAL TIME	VOLUME (liters)	CONCENTR. (ug/cc.)
1 IWA	on Roof 4 th Fl. Center of North Annex	3		3.0 3.0	9:15 16:45	450	1350	
2 IWA	on Roof 4 th Fl. West Section of W.A.	3		3.0 3.0	9:17 16:47	450	1350	
3 IWA	on Roof 4 th Fl. North Section of W.A.	3		3.0 3.0	9:19 16:49	450	1350	
4 IWA	on Roof 4 th Fl. East Section of W.A.	3		3.0 3.0	9:21 16:51	450	1350	
5 OWA	4 th Fl. on Hallway leading to Roof	3		3.0 3.0	9:23 16:53	450	1350	
6	Field Blank	1						
7	Field Blank	1						
8	S. Blank	1						

COMMENTS:

T02-10-048

SAMPLE BY: <u>Yury Bedin.</u>	DATE: <u>10-7-02</u>
SIGNATURE: <u>[Signature]</u>	
RELEASED BY: <u>Yury Bedin.</u>	DATE: <u>10-7-02</u>
SIGNATURE: <u>[Signature]</u>	
RECEIVED BY: <u>[Signature]</u>	DATE: <u>10/8/02</u>
SIGNATURE: <u>[Signature]</u>	

SAMPLE TYPE CODES	
1 - Blank	5 - Final Clearance (inside)
2 - Pre-Abatement	6 - Final Clearance (outside)
3 - During Abatement	7 - Personal
4 - During Glove Bag Removal	8 - Background

SEE REVERSE SIDE FOR ANALYSIS INFORMATION

CITY_21MC100_002950119

10/10/2002 06:50 FAX

014/015