

DEPARTMENT OF ENVIRONMENTAL PROTECTION

BUREAU OF ENVIRONMENTAL COMPLIANCE

AIR MONITORING AUDIT SHEET

for
ROOF/FACADE CLEAN-UP

NAME of AUDITOR: GEORGE ANAKHU DATE: 10/25/02

1. Location /Address(as listed on ACP 7): 45 PARK PL

2. Air Monitor Onsite: Yes ☐ No ☐ 3. Name of Monitor: RONALD KING

4. Certificate No. AH98-20226 5. Time of Audit: 7²⁰ am/pm ☒

6. Chain of Custody Sheet Completed: Yes ☐ No ☒
If No, Action Taken(describe): _____

7. Address on Chain of Custody correct(as listed on ACP 7): Yes ☐ No ☐
If No, Action Taken(describe): _____

8. Analytical Method Circled(TEM-AHERA) : Yes ☐ No ☐
If No, Action Taken(describe): _____

9. Number of samples listed on Chain of Custody(do not include blank) : _____

10. Activity at Work Area (Check): a. No Activity (☐) b. Setting up Equipment (☒) c. Calibrating Pump (☐)

d. Sampling in Process (☐) e. Breaking down Equipment (☐) f. Sampling Completed (☐) g. Doing Paper work(☐)

h. Other (Describe): _____

11. No of Pumps Running: _____
Problems Observed (describe): _____

Zone Coordinators:

Zone #1: Al Plumptre Zone #2: Denise Anzoulatos Zone #3: Carlstein Lutchmedial