NYC 9/11 Public Portal Document

DEPARTMENT OF ENVIRONMENTAL PROTECTION
BUREAU OF ENVIRONMENTAL COMPLIANCE
AIR MONITORING AUDIT SHEET
for
ROOF/FACADE CLEAN-UP

NAME of AUDITOR: A. Soloki **DATE:** 10-17-02

1. Location /Address(as listed on ACP 7): 20 John st.

2. Air Monitor Onsite: Yes ✓ **No** ___ **3. Name of Monitor :** IDRIS IDOWY

4. Certificate No. AH-02-11201 **5. Time of Audit:** 1140 **am/pm**

6. Chain of Custody Sheet Completed: Yes ✓ **No** ___
If No, Action Taken(describe): ___

7. Address on Chain of Custody correct(as listed on ACP 7): Yes ✓ **No** ___
If No, Action Taken(describe): ___

8. Analytical Method Circled(TEM-AHERA) : Yes ✓ **No** ___
If No, ActionTaken(describe): ___

9. Number of samples listed on Chain of Custody(do not include blank) : 5

10. Activity at Work Area (Check): a. No Activity ( ) b. Setting up Equipment ( ) c. Calibrating Pump ( )
d. Sampling in Process (✓) e. Breaking down Equipment ( ) F. Sampling Completed ( ) g. Doing Paper work ( )
h. Other (Describe): ___

11. No of Pumps Running: 5 FR5 @ 10L0
Problems Observed (describe):
Sample were taken on The roof.

Zone Coordinators:
Zone #1: Al Plumptre Zone #2: Denise Anzoulatos Zone #3: Carlstein Lutchmedial

NYC-WTC_000187200