

**DEPARTMENT OF ENVIRONMENTAL PROTECTION
BUREAU OF ENVIRONMENTAL COMPLIANCE
AIR MONITORING AUDIT SHEET
for
ROOF/FACADE CLEAN-UP**

NAME of AUDITOR: GEORGE ANAKHU DATE: 10/18/02

1. Location /Address(as listed on ACP 7): 85 NASSAU ST

2. Air Monitor Onsite: Yes ☒ No ☐ 3. Name of Monitor: FESTY OGBMWEGIE

4. Certificate No. AH01-01030 5. Time of Audit: 3⁵⁵ am/pm (p)

6. Chain of Custody Sheet Completed: Yes ☒ No ☐

If No, Action Taken(describe): _____

7. Address on Chain of Custody correct(as listed on ACP 7): Yes ☒ No ☐

If No, Action Taken(describe): _____

8. Analytical Method Circled(TEM-AHERA) : Yes ☒ No ☐

If No, Action Taken(describe): _____

9. Number of samples listed on Chain of Custody(do not include blank) : 5

10. Activity at Work Area (Check): a. No Activity () b. Setting up Equipment () c. Calibrating Pump ()

d. Sampling in Process (☒) e. Breaking down Equipment () f. Sampling Completed () g. Doing Paper work()

h. Other (Describe): _____

11. No of Pumps Running: 5

Problems Observed (describe): _____

Zone Coordinators:

Zone #1: Al Plumptre Zone #2: Denise Anzoulatos Zone #3: Carlstein Lutchmedial