

**DEPARTMENT OF ENVIRONMENTAL PROTECTION
BUREAU OF ENVIRONMENTAL COMPLIANCE
AIR MONITORING AUDIT SHEET**

for

ROOF/FACADE CLEAN-UP

Facade

NAME of AUDITOR: Gilbert Roman **DATE:** 8/18/02

1. Location /Address(as listed on ACP 7): 196 Broadway

2. Air Monitor Onsite: Yes ☒ No ☐ **3. Name of Monitor:** Festy ostenwegie

4. Certificate No. AH01-01030 **5. Time of Audit:** 7¹⁰ am/pm

6. Chain of Custody Sheet Completed: Yes ☒ No ☐

If No, Action Taken(describe): _____

7. Address on Chain of Custody correct(as listed on ACP 7): Yes ☒ No ☐

If No, Action Taken(describe): _____

8. Analytical Method Circled(TEM-AHERA) : Yes ☒ No ☐

If No, Action Taken(describe): _____

9. Number of samples listed on Chain of Custody(do not include blank) : 5

10. Activity at Work Area (Check): a. No Activity () b. Setting up Equipment () c. Calibrating Pump ()

d. Sampling in Process ☒ e. Breaking down Equipment () f. Sampling Completed () g. Doing Paper work()

h. Other (Describe): _____

11. No of Pumps Running: 5

Problems Observed (describe): _____

Zone Coordinators:

Zone #1: Al Plumptre **Zone #2:** Denise Anzoulatos **Zone #3:** Carlstein Lutchmedial