

7 Hillside Ave, Suit 100
New Rochelle, NY, 10801-1608

File #: 23401
NYSELAP #: 10898
AIHA-PAT #: 102509

PROJECT LOCATION: WTC, Various Locations

CONTAMINANT INVESTIGATED: Fibers Airborne

DATE MONITORED: 12/23/01

METHOD OF ABATEMENT:

NATURE OF TEST:

☐ PRE-TEST
☐ AFTER FINAL CLEAN-UP
☐ AGGRESSIVE

☐ CONTAINMENT

☐ GLOVE BAG ☐ TENT

☐ OTHER

☐ DURING PREPARATION

☐ DURING ASBESTOS REM ☐ DURING CLEAN-UP

☐ AIR-TEST

☐ OSHA

☐ NON-AGGRESSIVE

OTHERS:

METHOD: NIOSH 7400, ISSUE 2-8/16/94

SAMPLING LOCATION	SAMPLE #	VOLUME OF AIR SAMPLED (LITERS)	RESULTS FIBERS/FIELD	RESULTS FIBERS/CC	DETECTION LIMIT FIB/CC
West End of W Thomas	13-12/23/01	650.3	0.075	0.006	0.005
River Ter./ Park pl.	14-12/23/01	657	<0.07	<LOD	0.005
River Ter./ Chambers	15-12/23/01	643.5	<0.07	0.005	0.005
River Ter./ Warren	16-12/23/01	663.75	<0.07	<LOD	0.005
North End/Park pl	17-12/23/01	675	<0.07	<LOD	0.005
River Ter./ Vesey	18-12/23/01	652.50	<0.07	<LOD	0.005
Trinity pl./Thomas	19-12/23/01	675	0.10	0.007	0.005
Vesey/West Broadway	20-12/23/01	666	<0.07	<LOD	0.005
Field Blank	21-12/23/01		BDL		
Field Blank	22-12/23/01		BDL		

METHOD: NIOSH 7400, Rule A (PCM)

*BDL - Below Detectable Levels

**These results apply to these particular samples

L.O.D. = 0.07 fibers/Field = 0 Fibers/mm²

J. Fero
Analyst

[Signature]
Lab Supervisor's Signature

These samples were not collected by Enviro-Probe