

EMSL Analytical, Inc.

107 Haddon Ave., Westmont, NJ 08108

Phone: (856) 858-4800 Fax: (856) 858-4960 Email: ssiegel@EMSL.com



Attn: Jim Proctor
Health & Safety Services, Inc.
11 Oak Road
P.O. Box 249
Hammonton, NJ 08037

Fax: (609) 561-7646

Phone: 609-704-8850

Project: GSA

Customer ID: HESA55

Customer PO:

Received: 10/22/01 3:55 PM

EMSL Order: 040116467

EMSL Project ID:

Analysis Date: 10/24/2001

Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Location	Appearance	Treatment	Non-Asbestos		Asbestos
				% Fibrous	% Non-Fibrous	% Type
HSS-02	DEBRIS IN COWL	Gray	Teased	45% Cellulose		2% Chrysotile
040116467-0001		Fibrous		53% Synthetic		
		Homogeneous				

Analyst(s)

Scott Combs (1)

Stephen Siegel, CIH
or other approved signatory

PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Negative PLM results cannot be guaranteed. Samples reported as <1% or none detected should be tested with TEM. The above test report relates only to the items tested. This report may not be reproduced, except in full, without written approval by EMSL Analytical, Inc. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government.

Analysis performed by EMSL Westmont (NVLAP #101048-0), NY ELAP 10872

PLM-1

