



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 1 of 2

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other 15 min

PROJECT INFORMATION

1. Client: <u>Board of Education</u>		2. Project Name: <u>Stuyvesant H.S.</u>		3. Project #: <u>11703-042</u>		4. Project Monitor: <u>26. Kowalke</u>		4c. Rotameter Number: <u>10000</u>	
		2a. Project Address: <u>345 Chambers St.</u>		3a. Task #: <u>01</u>		4a. Air Sampler: <u>M. Bakh</u>			
5. Date: <u>10.05.01</u>		6. Abatement Location: <u>Outside the building North side</u>		7. ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture _____ Lot # _____		8. ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacture <u>Nuc</u> Lot # <u>98117612</u>		9. Type: a. ☐ Background c. ☐ Abatement b. ☐ Pre-Abate d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other	

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location		13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
		12a. IWA	12b. OWA	12c. Sample Coordinates	13a. Start	13b. End	13c. Total	14a. Start	14b. End	14b. Avg		
01				Field Blank								
02				Field Blank								
03			V	Outside the Bldg. North side Elevation - North East corner	02:55	06:09	174	9.5	9.5	9.5	1843	
04			V	Outside the Bldg. North side Elevation - 80' line N.E. corner	02:01	06:10	193	9.5	9.5	9.5	1833.5	
05			V	Outside the Bldg. North side Elevation - In front of the entrance	02:59	06:11	192	9.5	9.5	9.5	1824	
06			V	Outside the Bldg. North side Elevation - 80' line North East	03:00	06:12	193	9.5	9.5	9.5	1833.5	
07			V	Outside the Bldg. North side Elevation - In front of block B corner	03:02	06:14	192	9.5	9.5	9.5	1824	
08			V	11th floor Roof East side	06:05	06:14	192	9.5	9.5	9.5	1833.5	

CHAIN OF CUSTODY

18. Relinquished By: <u>I M. Bakh</u>	19. Received By: <u>RRly</u>	20. Date: <u>10.05</u>	21. Time: <u>8:00</u>
II			
III			

26. ATC Project Manager: <u>Rene Sanchez</u>	27. Result To: <u>Rene Sanchez</u> Beeper/Phone #'s _____
---	--

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: <u>ATC-TEM</u>	23. Date: <u>10.05</u>	24. Time: <u>11:45</u>	25. Microscope Make/Serial #: ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079
a. Analyzed By: <u>RRly</u>			
b. QC By: _____			
c. Lab Batch #: _____			
28. Comments:			
Analysis Methodology PCM - NIOSH 7400A TEM - AHERA			

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY-1 (1/01)

CITY_21MC100_003081926

Page 4 of 4

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other A

1. Client: <i>Board of Education</i>	2. Project Name <i>Oluyesant H.S.</i>	3. Project # <i>27803-062</i>	4. Project Monitor: <i>26. Kowalski</i>	4c. Rotameter Number: <i>100</i>
	2a. Project Address <i>346 Chambers St.</i>	3a. Task #	4a. Air Sampler: <i>M. Bobb</i>	
5. Date: <i>10.05.01</i>	6. Abatement Location: <i>Boys</i>	7. ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture _____ Lot # _____	8. ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacture _____ Lot # _____	9. Type: a. ☐ Background b. ☐ Pre-Abate
				c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA
				f. ☐ Environmental g. ☒ Ambient h. ☐ Other

[illegible]

18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I	R R R	10.05	8:00
II			
III			

22. Lab Name:	ATC-TEM	23. Date:	24. Time:
a. Analyzed By:	R. R. R.	10.05	11:45
b. QC By:			
c. Lab Batch #:			

☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

PCM - NIOSH 7400A
TEM - AHERA

27. Result To: 1. SANCHEZ

Beeper/Phone #'s _____

28. Comments:

NY-1 (1/01)

CITY_21MC100_003081927