



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 1 of 1

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other RUSH

PROJECT INFORMATION

1. Client: NYC - BOE		2. Project Name P.S 234 M		3. Project # 79569-77588		4. Project Monitor: Kevin		4c. Rotameter Number: 50087	
		2a. Project Address 292 GREENWICH ST NY NY 10007		3a. Task #		4a. Air Sampler: Fitzpatrick			
5. Date: 3-14-02		6. Abatement Location: ENTIRE SCHOOL VARIOUS LOCATIONS		7. ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture _____ Lot # _____		8. ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacture MMI Lot # 00763916		9. Type: a. ☐ Background d. ☐ Post-Abate b. ☐ Pre-Abate e. ☐ OSHA	
								f. ☐ Environmental g. ☒ Ambient h. ☐ Other	

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location			13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
		12a. IWA	12b. OWA	12c. Sample Coordinates	13a. Start	13b. End	13c. Total	14a. Start	14b. End	14b. Avg			
01				Field Blank									
02				Field Blank									
03				open BLANK									
04				1 ST FLOOR Hallway. NEXT TO STAIRWELL #1	7:01 AM	11:02 AM	241	8.0	8.0	8.0	1928		
05				WESTSIDE OF CAFETERIA 1 ST FLOOR	7:03 AM	11:03 AM	240	8.0	8.0	8.0	1920		
06				SOUTHSIDE OF GYM	7:04 AM	11:05 AM	242	8.0	8.0	8.0	1936		
07				WESTSIDE OF AUDITORIUM 2ND FLOOR	7:07 AM	11:07 AM	240	8.0	8.0	8.0	1920		
08				NORTHSIDE OF playground	7:09 AM	11:10 AM	241	8.0	8.0	8.0	1928		

CHAIN OF CUSTODY

18. Relinquished By:		19. Received By:		20. Date:	21. Time:
I. <u>Kevin Fitzpatrick</u>		II. <u>BKof</u>		03/14/02	
III.					

26. ATC Project Manager: <u>MARK REYES</u>		27. Result To: _____ Beeper/Phone #'s _____	
---	--	--	--

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: <u>TEC</u>		23. Date:	24. Time:	25. Microscope Make/Serial #: ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079
a. Analyzed By: <u>WOT</u>		3/15	3:00	
b. QC By:				
c. Lab Batch #: <u>7076</u>				Analysis Methodology PCM - NIOSH 7400A <u>TEM - AHERA</u>
28. Comments:				

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY-1 (1/01)

CITY_21MC100_003084649



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

 Page 2 of 2
TURNAROUND TIME
☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other PUSH
PROJECT INFORMATION

1. Client: NYC - BOE		2. Project Name P3 234 M		3. Project # 14584-0823		4. Project Monitor: Kevin		4c. Rotameter Number: SD057	
		2a. Project Address 272 GREENWICH ST NY NY 10001		3a. Task #		4a. Air Sampler: Fitzpatrick			
5. Date: 3-14-02		6. Abatement Location: ENTIRE SCHOOL VARIOUS LOCATIONS		7. ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture _____ Lot # _____		8. ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacture _____ Lot # _____		9. Type: a. ☐ Background d. ☐ Post-Abate b. ☐ Pre-Abate e. ☐ OSHA	
								c. ☐ Abatement f. ☐ Environmental g. ☒ Ambient h. ☐ Other	

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location			13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
		12a. IWA	12b. OWA	12c. Sample Coordinates	13a. Start	13b. End	13c. Total	14a. Start	14b. End	14b. Avg			
				Field Blank									
				Field Blank									
09				SOUTHSIDE OF ROOF AREA.	7:11 AM	7:11	240	8.0	8.0	8.0	1920		
10				WESTSIDE OF PLAYGROUND AREA.	7:14 AM	11:15 AM	241	8.0	8.0	8.0	1928		
11				1 ST FLOOR HALLWAY NEXT TO STAIRWELL #1	11:17 AM	3:17 PM	240	8.0	8.0	8.0	1920		
12				NORTHSIDE OF PLAYGROUND	11:19 AM	3:19 PM	240	8.0	8.0	8.0	1920		
13				WESTSIDE OF PLAYGROUND	11:21 AM	3:22 PM	241	8.0	8.0	8.0	1928		
14				SOUTHSIDE OF ROOF AREA.	11:25 AM	3:27 PM	242	8.0	8.0	8.0	1936		

CHAIN OF CUSTODY

18. Relinquished By:		19. Received By:		20. Date:		21. Time:	
I <u>Jim Fitzpatrick</u>		<u>Shop</u>		<u>3/14/02</u>			
II _____							
III _____							

26. ATC Project Manager: MARK REJESAN		27. Result To: _____ Beeper/Phone #'s _____	
---	--	--	--

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: <u>YES</u>		23. Date: <u>3/15-3:00</u>		24. Time: _____	
a. Analyzed By: <u>CMC</u>					
b. QC By: _____					
c. Lab Batch #: <u>7076</u>					
28. Comments: _____					
25. Microscope Make/Serial #: ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079 Analysis Methodology PCM - NIOSH 7400A <u>TEM - AHERA</u>					

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY-1 (1/01)

CITY_21MC100_003084650



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

 Page 3 of 3
TURNAROUND TIME
☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other PUSH
PROJECT INFORMATION

1. Client: NMC - BOE		2. Project Name: PS 234 M		3. Project #: 1584-0823		4. Project Monitor: Kurin		4c. Rotameter Number: 20087	
		2a. Project Address: 292 Greenwich ST NY NY 10001		3a. Task #:		4a. Air Sampler: Ritzpatrick			
5. Date: 3-14-02		6. Abatement Location: ENTIRE SCHOOL VARIOUS LOCATIONS		7. ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture _____ Lot # _____		8. ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacture _____ Lot # _____		9. Type: a. ☐ Background d. ☐ Post-Abate b. ☐ Pre-Abate e. ☐ OSHA	
								c. ☐ Abatement f. ☐ Environmental g. ☒ Ambient h. ☐ Other	

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location		12c. Sample Coordinates	13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
		12a. IWA	12b. OWA		13a. Start	13b. End	13c. Total	14a. Start	14b. End	14b. Avg			
				Field Blank									
				Field Blank									
15				SOUTHSIDE OF CLASSROOM 2ND FLOOR RM 223	3:36 pm	7:36 pm	240	8.0	8.0	8.0	1920		
16				SOUTHSIDE OF CLASSROOM 219 2ND FLOOR	3:38 pm	7:38 pm	240	8.0	8.0	8.0	1920		
17				SOUTHSIDE OF CLASSROOM 215 2ND FLOOR	3:40 pm	7:40 pm	240	8.0	8.0	8.0	1920		
18				EASTSIDE OF CLASSROOM KINDERGARTEN RM 118	5:56 pm	9:51 pm	241	8.0	8.0	8.0	1928		
19				EASTSIDE OF CLASSROOM KINDERGARTEN RM 116	5:59 pm	9:59 pm	240	8.0	8.0	8.0	1920		
20				EASTSIDE OF CLASSROOM KINDERGARTEN RM 122	6:01 pm	10:03 pm	242	8.0	8.0	8.0	1936		

CHAIN OF CUSTODY

18. Relinquished By: [Signature]		19. Received By: [Signature]		20. Date: 03/14/02		21. Time:	
I							
II							
III							
26. ATC Project Manager: MARK FERGUSON				27. Result To: _____ Beeper/Phone #'s _____			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: VEU		23. Date: 3/15		24. Time: 3:00		25. Microscope Make/Serial #: ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079	
a. Analyzed By: [Signature]							
b. QC By:							
c. Lab Batch #: 7076						Analysis Methodology PCM - NIOSH 7400A <u>TEM - AHERA</u>	
28. Comments:							

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY-1 (1/01)

CITY_21MC100_003084651