NYC 9/11 Public Portal Document

# AIR MONITORING DATA AND CHAIN OF CUSTODY FORM



TURNAROUND TIME: ☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard ☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other PLUS

7262 1/8/18 82403-82420

PROJECT INFORMATION

| 1. | 2. Project Name | 3. Project # | 4. Project Monitor | 4c. Rotameter Number |
|---|---|---|---|---|
| NYC-BCE | PS 234M<br>2a. Project Address: 292 Greenwich St, NY, NY 10007 | 14584-0823 | 4a. Air Sampler: MARK NAKHUMOVICH | HP107 |

| 5. Location | 7. ☐ PCM (0.8 micron MCE) | 8. ☒ TEM (0.45 micron MCE) | 9. Type: | |
|---|---|---|---|---|
| 3-29 ENTIRE | Cassette/Filter Manufacturer: _____ Lot #: _____ | Cassette/Filter Manufacturer: NUC. Lot #: 98302417 | a. ☐ Background b. ☐ Pre-Abate | c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA |

f. ☐ Environmental g. ☒ Ambient h. ☐ Other

AIR SAMPLE RECORD

| Sample I.D. Number | 11. Pump# Number | 12. Sample Location 12a. IWA | 12b. OWA | 12c. Sample Coordinates | 13. Time (24 hrs clock) 13a. Start | 13b. End | 13c. Total | 14. Flow Rate (L/min.) 14a. Start | 14b. End | 14b. Avg | 15. Total Air Vol (liters) | 16. # Fibers/Fields Minus Blank | 17. Fiber Conc. f/cc |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 16 | | | | Field Blank | | | | | | | | | |
| 17 | | | | Field Blank | | | | | | | | | |
| 01 | | | | First Floor - hallway | 6:25 | 10:25 | 240 | 8.0 | 8.0 | 8.0 | 1920 | | |
| 02 | | | | Cafeteria | 6:27 | 10:27 | 240 | 8.0 | 8.0 | 8.0 | 1920 | | |
| 03 | | | | Gymnasium | 6:29 | 10:29 | 240 | 8.0 | 8.0 | 8.0 | 1920 | | |
| 04 | | | | Auditorium | 6:31 | 10:31 | 240 | 8.0 | 8.0 | 8.0 | 1920 | | |
| 05 | | | | North playground | 6:33 | 10:33 | 240 | 8.0 | 8.0 | 8.0 | 1920 | | |
| 06 | | | | West playground | 6:35 | 10:35 | 240 | 8.0 | 8.0 | 8.0 | 1920 | | |
| 07 | | | | Roof - South part | 6:37 | 10:37 | 240 | 8.0 | 8.0 | 8.0 | 1920 | | |
| 08 | | | | First Floor - hallway | 10:25 | 14:25 | 240 | 8.0 | 8.0 | 8.0 | 1920 | | |
| 09 | | | | North playground | 10:33 | 14:33 | 240 | 8.0 | 8.0 | 8.0 | 1920 | | |
| 10 | | | | West playground | 10:35 | 14:35 | 240 | 8.0 | 8.0 | 8.0 | 1920 | | |
| 11 | | | | Roof - South part | 10:37 | 14:37 | 240 | 8.0 | 8.0 | 8.0 | 1920 | | |
| 12 | | | | Classroom # | 6:40 | 10:40 | 240 | 8.0 | 8.0 | 8.0 | 1920 | | |

CHAIN OF CUSTODY

| 18. Relinquished By: | 19. Received By: | 20. Date: | 21. Time: |
|---|---|---|---|
| | M. Gray | 03/24/02 | 17:00 |
| | | | |
| | | | |

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

| 22. Lab Name: ATC | 23. Date: | 24. Time: |
|---|---|---|
| a. Analyzed By: | 3/29 | 20:30 |
| b. QC By: | | |
| c. Lab Data #: 7262 | | |

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

17. Project Manager: Y. Efstathiou

27. Relinquished By: Y. Efstathiou

28. Comments:

Analyzed Structures:

Fiber Concentration:

CITY_21MC100_0030849 70

NYC-WTC_000189278

NYC 9/11 Public Portal Document

# AIR MONITORING DATA AND CHAIN OF CUSTODY FORM



TURNAROUND TIME
☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other RUSH

## IECT INFORMATION

| | 2. Project Name | 3. Project # | 4. Project Monitor | 4c. Rotameter Number |
|---|---|---|---|---|
| YC-RSCE | PS234M | K1584-C823 | MARK NAKHUMOVICH | HP107 |
| | 2a. Project Address: 242 Greenwich St, NY, NY 10007 | | 4a. Air Sampler: MARK Nakhumovich | |

| 5-Mo/Day/Yr | 6. Location: | 7. ☐ PCM (0.8 micron MCE) | 8. ☒ TEM (0.45 micron MCE) | 9. Type: |
|---|---|---|---|---|
| 3-29 | ENTIRE | Cassette/Filter Manufacturer: Lot #: | Cassette/Filter Manufacturer: Lot # | a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other |

## Y AIR SAMPLE RECORD

| ple I.D. Number | 11. Pump Number | 12. Sample Location 12a. PWA | 12b. DWA | 12c. Sample Coordinates | 13. Time (24 hrs clock) 13a. Start | 13b. End | 13c. Total | 14. Flow Rate (L/min.) 14a. Start | 14b. End | 14b. Avg | 15. Total Air Vol (liters) | 16. # Fibers/Fields Minus Blank | 17. Fiber Conc. F/ |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 18 | | | | Field Blank / Field Blank | | | | | | | | | |
| 13 | | | | Classroom # | 6:42 | 10:42 | 240 | 8.0 | 8.0 | 8.0 | 1920 | | |
| 14 | | | | Classroom # | 6:44 | 10:44 | 240 | 8.0 | 8.0 | 8.0 | 1920 | | |
| 15 | | | | Kindergarden | 6:46 | 10:46 | 240 | 8.0 | 8.0 | 8.0 | 1920 | | |

## IN OF CUSTODY

| inquished By: | 19. Received By: | 20. Date: | 21. Time: |
|---|---|---|---|
| | | | |
| | | | |
| | | | |

## LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

| 22. Lab Name: ATC Assoc | 23. Date: | 24. Time: |
|---|---|---|
| a. Analyzed By | 3/29 | 20:30 |
| b. QC By: | | |
| c. Lab Batch #: | | |

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Method(s):
PCM - NIOSH 7400A

| 17. Project Manager: | 27. Result To: | 28. Comments: |
|---|---|---|
| Y.Efstathiou | Y.Efstathiou | |
| | Beeper/Phone #'s: (646) 772-1155 | |

CITY_21MC100_00308497I

NYC-WTC_000189279