



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 1 of 4

PROJECT INFORMATION

1. Client: NYC - BOE		2. Project Name: New Stuyvesant HS (M477)		3. Project #: 97635-87058		4. Project Monitor: HERANT ANTONYAN		4c. Rotameter Number: HP-88	
		2a. Project Address: 345 Chambers St. NY, NY 10007		19125-0246		4a. Air Sampler: HERANT ANTONYAN			
5. Date: 5/1/02		6. Abatement Location: Exterior, Interior of the bldg. & the roof		7. ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture Lot #		8. ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacture Mully Meter Lot #		9. Type: a. ☐ Background b. ☐ Pre-Abate d. ☐ Post-Abate c. ☐ Abatement e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other	

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location			13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
		12a. IWA	12b. OWA	12c. Sample Coordinates	13a. Start	13b. End	13c. Total	14a. Start	14b. End	14c. Avg			
22				Field Blank									
23				Field Blank									
1				5th floor Cafeteria	7:00	11:00	240	8	8	8	1920		
2				3rd floor Aux Gym	7:03	11:03	240	8	8	8	1920		
3				Inside the Pool area	7:06	11:06	240	8	8	8	1920		
4				Inside the Auditorium	7:09	11:09	240	8	8	8	1920		
5				Outside of the building North side	7:12	11:14	242	8	8	8	1936		
6				Outside the building East side	7:15	11:17	242	8	8	8	1936		

CHAIN OF CUSTODY

18. Relinquished By:		19. Received By:		20. Date	21. Time
I. H. A. Lopez		AKOP		5/1/02	2:00
II.					
III.					

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC-TEM		23. Date	24. Time	25. Microscope Make/Serial # [] Nikon Labophot 238913 [] Nikon Labophot 238917 [] Nikon Labophot 239079
a. Analyzed By: RRUY		5/2/02	1:30	
b. QC By:				
c. Lab Batch #: 7601				Analysis Methodology PCM - NIOSH 7400A TEM - AIFRA
26. ATC Project Manager: Yiannis Efsthathiou				
27. Results To: Yiannis Efsthathiou Beep/Phone #'s (646) 772-1155				28. Comments:



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 2 of 4

PROJECT INFORMATION

1. Client: NYC - BOE		2. Project Name: New Stuyvesant HS (M477)		3. Project #: 19125-0246		4. Project Monitor: HERANT ANTONYAN		4c. Rotameter Number: HP-88	
		2a. Project Address: 345 Chambers St. NY, NY 10007				4a. Air Sampler: HERANT ANTONYAN			
5. Date: 5/1/02		6. Abatement Location: Exterior, Interior of the Bldg. & the Roof		7. ☐ PCM (0.8 micron MCE) Cassette/Filler Manufacture _____ Lot # _____		8. ☒ TEM (0.45 micron MCE) Cassette/Filler Manufacture _____ Lot # _____		9. Type a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other	

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location			13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
		12a. IWA	12b. CWA	12c. Sample Coordinates	13a. Start	13b. End	13c. Total	14a. Start	14b. End	14c. Avg			
24				Field Blank <i>Sealed blank</i>									
				Field Blank									
7				<i>Outside the building South side</i>	7:18	11:20	242	8	8	8	1936		
8				<i>1st floor lobby area</i>	7:21	11:24	243	8	8	8	1944		
9				<i>2nd floor lobby area</i>	7:22	11:25	243	8	8	8	1944		
10				<i>Outside the building 11th floor Roof.</i>	7:27	11:30	243	8	8	8	1944		
11				<i>Outside the building North side</i>	11:14	15:15	241	8	8	8	1928		
12				<i>Outside the building East side</i>	11:17	15:18	241	8	8	8	1928		

CHAIN OF CUSTODY

18. Relinquished By:		19. Received By:		20. Date	21. Time
I. <i>H. Adoy</i>		<i>Whop</i>		5/1/02	2:00
II.					
III.					

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: <i>ATC-TEM</i>		23. Date	24. Time	25. Microscope Make/Serial # ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079
a. Analyzed By: <i>Ricky</i>		5.2.02	11:30	
b. QC By:				
c. Lab Batch #: <i>7601</i>				

26. ATC Project Manager: Yiannis Efsthathiou	27. Results To: Yiannis Efsthathiou Beeper/Phone #'s (646) 772-1155
--	--

28. Comments:

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 3 of 4

TURNAROUND TIME			
☐ 2 hrs	☐ 6 hrs	☐ 48 hrs	☐ Standard
☐ 4 hrs	☐ 24 hrs	☐ 72 hrs	☒ Other <u>Push</u>

PROJECT INFORMATION

1. Client: <u>NYC - BOE</u>		2. Project Name: <u>New Stuyvesant HS (M477)</u>		3. Project #: <u>19125-0246</u>		4. Project Monitor: <u>HERANT ANTONYAN</u>		4c. Rotameter Number: <u>HP-88</u>	
5. Date: <u>5/1/02</u>		6. Abatement Location: <u>Exterior, Interior of the bldg. & the Roof</u>		7. ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture _____ Lot # _____		8. ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacture _____ Lot # _____		9. Type a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other	

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location			13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc f/cc
		12a. IWA	12b. OWA	12c. Sample Coordinates	13a. Start	13b. End	13c. Total	14a. Start	14b. End	14c. Avg			
				Field Blank									
				Field Blank									
13				<u>Outside the building</u> <u>South side</u>	<u>11:20</u>	<u>15:21</u>	<u>241</u>	<u>8</u>	<u>8</u>	<u>8</u>	<u>1928</u>		
14				<u>1st floor lobby area</u>	<u>11:24</u>	<u>15:26</u>	<u>242</u>	<u>8</u>	<u>8</u>	<u>8</u>	<u>1936</u>		
15				<u>2nd floor lobby area</u>	<u>11:25</u>	<u>15:27</u>	<u>242</u>	<u>8</u>	<u>8</u>	<u>8</u>	<u>1936</u>		
16				<u>Outside the building</u> <u>11th floor Roof</u>	<u>11:30</u>	<u>15:34</u>	<u>244</u>	<u>8</u>	<u>8</u>	<u>8</u>	<u>1952</u>		
17				<u>7th floor Hallway</u>	<u>14:52</u>	<u>18:54</u>	<u>242</u>	<u>8</u>	<u>8</u>	<u>8</u>	<u>1936</u>		
18				<u>6th floor Hallway</u>	<u>14:50</u>	<u>18:50</u>	<u>240</u>	<u>8</u>	<u>8</u>	<u>8</u>	<u>1920</u>		

CHAIN OF CUSTODY

18. Relinquished By:	19. Received By	20. Date	21. Time
I. <u>H. Arday</u>	<u>Whop</u>	<u>5/1/02</u>	<u>8:00</u>
II.			
III.			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: <u>ATC-TEM</u>	23. Date	24. Time
a. Analyzed By: <u>RRY</u>	<u>5.2.02</u>	<u>1:30</u>
b. QC By:		
c. Lab Batch #: <u>7601</u>		

25. Microscope Make/Serial #
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

26. ATC Project Manager: <u>Yiannis Efsthion</u>	27. Results To: <u>Yiannis Efsthion</u> Beeper/Phone #'s <u>(646) 772-1155</u>
---	---

28. Comments:	Analysis Methodology PCM - NIOSH 7400A TEM - AHERA
---------------	--



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 4 of 4

TURNAROUND TIME			
☐ 2 hrs	☐ 6 hrs	☐ 48 hrs	☐ Standard
☐ 4 hrs	☐ 24 hrs	☐ 72 hrs	☒ Other <u>Rush</u>

PROJECT INFORMATION

1. Client: <u>NYC - BOE</u>		2. Project Name: <u>New Stuyvesant HS (M477)</u>		3. Project #: <u>19125-0246</u>		4. Project Monitor: <u>HERANT ANTONYAN</u>		4c. Rotameter Number: <u>HP-88</u>	
5. Date: <u>5/1/02</u>		6. Abatement Location: <u>Exterior, Interior of the Bldg. & the Roof</u>		7. ☐ PCM (0.8 micron MCE) Cassette/Filler Manufacture _____ Lot # _____		8. ☒ TEM (0.45 micron MCE) Cassette/Filler Manufacture _____ Lot # _____		9. Type a. ☐ Background f. ☐ Environmental b. ☐ Pre-Abate d. ☐ Post-Abate g. ☒ Ambient c. ☐ Abatement e. ☐ OSHA h. ☐ Other	

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location			13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
		12a. IWA	12b. OWA	12c. Sample Coordinates	13a. Start	13b. End	13c. Total	14a. Start	14b. End	14c. Avg			
				Field Blank									
				Field Blank									
19				<u>6th floor, Rm. 638 N.</u>	<u>14:47</u>	<u>18:47</u>	<u>240</u>	<u>8</u>	<u>8</u>	<u>8</u>	<u>1920</u>		
20				<u>5th floor, Rm. 507 S.</u>	<u>14:44</u>	<u>18:44</u>	<u>240</u>	<u>8</u>	<u>8</u>	<u>8</u>	<u>1920</u>		
21				<u>4th floor, Rm. 401 E.</u>	<u>14:41</u>	<u>18:41</u>	<u>240</u>	<u>8</u>	<u>8</u>	<u>8</u>	<u>1920</u>		

CHAIN OF CUSTODY

18. Relinquished By:		19. Received By:		20. Date	21. Time
I. <u>H. Long</u>		<u>Shop</u>		<u>5/1/02</u>	<u>2100</u>
II.					
III.					

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: <u>ATC-TEM</u>		23. Date	24. Time	25. Microscope Make/Serial # ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079
a. Analyzed By: <u>RPL</u>		<u>5.2.02</u>	<u>15:20</u>	
b. QC By:				
c. Lab Batch #: <u>7601</u>				Analysis Methodology PCM - NIOSH 7400A TEM - AHERA
26. ATC Project Manager: <u>Yiannis Efsthathiou</u>				
27. Results To: <u>Yiannis Efsthathiou</u> Beeper/Phone #'s <u>(646) 772-1155</u>				28. Comments: