



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 1 of 4

PROJECT INFORMATION

2977

2/24

92933-92956

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other Rush

1. Client: NYC - BOE		2. Project Name: New Stuyvesant HS (M477)		3. Project #: 19125-0246		4. Project Monitor: HERANT ANTONYAN		4c. Rotameter Number: HP-88	
		2a. Project Address: 345 Chambers St. NY, NY 10007				4a. Air Sampler: HERANT ANTONYAN			
5. Date: 6/5/02		6. Abatement Location: Exterior, Interior of the bldg. & the Ref		7. ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture Lot #		8. ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacture Metty Metric Lot # 01205916		9. Type a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other	

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location			13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc F/CC
		12a IWA	12b OWA	12c. Sample Coordinates	13a. Start	13b. End	13c. Total	14a. Start	14b. End	14c. Avg			
22				Field Blank									
23				Field Blank									
1				5th floor Cafeteria	7:00	11:00	240	8	8	8	1920		
2				3rd floor Aux Gym	7:04	11:04	240	8	8	8	1920		
3				Inside the Pool area	7:07	11:07	240	8	8	8	1920		
4				Inside the Auditorium	7:10	11:10	240	8	8	8	1920		
5				Outside of the building North side	7:13	11:13	240	8	8	8	1920		
6				Outside the building East side	7:16	11:16	240	8	8	8	1920		

CHAIN OF CUSTODY

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

18. Relinquished By: I. H. Arslany		19. Received By: Rthop		20. Date: 6/5/02		21. Time: 2100		22. Lab Name: ATC-TEM		23. Date: 6.6.02		24. Time: 00:10		25. Microscope Make/Serial # ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079	
II.								a. Analyzed By: Rthop							
III.								b. QC By:							
										c. Lab Batch #: 7977					
26. ATC Project Manager: Yiannis Efsthathiou				27. Results To: Yiannis Efsthathiou Beeper/Phone #'s (646) 772-1155				28. Comments:				Analysis Methodology PCM - NIOSH 7400A TEM - AHERA			

White - File Yellow - Client/Report Pink - Lab Goldenrod - Field



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 2 of 4

TURNAROUND TIME			
☐ 2 hrs	☐ 6 hrs	☐ 48 hrs	☐ Standard
☐ 4 hrs	☐ 24 hrs	☐ 72 hrs	☒ Other <u>Rush</u>

PROJECT INFORMATION

1. Client: <u>NYC - BOE</u>		2. Project Name: <u>New Stuyvesant HS (M477)</u>		3. Project #: <u>19125-0246</u>		4. Project Monitor: <u>HERANT ANTONYAN</u>		4c. Rotameter Number: <u>HP-88</u>	
2a. Project Address: <u>345 Chambers St. NY, NY 10007</u>		5. Date: <u>6/5/02</u>		6. Abatement Location: <u>Exterior, Interior of the bldg. & the Roof</u>		7. ☐ PCM (0.8 micron MCE) Cassette/Filler Manufacture _____ Lot # _____		8. ☒ TEM (0.45 micron MCE) Cassette/Filler Manufacture _____ Lot # _____	
9. Type		a. ☐ Background		f. ☐ Environmental		b. ☐ Pre-Abate		d. ☐ Post-Abate	
c. ☐ Abatement		e. ☐ OSHA		g. ☒ Ambient		h. ☐ Other			

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location			13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
		12a. IWA	12b. OWA	12c. Sample Coordinates	13a. Start	13b. End	13c. Total	14a. Start	14b. End	14c. Avg			
24				Field Blank <u>Sealed blank</u>									
				Field Blank									
7				<u>Outside the building</u>	7:19	11:20	241	8	8	8	1928		
				<u>South side</u>									
8				<u>1st floor lobby area</u>	7:22	11:23	241	8	8	8	1928		
9				<u>2nd floor lobby area</u>	7:23	11:24	241	8	8	8	1928		
10				<u>Outside the building</u>	7:29	11:32	243	8	8	8	1944		
				<u>11th floor Roof.</u>									
11				<u>Outside the building</u>	11:13	15:15	242	8	8	8	1936		
				<u>North side</u>									
12				<u>Outside the building</u>	11:16	15:18	242	8	8	8	1936		
				<u>East side</u>									

CHAIN OF CUSTODY

18. Relinquished By:		19. Received By		20. Date		21. Time	
I. <u>H. Adley</u>				<u>6/5/02</u>			
II.							
III.							

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: <u>ATC TEM</u>		23. Date		24. Time		25. Microscope Make/Serial # ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079	
a. Analyzed By: <u>RKly</u>		<u>6-6-02</u>		<u>00:10</u>			
b. QC By:							
c. Lab Batch #:						Analysis Methodology PCM - NIOSH 7400A TEM - AHERA	

26. ATC Project Manager: <u>Yiannis Efsthathiou</u>		27. Results To: <u>Yiannis Efsthathiou</u> Beeper/Phone #'s <u>(646) 772-1155</u>	
--	--	--	--

28. Comments:

White - File Yellow - Client/Report Pink - Lab Goldenrod - Field



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 3 of 4

TURNAROUND TIME				
☐ 2 hrs	☐ 6 hrs	☐ 48 hrs	☐ Standard	
☐ 4 hrs	☐ 24 hrs	☐ 72 hrs	☒ Other <u>Rush</u>	

PROJECT INFORMATION

1. Client: <u>NYC - BOE</u>		2. Project Name: <u>New Stuyvesant HS (M477)</u>		3. Project #: <u>19125-0246</u>		4. Project Monitor: <u>HERANT ANTONYAN</u>		4c. Rotameter Number: <u>HP-88</u>	
5. Date: <u>6/5/02</u>		6. Abatement Location: <u>Exterior, Interior of the bldg. & the Roof</u>		7. ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture _____ Lot # _____		8. ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacture _____ Lot # _____		9. Type a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other	

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location			13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc F/CC
		12a. IWA	12b. OWA	12c. Sample Coordinates	13a. Start	13b. End	13c. Total	14a. Start	14b. End	14c. Avg			
				Field Blank									
				Field Blank									
13				Outside the building South side	11:20	15:21	241	8	8	8	1928		
14				1st floor lobby area	11:23	15:25	242	8	8	8	1936		
15				2nd floor lobby area	11:24	15:26	242	8	8	8	1936		
16				Outside the building 11th floor Roof	11:32	15:36	244	8	8	8	1952		
17				1st floor, Rm. 125 S.	14:20	18:20	240	8	8	8	1920		
18				10th floor, Rm. 1001 E.	14:15	18:15	240	8	8	8	1920		

CHAIN OF CUSTODY

18. Relinquished By: <u>I. H. Antonyan</u>	19. Received By: <u>R. H. O'Neil</u>	20. Date: <u>6/5/02</u>	21. Time: <u>2100</u>
II.			
III.			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: <u>ATC-TEM</u>	23. Date: <u>6.6.02</u>	24. Time: <u>00:00</u>	25. Microscope Make/Serial # ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079
a. Analyzed By: <u>R. H. O'Neil</u>			
b. QC By:			
c. Lab Batch #: <u>7977</u>			

26. ATC Project Manager: <u>Yiannis Efsthion</u>	27. Results To: <u>Yiannis Efsthion</u> Beeper/Phone #'s: <u>(646) 772-1155</u>
---	--

28. Comments:	Analysis Methodology PCM - NIOSH 7400A TEM - AHERA
---------------	--

White - File Yellow - Client/Report Pink - Lab Goldenrod - Field



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 4 of 4

TURNAROUND TIME			
☐ 2 hrs	☐ 6 hrs	☐ 48 hrs	☐ Standard
☐ 4 hrs	☐ 24 hrs	☐ 72 hrs	☒ Other <u>Rush</u>

PROJECT INFORMATION

1. Client: <u>NYC - BOE</u>		2. Project Name: <u>New Stuyvesant HS (M477)</u>		3. Project #: <u>19125-0246</u>		4. Project Monitor: <u>HERANT ANTONYAN</u>		4c. Rotameter Number: <u>HP-88</u>	
5. Date: <u>6/5/02</u>		6. Abatement Location: <u>Exterior, Interior of the Bldg. & the Roof</u>		7. ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture _____ Lot # _____		8. ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacture _____ Lot # _____		9. Type a. ☐ Background f. ☐ Environmental b. ☐ Pre-Abate d. ☐ Post-Abate g. ☒ Ambient c. ☐ Abatement e. ☐ OSHA h. ☐ Other _____	

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location			13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
		12a. IWA	12b. OWA	12c. Sample Coordinates	13a. Start	13b. End	13c. Total	14a. Start	14b. End	14c. Avg			
				Field Blank									
				Field Blank									
19				<u>3rd floor, Rm. 340N</u>	<u>14:10</u>	<u>18:10</u>	<u>240</u>	<u>8</u>	<u>8</u>	<u>8</u>	<u>1920</u>		
20				<u>7th floor Hallway</u>	<u>14:03</u>	<u>18:03</u>	<u>240</u>	<u>8</u>	<u>8</u>	<u>8</u>	<u>1920</u>		
21				<u>6th floor Hallway</u>	<u>14:00</u>	<u>18:00</u>	<u>240</u>	<u>8</u>	<u>8</u>	<u>8</u>	<u>1920</u>		

CHAIN OF CUSTODY

18. Relinquished By: <u>I. H. Hsiao</u>	19. Received By: <u>R. Hsiao</u>	20. Date: <u>6/5/02</u>	21. Time: <u>11:00</u>
II.			
III.			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: <u>ATC-TEM</u>	23. Date: <u>6/6/02</u>	24. Time: <u>08:10</u>	25. Microscope Make/Serial # ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079
a. Analyzed By: <u>R. Hsiao</u>			
b. QC By: _____			
c. Lab Batch #: <u>7977</u>			

26. ATC Project Manager: <u>Yiannis Efstathiou</u>	27. Results To: <u>Yiannis Efstathiou</u> Beeper/Phone #'s <u>(646) 772-1155</u>
---	---

28. Comments:	Analysis Methodology PCM - NIOSH 7400A TEM - AHERA
---------------	--

White - File Yellow - Client/Report Pink - Lab Gold/Red - Field